DEPARTMENT OF SAFETY AND INSPECTIONS Steve Magner, Manager of Code Enforcement

375 Jackson Street., Suite 220 Saint Paul, MN 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-1919 Web: www.stpaul.gov/dsi

SAINT PAUL

CITY OF SAINT PAUL Christopher B. Coleman, Mayor

331

November 16, 2010

Justin Obrien 1317 Summit Ave St Paul MN 55105-2602

MERS c/o Citimortgage 1111 Northpoint Drive #100 Coppell, TX 75019 Justin O'Brien c/o Guru Kripa 1129 Washington Ave S, Ste 2 Minneapolis, MN 55415

Peterson, Fram & Bergman 55 East Fifth Street, Ste. 800 St. Paul, MN 55101

Order to Abate Nuisance Building(s)

Dear: Sir or Madam

The Vacant/Nuisance Buildings Unit, Department of the Department of Safety and Inspections, Division of Code Enforcement, hereby declares the premises located at:

697 BRADLEY ST

With the following Historic Preservation information: NONE

and legally described as follows, to wit:

Sub Of And Add To Irvines Add Lot 6 Blk 2

to comprise a nuisance condition in violation of the Saint Paul Legislative Code, Chapter 45.02, and subject to demolition under authority of Chapter 45.11.

On <u>September 22, 2010</u>, a Building Deficiency Inspection Report was compiled and the following conditions were observed.

This list of deficiencies is not necessarily all the deficiencies present at this time. This building(s) is subject to the restrictions of Saint Paul Ordinance Chapter 33.03 and shall not again be used for occupancy until such time as a Certificate of Compliance or a Certificate of Occupancy has been issued. All repairs must be in accordance with appropriate codes. Changes or additions to the electrical system, mechanical system, or the plumbing system may necessitate updating or upgrading the systems involved.

This is a one and one half story, wood frame, single family dwelling and its over-sized single stall, detached garage.



December 14, 2010 697 BRADLEY ST page 2

Interior

- 1. FURNACE: Have a licensed heating contractor service and clean the furnace or boiler and make any necessary repairs. Perform a C/O test on the heating plant. Then, send the attached form back to the Inspector. Repair of gas fired appliances requires a permit.
- 2. Lack of Natural Gas Service. Immediately restore natural gas service. Failure to provide natural gas service will result in these premises being declared Unfit for Human Habitation and ordered vacated for lack of this basic facility.
- 3. G.F.C.I.: The bathroom is lacking an electrical G.F.C.I. outlet. Permit May Be Required.
- 4. The stairs have missing or defective handrails. Provide all interior and exterior stairways and steps of more that three (3) risers with handrails which are grippable and installed 34" to 38" above the nose of the stair treads.
- 5. The interior ceilings are defective. Repair all ceiling defects and finish in a professional manner.
- 6. The interior walls are defective. Repair all wall defects and finish in a professional manner.
- 7. There is evidence of a rodent infestation. Immediately exterminate and eliminate all rodents from the entire building. Remove rodent harborages in the yard areas. Tuckpoint the foundation if necessary to rodent-proof the building to prevent re-infestation. Immediately remove any dead rodents from the premises.
- 8. SANITATION: Immediately remove improperly stored or accumulated refuse including; garbage, rubbish, junk, vehicle parts, wood, metal, recycling materials, household items, building materials, rubble, tires, etc., from yard. The Saint Paul Legislative Code requires all exterior property areas to be maintained in a clean and sanitary condition. Usable materials must be stored in an approved manner, so as not to constitute a nuisance.
- 9. Smoke Detector: Lack of properly installed and operable smoke detector. Provide functioning smoke detectors in accordance with the attached requirement, within 24 hours.
- 10. DEFECTIVE STAIRS. Stairs are broken, defective, or in disrepair. Repair in a professional manner.
- 11. Molds have the potential to cause health problems. Clean it and repair surfaces if needed to eliminate the moisture source causing the mold growth.
- 12. Lack of Water Service. Immediately restore water service. Failure to provide water service will result in these premises being declared Unfit for Human Habitation and ordered vacated for lack of this basic facility.

Exterior

13. The exterior walls of the house and/or garage are defective. Repair all holes, breaks, loose or rotting siding, to a professional state of maintenance.

14. The windows and/or storm windows are in a state of disrepair. Replace all missing or broken window glass. Make all necessary repairs to frames, sashes, hardware and associated trim in a professional manner. Permit may be required.

As owner, agent or responsible party, you are hereby notified that if these deficiencies and the resulting nuisance condition is not corrected by **December 17, 2010**, the Department of Safety and Inspections, Division of Code Enforcement, will begin a substantial abatement process to demolish and remove the building(s). The costs of this action, including administrative costs and demolition costs will be assessed against the property taxes as a special assessment in accordance with law.

As first remedial action, a Code Compliance Inspection Report must be obtained from the Building Inspection and Design Section, 375 Jackson Street, Suite 220, (651) 266-8989. This inspection will identify specific defects, necessary repairs and legal requirements to correct this nuisance condition. You may also be required to post a five thousand dollar (\$5,000.00) performance bond with the Department of Safety and Inspections before any permits are issued, except for a demolition permit. Call the Department of Safety and Inspections for more information at 651-266-8989.

If this building is located in a historic district or site (noted on page 1, above, just below the property address) then you must contact Heritage Preservation (HPC) staff to discuss your proposal for the repairs required by this order and compliance with preservation guidelines. Copies of the guidelines and design review application and forms are available from the Department of Safety and Inspections web site (see letterhead) and from the HPC staff. No permits will be issued without HPC review and approval. HPC staff also can be reached by calling 651-266-9078.

As an owner or responsible party, you are required by law to provide full and complete disclosure of this "Order to Abate" to all interested parties, all present or subsequent renters and any subsequent owners. The property shall not be sold, transferred or conveyed in any manner until the Nuisance Conditions have been abated and the Certificate of Code Compliance or Certificate of Occupancy has been issued.

The Enforcement Officer is required by law to post a placard on this property which declares it to be a "nuisance condition", subject to demolition and removal by the City. This placard shall not be removed without the written authority of the Department of Safety and Inspections, Division of Code Enforcement. The department is further required to file a copy of this "Order to Abate" with the City Clerk's Office.

If corrective action is not taken within the time specified in this order, the Enforcement Officer will notify the City Council that abatement action is necessary. The City Clerk will then schedule dates for Public Hearings before the City Council at which time testimony will be heard from interested parties. After this hearing the City Council will adopt a resolution stating what action if any, it deems appropriate.

If the resolution calls for abatement action the Council may either order the City to take the abatement action or fix a time within which this nuisance must be abated in accordance with the provisions of Chapter 33 of the Saint Paul Legislative Code and provide that if corrective action is not taken within the specified time, the City shall abate this nuisance. The costs of this action, including administrative costs will be assessed against the property as a special assessment in accordance with law.

December 14, 2010 697 BRADLEY ST page 4

If you have any questions or request additional information please contact **Rich Singerhouse** between the hours of 8:00 and 9:30 a.m. at **651-266-1945**, or you may leave a voice mail message.

Sincerely,

Rich Singerhouse Vacant Buildings Enforcement Inspector

cc: Mary Erickson - Council Research Cindy Carlson - PED Housing Amy Spong – Heritage Preservation

ota60135 7/10