



CITY OF SAINT PAUL

Code Compliance Report

March 01, 2023

*** * This Report must be Posted
on the Job Site * ***

METRO HOLDINGS LLC
7279 40TH ST N
OAKDALE MN 55128-3305

Re: 1011 Burns Ave
File#: 18 101644 VB3

Dear Property Owner:

The following is the Code Compliance report you requested on February 10, 2023.

Please be advised that this report is accurate and correct as of the date March 01, 2023. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from March 01, 2023. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected. A Legislative Code exemption (Chapter 33.03(f)) allows a Category 2 Vacant Building to be sold "as is" providing the buyer, prior to closing, completes an approval process. For further information, call Robert Humphrey at 651-266-9123.

Please note that permits cannot be issued online. Permits must be applied for in person, via fax or mail.

ZONING

1. This property is in a(n) R4/RM2 zoning district.
2. This property was inspected as a Single Family Dwelling.

BUILDING Inspector: Clint Zane

Phone: 651-266-9029

1. Install handrails (34 inches - 38 inches above each nosing) and guardrails (36

- inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment. MNRC Ch 1309 Sect. 311 & 312
2. Any framing members that required repair or do not meet code (where wall and ceiling covering is removed, members that are over-spanned, over-spaced, not being carried properly, door and window openings that are not adequately supported, etc.) are to be reconstructed in an approved manner. SPLC 34.34 (1)
***Deck: Rim joist needs to be doubled up, verify ledger attachment, repair or replace guard rails.
 3. Air-seal and insulate attic/access door. MN Energy Code Ch 1322.1102.4
 4. Install Smoke Detectors/Carbon Monoxide Detectors per MN Conservation Code and the MN Dept. of Labor and Industry: Install per code where feasible. MNRC Ch 1309 Sect 313.2.1
 5. Provide major clean-up of premises. SPLC 34.34 (4)
 6. Repair siding, soffit, fascia, trim, etc. as necessary. SPLC 34.09 (1)
 7. Replace damaged garage overhead door(s).
 8. Repair or replace retaining walls that have eroded and sloped from soil pressures.
 9. Repair or replace fences.
 10. Provide complete storms and screens, in good repair for all door and window openings. SPLC 34.09 (3e)
 11. Provide functional hardware at all doors and windows. SPLC 34.09 (3f)
 12. Exit doors shall be capable of being opened from the inside, easily and without the use of a key. Remove all surface bolts. SPLC 34.09 (3h)
 13. Repair or replace damaged doors and frames as necessary, including storm doors. SPLC 34.09 (3f)
 14. Weather seal exterior doors, threshold and weather-stripping. SPLC 34.09 (3f)
 15. Install floor covering in bathroom and kitchen that is impervious to water. SPLC 34.10 (4)
 16. Repair walls, ceiling and floors throughout, as necessary. SPLC 34.34 (6)
***Hole in rear of cabinet with electrical box.
 17. Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present. SPLC 34.33 (1)
 18. A building permit is required to correct the above deficiencies. All work is to be done in a workmanship like manner. SPLC 33.03 (a)

ELECTRICAL Inspector: Randy Klossner

Phone: 651-266-9032

1. Properly wire electric range receptacle/branch circuit/overcurrent device to current NEC.
2. Verify that fuse/circuit breaker amperage matches wire size in panel. Replace improperly sized overcurrent devices. Article 240.4, NEC
3. Close openings in service panel/junction boxes with knockout seals, breaker blanks, proper cable clamps, and/or junction box covers. Article 110.12 (A), NEC

4. Repair or replace all broken, painted over, corroded, missing or loose receptacles, luminaires (light fixtures), switches, covers and plates to current code. Article 406.4(D) & Article 410, NEC
5. Check all receptacles for proper polarity (including 2-prong) and verify ground on 3-prong receptacles. Ensure all GFCI receptacles are functioning properly. Rewire and/or replace receptacles that are improperly wired or not functioning properly. Article 406.4(D), NEC
6. No access to the garage at time of inspection, insure garage is wired to NEC standards.
7. All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

PLUMBING Inspector: Paul Zellmer

Phone: 651-266-9048

1. Basement -Plumbing - General -(MPC .0101 Subp. 6) Remove all unused waste, vent, water and gas piping to the main and cap or plug to code.
2. Basement -Toilet Facilities -(MPC 301.1) Repair/replace the fixture that is missing, broken or has parts missing.
3. Basement -Water Heater -(MPC .0100 Q)The water heater must be fired and in service.
4. Basement -Water Piping -(MPC 301.1 (3))Repair or replace all the corroded, broken, or leaking water piping.
5. Bathroom -Plumbing - General -(MPC 402.2) Provide a water tight joint between the fixture and the wall or floor.
6. First Floor -Sink -(MPC 301.1) Repair/replace the fixture that is missing, broken or has parts missing.
7. First Floor -Toilet Facilities -(MPC 301.1) Repair/replace the fixture that is missing, broken or has parts missing.
8. Second Floor -Toilet Facilities -(MPC 301.1) Repair/replace the fixture that is missing, broken or has parts missing.
9. All the above corrections to waste, vent, water, and gas piping shall be per the Minnesota Plumbing Code Chapter 4714, Minnesota Rules Chapter 326, 4716, 1300, the Minnesota Mechanical Code, the Minnesota Fuel Gas Code, and Saint Paul Regional Water Services Water Code. All plumbing must be done by a plumbing contractor licensed in the State of Minnesota and the City of St. Paul by a plumber licensed in the State of Minnesota who also possess a City of Saint Paul Competency Card and after obtaining an approved City of Saint Paul Plumbing Permit.

Heating Inspector: Aaron Havlicek

Phone: 651-266-9043

1. Clean and Orsat test furnace/boiler burner. Check all controls for proper operation. Check furnace heat exchanger for leak; provide documentation from a licensed contractor that the heating unit is safe.
2. Provide a means of returning air from every habitable room to the furnace. Return air can not be taken from closets, bathrooms, toilet rooms, kitchen, or mechanical rooms.

3. Vent clothes dryer to code.
4. Provide support for gas lines to code.
5. Provide a window in the bathrooms with an aggregate glazing area of not less than 3 square feet, one-half of which must be openable or provide exhaust system vented to outside. A mechanical ventilation permit is required if an exhaust system is installed.
6. All supply and return ducts for warm air heating system must be clean before final approval for occupancy. Provide access for inspection of inside of ducts or provide documentation from a licensed duct-cleaning contractor that the duct system has been cleaned.
7. Repair and/or replace heating registers as necessary.
8. Provide heat in every habitable room and bathrooms.
9. Verify that A/C system is operable, if not, repair, replace or remove and seal all openings.
10. Run A/C condensate drain three-quarter inch nominal size to an approved location and secure as needed.
11. Mechanical permits are required for the above work.

Notes:

1. See attachment for permit requirements and appeals procedure.
2. This property is designated by the Vacant Buildings Department as a Category #3 which requires a \$5,000.00 Performance Bond or Deposit at the time the permit is issued.
3. Roof, sidewalks, etc. snow covered and could not be inspected. All must meet appropriate codes when completed.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected in accordance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34) and all required permits must receive final approval within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

Re: 1011 Burns Ave
March 01, 2023
Page 5

If you have any questions regarding this inspection report, please contact Clint Zane between 7:30 - 9:00 AM at 651-266-9029 or leave a voice mail message.

Sincerely,

Clint Zane
Code Compliance Officer
Department of Safety and Inspections
City of Saint Paul
375 Jackson Street, Suite 300
Saint Paul MN 55101
Phone: 651-266-9029
Email: Clint.Zane@ci.stpaul.mn.us

Attachments