From: Palm, Michael (CI-StPaul)
To: Doody, Melissa (CI-StPaul)

**Subject:** 823 Englewood

**Date:** Friday, October 2, 2020 8:04:38 AM

Attachments: image002.png

image003.png image004.png

Basement bedroom - No egress window, It does have a door that goes to a stairway that goes directly out the rear side of the house. It also has No heat in the room but it does have a hot water heater in the closet.

Main floor looked ok.

 $2^{nd}$  floor has a bedroom with No heat in the room rear side of the house. Bathroom has questionable height problems.

I will send you pictures of the place that I took.

I will also send you the other trades findings.

Mike



City in America

## **Michael Palm**

Sr. Building Inspector

Dept of Safety and Inspections 375 Jackson St. Suite 220 Saint Paul, MN 55102 P: 651-266-9025

C: 651-248-9025

F: 651-266-9099

michael.palm@ci.stpaul.mn.us



Making Saint Paul the Most Livable City in America

"DSI's Mission: To preserve and improve the quality

Of life in St. Paul by protecting and promoting

Public health and safety for all."