

□ Other

The City Clerk needs the following to process your appeal:

APPLICATION FOR APPEAL

RECEIVED

APR 27 2011

CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

YOUR HEARING Date and Time:

\$25 filing fee payable to the City of S	aint Paul	5 10 11
∀ (if cash: receipt number)	7	uesday, 9-10-11
Copy of the City-issued orders or lett	er which	ime1-30
are being appealed		ime
Attachments you may wish to includ	Ei .	ocation of Hearing:
	R	Room 330 City Hall/Courthouse
		Walkin
Address Being Appeal	ed:	
Number & Street: 1036-57		
Appellant/Applicant: MARY /	DENST Email	mjwendt Otravelers.co.
Phone Numbers: Business 310 – 331	5 Residence <u>748 ~ 1</u>	0272 Cell
Signature: Dary We	nd4	Date: 4/19/2011
Name of Owner (if other than Appellant):		
Address (if not Appellant's): /580	MCKNIGHT RE	N. MAPLELEDOS, MN
Phone Numbers: Business		
What Is Being appealed	d and why? A	ttachments Are Acceptable
Vacate Order/Condemnation/		
Revocation of Fire C of O	Secretary to the second secretary for the second se	
☐ Summary/Vehicle Abatement		
□ Fire C of O Deficiency List		
Fire C of O: Only Egress Windows	PHE WINDOWS A BY A PREVIOU.	RE NEWER LUINDOWS PUT IN SOWNER - THEY ARE IN
□ Code Enforcement Correction Notice	UERY 6-000 CO	NSITION - CORRECTION
□ Vacant Building Registration (COCCO - I HI	SUE PUT A LOT OF
□ Other	MONEY INTO	FIXING THIS HOME
□ Other		SAFE & ENTOYABLE

FOR TENANTS-PLEASE CONSIDER LIFTING THIS BEQUIREMENT Revised 8/20/2010



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

April 15, 2011

MARY WENDT 1580 MCKNIGHT RD N MAPLEWOOD MN 55119-3194

FIRE INSPECTION CORRECTION NOTICE

RE:

1036 5TH ST E

Ref. #116159

Residential Class: C

Dear Property Representative:

Your building was inspected on April 14, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on May 16, 2011 at 11:15 am.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. EXTERIOR SPLC 34.09 (3), 34.32 (3) Provide or repair and maintain the window screens.
- 2. INTERIOR BASEMENT MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 3. INTERIOR MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.-Provide smoke detector for main floor and basement bedroom.

- 4. INTERIOR MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Upon inspection, double-hung windows in both main floor bedrooms measured 16 inches openable height x 30 inches openable width.
- 5. INTERIOR BASEMENT MSFC 605.4 Discontinue use of all multi-plug adapters.
- 6. INTERIOR BASEMENT UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work DOES require a permit(s). Call DSI at (651) 266-8989.-Current vent is flexible plastic.
- 7. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 8. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: kelly.booker@ci.stpaul.mn.us or call me at 651-266-8985 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Kelly Booker Fire Inspector

Reference Number 116159