# TA THE REAL PROPERTY OF THE PARTY OF THE PAR

## APPLICATION FOR APPEAL

# RECEIVED

JUN 0 3 2011

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

|     | 0011 00 2011   |                               |
|-----|--|-------------------------------|
| The | City Clerk needs the following to process your appeal RK | YOUR HEARING Date and Time:   |
|     | \$25 filing fee payable to the City of Saint Paul        |                               |
| *   | (if cash: receipt number)                                | Tuesday, June 14, 2011        |
|     | Copy of the City-issued orders or letter which           | 15 72 00                      |
|     |  | Time 1.50 p. M.               |
|     | Attachments you may wish to include                      | Location of Hearing:          |
| A   | This appeal form completed                               | Room 330 City Hall/Courthouse |
|     | •  | walkin                        |

# **Address Being Appealed:**

| Address being Appea  | icu.   |
|--|--|
| Number & Street: 674 Van   | Buren Wity: St. Paul State: MN Zip: SS Jay               |
| Appellant/Applicant: Leslie  | te, Lucut Email Les 1960 2003 & Yahoo. Co.               |
| Phone Numbers: Business 651 36  Signature: L   | 789848 Residence 6514897436 Cell  Date: 6131 2011        |
| Name of Owner (if other than Appellant)  | : Leslie to Lucht  |
| Address (if not Appellant's): 10 90  | camberland St. St. Paul, men 55004                       |
| Phone Numbers: Business  | Residence 6514897436 Cell                                |
| What Is Being appeale  | ed and why? Attachments Are Acceptable                   |
| Vacate Order/Condemnation/ Revocation of Fire C of O  Summary/Vehicle Abatement Fire C of O Deficiency List Fire C of O: Only Egress Windows  Code Enforcement Correction Notice Vacant Building Registration  Other | #1,#4,#10# 20#15, Anlact enoughtime Lix all other items, |
| □ Other  |  |
| - Other  |  |

Revised 8/20/2010



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

May 23, 2011

ELIZABETH LUCHT LESLIE K LUCHT 1090 CUMBERLAND ST ST PAUL MN 55117-4869

# FIRE INSPECTION CORRECTION NOTIC

RE:

674 VAN BUREN AVE

Ref. #102794

Residential Class: C



### Dear Property Representative:

Your building was inspected on May 20, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. <u>A re-inspection will be made on June 24, 2011 at 11:00am.</u>

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

### **DEFICIENCY LIST**

1. Basement - MSFC1026.1 - Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)-266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Repair the egress window in the basement also remove all refuse in the window well.

- 2. Basement MSFC 1011.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.-Repair the egress window in the basement also remove all refuse in the window well.
- 3. Basement UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work will require a permit(s). Call DSI at (651) 266-8989.-Contact a licensed contractor it install the dryer vent to code, all work must be done under permit and approved.

On inspection the dryer vent was not connected to the dryer in several places clean up and remove all lint and other combustibles around the dryer.

- 4. Basement MSFC 605.5.3 Immediately, discontinue use of frayed, deteriorated, damaged or spliced electrical cords.-Replace the damaged electrical wiring and fixture that were damaged by a large amount of clothing hanging from the wire and fixture. this work must be done by a licensed electrician under permit and approved.
- 5. Basement SPLC 34.10 (1) Abate and maintain the basement reasonably free from dampness and free of mold and mildew.-Repair the foundation signs of deterioration and water infiltration into the basement are present.

Once repairs have been done clean up and remove all water and water damaged material.

- 6. Basement MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 7. Bathroom SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 Repair or replace and maintain the plumbing fixture to an operational condition.-Repair or replace and maintain an approved private hand sink in the bathroom off the kitchen. The sink must be properly secured to the wall in a professional manner.
- 8. Exterior SPLC 34.09 (3), 34.32 (3) Provide or repair and maintain the window screen.
- 9. Exterior SPLC 34.09 (3), 34.32 (3) Repair and maintain the window glass.
- 10. Exterior SPLC 34.09 (1) e, 34.32 (1) d Provide and maintained the roof weather tight and free from defects.-Repair and re-paint sofit and fasica in an approved manner
- 11. Exterior SPLC 34.09 (1) b,c, 34.32 (1) b,c Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.-Repair and repaint the unprotected wood surfaces Window frames and sills in an approved manner. Repair or replace missing and damaged siding with approved material.

- 12. Exterior SPLC 34.09 (1) a, 34.32 (1) a Provide and maintain foundation elements to adequately support this building at all points. Repair the foundation in an approved manner this work may require a permit for structural repair to foundation.-Repair the foundation signs of deterioration and water infiltration into the basement are present.
- 13. Exterior SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition.- Front screen door
- 14. Exterior MSFC 605.5.3 Immediately, discontinue use of frayed, deteriorated, damaged or spliced electrical cords.-Contact a licensed electrican
- 15. Exterior SPLC 34.08 (3) Provide and maintain suitable ground cover on all exterior areas to control erosion.
- 16. Kitchen SPLC 34.10 (7), 34.33 (6) Repair and maintain the cabinets in an approved manner.-Repair or replace the damaged or missing door.

  Repair or replace the damaged framing.

  Repair or replace the damaged or missing hardware.
- 17. Upper Bedrooms MSFC 1011.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.-Remove objects in front of the bedroom door or egress window to the exterior.
- 18. Upper Bedrooms SPLC 34.09 (2) 34.32 (2) Provide an approved guardrail with intermediate ballustrade or rails 4 inches or less apart. This work may require a permit(s). Call DSI at (651) 266-9090.-Around the flat room
- 19. Upper bathroom SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls in an approved manner.-Paint the wall.

  Patch the holes and/or cracks in the walls.
- 20. Upper bathroom SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.-Paint the ceiling.

  Patch the holes and/or cracks in the ceiling.
- 21. Upper rooms SPLC 34.10 (7), 34.33 (6) Replace and maintain the woodwork and doors in an approved manner.-Replace all damaged doors throughout and on the second floor.
- 22. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.

\For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse,

15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: mike.urmann@ci.stpaul.mn.us or call me at 651-266-8990 between 8:00 a.m. - 9:30 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Michael Urmann Fire Inspector

Reference Number 102794