



CITY OF SAINT PAUL
Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220
Saint Paul, Minnesota 55101-1806

Telephone: 651-266-8989
Facsimile: 651-266-9124
Web: www.stpaul.gov/dsi

September 16, 2010

DINA DIAZ
1307 MAYNARD DRIVE APT 10
ST PAUL MN 55116

Re: 718 Lafond Ave
File#: 06 085192 VB2

Dear Property Owner:

The following is the Code Compliance report you requested on August 30, 2010.

Please be advised that this report is accurate and correct as of the date September 16, 2010. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from September 16, 2010. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected:

BUILDING **Inspector: Jim Seeger** **Phone: 651-266-9046**

- Insure basement cellar floor is even, is cleanable, and all holes are filled.
- Dry out basement and eliminate source of moisture.
- Remove mold, mildew and moldy or water damaged materials.
- Install handrails (34 inches - 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment.
- Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary.
- Provide complete storms and screens, in good repair for all door and window openings.
- Provide functional hardware at all doors and windows
- Exit doors shall be capable of being opened from the inside, easily and without the use of a key. Remove all surface bolts.
- Repair or replace damaged doors and frames as necessary, including storm doors.
- Repair walls, ceiling and floors throughout, as necessary.
- Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present.
- Air-seal and insulate attic/access door.

BUILDING **Inspector: Jim Seeger** **Phone: 651-266-9046**

- Install Smoke Detectors/Carbon Monoxide Detectors per MN Co Conservation Code and the MN Dept. of Labor and Industry.
- Habitable rooms with new usage and replaced windows shall have glass area equal to 8% of floor area, one-half of which shall operate.
- Provide major clean-up of premises.
- Repair siding, soffit, fascia, trim, etc. as necessary.
- Provide proper drainage around house to direct water away from foundation of house.
- Review all applicable codes & policies when replacing windows including egress windows for sleeping rooms.
- Openings in stair risers must be less than 4 inches.
- Repair front gate or remove.
- Properly flash and install front porch windows to code.
- Basement door not to wing over stairs.
- Remove illegal bedroom from basement.
- Second floor has one legal bedroom.
- Insure roof has step flashings on roof gable ends.
- Jack up and re level front and east side porch and supply footings and support to code with inspections before covering.
- A building permit is required to correct the above deficiencies.

ELECTRICAL **Inspector: Dan Jambor** **Phone: 651-266-9032**

- Ground the electrical service to the water service with a copper conductor within 5 feet of the entrance point of the water service
- Bond around water meter with a copper wire sized for the electrical service per Article 250 of the NEC
- Provide a complete circuit directory at service panel indicating location and use of all circuits
- verify/install a separate 20 ampere laundry circuit and a separate 20 ampere kitchen appliance circuit
- Verify that fuse/circuit breaker amperage matches wire size
- Ground bathroom light in basement/first bathroom/second bathroom and disconnect receptacle on fixture
- Install globe-type enclosed light fixture on all closet lights
- Repair or Replace all broken, missing or loose light fixtures, switches and outlets, covers and plates
- Check all outlets for proper polarity and verify ground on 3-prong outlets
- Remove any 3-wire ungrounded outlets and replace with 2-wire or ground 3-wire to code
- Remove and or/ re-wire all illegal, improper or hazardous wiring in basement/garage
- Replace all painted-over receptacles.
- Throughout building, install outlets and light fixtures as specified in Bulletin 80-1.
- Provide ground rod.

ELECTRICAL **Inspector: Dan Jambor** **Phone: 651-266-9032**

- All added receptacles must be grounded, tamper-resistant and be on an Arc-Fault Circuit Interrupter-protected circuit.
- Any open walls or walls that are opened as part of this project must be wired to the standards of the 2008 NEC.
- All buildings on the property must meet the St. Paul Property Maintenance Code (Bulletin 80-1).
- All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

PLUMBING **Inspector: Tom Schweitzer** **Phone: 651-266-9055**

- Basement - Gas Piping - dryer gas shutoff; connector or piping incorrect (IFGC 402.1)
- Basement - Gas Piping - run dryer vent to code (IFGC 613.1 - IMC 604.1)
- Basement - Laundry Tub - unvented (MPC 0200 E)
- Basement - Soil and Waste Piping - no front sewer clean out (MPC 1000)
- Basement - Soil and Waste Piping - no soil stack base clean out
- Basement - Toilet Facilities - unvented (MPC 0200. E)
- Basement - Water Heater - No gas shut off or gas piping incorrect (IFGC 402.1)
- Basement - Water Heater - Vent must be in chimney liner (IFGC 501.12)
- Basement - Water Heater - Water piping incorrect (MPC 1730 Subp. 1)
- Basement - Water Heater - not fired or in service (MPC 2180)
- Basement - Water Meter - remove meter from pit (MPC 88.08)
- Basement - Water Piping - repair or replace all corroded, broken or leaking piping (MPC 4715.1720)
- Basement - Water Piping - run 1 inch water line from meter to first major take off (SPRWS Water Code)
- First Floor - Sink - incorrectly vented (MPC 2500)
- First Floor - Sink - waste incorrect (MPC 2300)
- Second Floor - Lavatory - waste incorrect (MPC 2300)
- Second Floor - Tub and Shower - provide anti-scald valve (MPC 1380. Subp. 5)
- Obtain plumbing permits prior to commencement of work.

HEATING **Inspector: Kevin Chapdelaine** **Phone: 651-266-9042**

- Install approved lever handle manual gas shutoff valve on furnace and remove unapproved valve.
- Install approved lever handle manual building shutoff gas valve in an accessible location ahead of the first branch tee.
- Clean and Orsat test furnace burner. Check all controls for proper operation. Check furnace heat exchanger for leaks; provide documentation from a licensed contractor that the heating unit is safe.
- Install approved metal chimney liner.
- Connect furnace and water heater venting into chimney liner.
- Vent clothes dryer to code.

September 16, 2010
718 Lafond Ave
Page 4

HEATING **Inspector: Kevin Chapdelaine** **Phone: 651-266-9042**

- Provide appropriate size operable window in bathrooms or provide exhaust system vented to outside. A mechanical ventilation permit is required if an exhaust system is installed.
- All supply and return ducts for warm air heating system must be clean before final approval for occupancy. Provide access for inspection of inside of ducts or provide documentation from a licensed duct-cleaning contractor that the duct system has been cleaned.
- Repair and/or replace heating registers as necessary.
- A gas mechanical permit is required for the above work.

ZONING

1. This property is in a(n) R4 zoning district.
2. This property was inspected as a Single Family Dwelling.

Notes:

- See attachment for permit requirements and appeals procedure.
- Most of the roof covering could not be inspected from grade. Recommend this be done before rehabilitation is attempted.
- There was considerable storage/clutter within property at the time of the inspection. Property is to meet appropriate Codes when complete.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Jim Seeger between 7:30 - 9:00 AM at 651-266-8989 or leave a voice mail message.

Sincerely,
James L. Seeger
Code Compliance Officer

JLS:dj

Attachments