Saint Paul Safety & Inspections

375 Jackson Street #220

St. Paul, MN 55101

RE: 1436 Snelling Ave N SPLC 34.23

Photos were taken by Roy Kingsley DSI Fire Inspector

1. Front of 1436 Snelling
2. Front of house
3. Address of house
4. Front door of house
5. Looking at living room from front door
6. Staircase to 2nd floor.
7. Bathroom at top of 2nd floor
8. Bedroom to the left of hallway
9. Looking at bedroom window.
10. Close look at bedroom window is not operational and taped up.
11. Bedroom to the right on 2nd floor
12. Bedroom window of bedroom on the right
13. Another window located in 2nd bedroom.
14. 2nd floor bedroom sink with sign located on top do not use.
15. Smoke detector located at top of stairs on 2nd floor.
16. Ceiling panel for the 2nd floor bedroom.
17. Another view of the smoke detector on 2nd floor with rapping still on it.
18. Light fixture in hallway of the 2nd floor hanging by the wires.
19. Exit door location on the 2nd floor to outside roof.
20. Looking at roof line from 2nd floor exit door.
21. Storage tote in living room
22. Extension cord located in the living room.
23. Same extension cord showing it was not plug into it this time.
24. Cox cable from living room to upper level.
25. Fly strip located in the living room.
26. Another fly strip located in the living room.
27. Looking at room next to the living room.
28. Window located in room next to living room.
29. Blue extension cord from living room to kitchen.

30. Blue extension cord plugs into outlet in living room.
31. Blue extension cord behind refrigerator.
32. Another look at blue extension cord behind refrigerator.
33. Refrigerator cord plugs into blue extension cord.
34. Pizza oven located in the kitchen.
35. Looking at kitchen sink.
36. Kitchen stove top with combustibles located on it.
37. Kitchen counter space
38. Another look at kitchen counter space
39. Stairwell to basement.
40. Standing at bottom of stairs to the basement looking at bedroom.
41. Looking down hallway to laundry room.
42. Looking at storage next to furnace
43. Looking at freezer, dryer and wash machine located in the laundry room.
44. Looking at gas line located
45. Looking at wiring for old phone lines.
46. Storage located on top of washer machine.
47. More storage next to wash machine.
48. Light fixture located in laundry room missing light bulb.
49. Fly strip located in lower-level laundry room.
50. Gas line for furnace with gas valve in the open position.
51. Looking into bedroom located in lower level.
52. Another view of lower-level bedroom with no egress window.
53. Window located in lower-level bedroom.
54. Ceiling in lower-level bedroom.
55. Storage located on furnace
56. Looking inside furnace burn area
57. Looking at the lower level of furnace with cobwebs throughout.
58. Room located in rear of home on the main level going to the outside.
59. Light fixture in back room
60. Power strip located in back room for permanent power.
61. Outlet in back room of main level.
62. Rear door of the house
63. Photo of Condemned date 11/7/2025
64. Pole located at front door deconstruction.
65. Front door with Condemned placard date 11/7/2025