Saint Paul Fire Department
645 Randolph Avenue
Saint Paul, MN 55102
(651) 224-7811

NFIRS-1 Basic

A

FDID	State	Month	Day	Year	Station	Number	Exposure
62210	MN	08	11	2024	Station #18 (18)	SPFD240811039322	0

B **Location Type**

Census tract: 0325.00

- [x] Street Address
- [ ] Intersection
- [ ] In Front Of
- [ ] Rear Of
- [ ] Adjacent To
- [ ] Directions
- [ ] US National Grid

Number	Prefix	Street or Highway	Street Type	Suffix
799		UNIVERSITY	AVE-Avenue	W-West

Apt./Suite/Room	City	State	Zip Code
	Saint Paul	MN	55104

Cross Street:

C **Incident Type**

111-Building fire

D **Aid Given Or Received**

- [ ] 1 Mutual Aid Received
- [ ] 2 Auto. Aid Received
- [ ] 3 Mutual Aid Given
- [ ] 4 Auto. Aid Given
- [ ] 5 Other Aid Given
- [x] None

Their FDID | Their State

Their Incident Number

E1 **Dates and Times**

Alarm	08	11	2024	23:12
Arrival	08	11	2024	23:13
Controlled				
Last Unit Cleared	08	12	2024	10:27

E2 **Shifts and Alarms**

Shift or Platoon	Alarms	District
A	2	D2

E3 **Special Studies**

ID#	Value
9244	4 - Unknown

F **Actions Taken**

11-Extinguishment by fire service personnel

Primary Action Taken

12-Salvage & overhaul

Additional Action Taken

84-Refer to proper authority

Additional Action Taken

G1 **Resources**

☑ Apparatus or Personnel Module is used.

	Apparatus	Personnel
Suppression	20	0
EMS	2	0
Other	1	0

☐ Resource counts include aid received resources.

G2 **Estimated Dollar Losses and Values**

Losses: Required for all fires if known. Optional for all non-fires. None

Property: $ 160,000.00 ☐

Contents: $ 120,000.00 ☐

Pre-Incident Values: Optional None

Property: $ 160,000.00 ☐

Contents: $ 120,000.00 ☐

Completed Modules

☐ 2 - Fire
☐ 3 - Structure Fire
☐ 4 - Civilian Fire Cas.
☐ 5 - Fire Service Cas.
☐ 6 - EMS
☐ 7 - HazMat
☐ 8 - Wildland Fire
☐ 9 - Apparatus
☐ 10 - Personnel
☐ 11 - Arson

H1 **Casualties** ☑ None

	Deaths	Injuries
Fire Service	0	0
Civilian	0	0

H2 **Detector**

Required for Confined Fires

☐ 1 - Detector Alerted Occupants
☐ 2 - Detector Did Not Alert Them
☐ 3 - Unknown

H3 **Hazardous Materials Release**

☐ 1 - Natural Gas
☐ 2 - Propane Gas
☐ 3 - Gasoline
☐ 4 - Kerosene
☐ 5 - Diesel Fuel / Fuel Oil
☐ 6 - Household Solvents
☐ 7 - Motor Oil
☐ 8 - Paint
☐ 0 - Other
☑ None

I **Mixed Use Property**

☐ Not Mixed
☐ 10 - Assembly Use
☐ 20 - Education Use
☐ 33 - Medical Use
☐ 40 - Residential Use
☐ 51 - Row Of Stores
☐ 53 - Enclosed Mall
☐ 58 - Business and Residential
☑ 59 - Office Use
☐ 60 - Industrial Use
☐ 63 - Military Use
☐ 65 - Farm Use
☐ 00 - Other Mixed Use

J **Property Use** ☐ None

Structures

131 ☐ Church, Place of Worship
161 ☑ Restaurant or Cafeteria
162 ☐ Bar/Tavern or Nightclub
213 ☐ Elementary School, Kindegarten
215 ☐ High School, Junior High
241 ☐ College, Adult Education
311 ☐ Nursing Home
331 ☐ Hospital
341 ☐ Clinic, Clinic-Type Infirmary
342 ☐ Doctor/Dentist Office
361 ☐ Prison or Jail, Not Juvenile
419 ☐ 1- or 2-Family Dwelling
429 ☐ MultiFamily Dwelling
439 ☐ Rooming/Boarding House
449 ☐ Commerical Hotel or Motel
459 ☐ Residential, Board and Care
464 ☐ Dormitory/Barracks
519 ☐ Food and Beverage Sales
539 ☐ Household Goods, Sales, Repairs
571 ☐ Gas or Service Station
579 ☐ Motor Vehicle/Boat Sales/Repairs
599 ☐ Business Office
615 ☐ Electric-Generating Plant
629 ☐ Laboratory/Science Laboratory
700 ☐ Manufacturing Plant
819 ☐ Livestock/Poultry Storage (Barn)
882 ☐ Non-Residential Parking Garage
891 ☐ Warehouse

Outside

124 ☐ Playground or Park
655 ☐ Crops or Orchard
669 ☐ Forest (Timberland)
807 ☐ Outdoor Storage Area
919 ☐ Dump or Sanitary Landfill
931 ☐ Open Land or Field
936 ☐ Vacant Lot
938 ☐ Graded/Cared for Plot of Land
946 ☐ Lake, River, Stream
951 ☐ Railroad Right-of-Way
960 ☐ Other Street
961 ☐ Highway/Divided Highway
962 ☐ Residential Street/Driveway
981 ☐ Construction Site
984 ☐ Industrial Plant Yard

Property Use:

Description

Look up and enter a Property Use code and description only if you have NOT checked a Property Use box.

K2

Owner

Local Option	Person/Entity Type	Business Name (if applicable)	Phone Number

Mr., Ms., Mrs.	First Name	MI	Last Name	Suffix

Number	Prefix	Street or Highway	Street Type	Suffix

Post Office Box	Apt./Suite/Room	City

State	Zip Code

L **Remarks:**

Saint Paul fire crews were called for a report of a building fire. Crews arrived to find heavy smoke and fire on the first and second floors of a 2-story multi-occupancy structure. A restaurant occupied the first floor, and storage occupied the basement and second floor.

Fire crews performed forcible entry, made entry, and attempted to extinguish the fire. Squad 2 encountered high heat, fire, and heavy smoke in the stairwell leading to the second floor. Squad 2's hose line malfunctioned, and the crew backed out. Additional crews attempted to locate basement access.

Water supplies were established. Ladder 22 and Ladder 18 deployed their aerials for use and secured water supplies as well. Heavy smoke became visible from the entire Bravo side at the roofline, as well as just above ground level on the Delta side.

The decision was made to transition to a defensive strategy. All fire companies exited the structure and prepared for defensive operations. PAR was conducted and all crews were accounted for.

Ladder 22 employed their aerial master stream from the B side, into the second floor. A sizeable percentage of the fire was knocked down with the master stream use, and that was shut down.

After conferring with senior command staff, the decision was made to once again make entry with hand lines and conduct final extinguishment of the remaining fire. Ladder 6's crew and Ladder 18's crew made vent/inspection holes in the roof, and determined the roof was not involved in fire....

Full primary narrative can be found in NFIRS 1S - Supplemental

M **Authorization**

Officer In Charge ID	Signature	Position or Rank	Assignment	Date
4804	Wolfsberger, John	DC	C2	08/12/2024

Member Making Report ID	Signature	Position or Rank	Assignment	Date
4804	Wolfsberger, John	DC	C2	08/12/2024

NFIRS-2 Fire

A

FDID	State	Month	Day	Year	Station	Number	Exposure
62210	MN	08	11	2024	Station #18 (18)	SPFD240811039322	0

B

Property Details

B1 ☐ ☑ Not Residential

Estimated number of residential living units in the building of origin whether or not all units became involved

B2 1 ☐ Buildings Not Involved

Number of buildings involved

B3 ☑ None ☐ Less than 1 acre

Acres burned (outside fires)

C

On-Site Materials Or Products

On-Site Materials Storage Use

D

Ignition

D1 05-Entranceway, lobby

Area of Fire Origin

D2 13-Electrical arcing

Heat Source

D3 81-Electrical wire, cable insulation

Item First Ignited

D4

Type of Material First Ignited

E1

Cause of Ignition

☐ 1 - Intentional
☑ 2 - Unintentional
☐ 3 - Failure of Equipment or Heat Source
☐ 4 - Act of Nature
☐ 5 - Cause Under Investigation
☐ U - Cause Undetermined After Investigation

E2

Factors Contributing to Ignition

30-Electrical failure, malfunction, other

Factor Contributing to Ignition

E3

Human Factors Contributing to Ignition

Check all applicable boxes

☑ None
☐ 1 - Asleep
☐ 2 - Possibly impaired by alcohol or drugs
☐ 3 - Unattended person
☐ 4 - Possibly Mentally Disabled
☐ 5 - Physically Disabled
☐ 6 - Multiple Persons Involved

☐ 7 - Age Was A Factor

Estimated Age of Person Involved

☐ Male ☐ Female

F1

Equipment Involved In Ignition

☑ None

☐

Equipment Involved

Brand

Model

Serial #

Year

F2

Equipment Power Source

☑

☐

Equipment Power Source

F3

Equipment Portability

☐ 1 - Portable
☐ 2 - Stationary

Portable equipment normally can be moved by one or two persons.

G

Fire Suppression Factors

None

Fire Suppression Factor

H1

Mobile Property Involved

- [ ] 1 - Not involved in ignition, but burned
- [ ] 2 - Involved in ignition, but did not burn
- [ ] 3 - Involved in ignition and burned
- [x] None

H2

Mobile Property Type and Make

Mobile Property Type

Mobile Property Make

Mobile Property Model

Year

State

License Plate Number

VIN

Local Use

- [ ] Pre-Fire Plan Available
- [ ] Arson Report Attached
- [ ] Police Report Attached
- [ ] Coroner Report Attached
- [ ] Other Reports Attached

NFIRS-3 Structure Fire

I1

Structure Type

- [x] 1 - Enclosed Building
- [ ] 2 - Portable/Mobile Structure
- [ ] 3 - Open Structure
- [ ] 4 - Air-Supported Structure
- [ ] 5 - Tent
- [ ] 6 - Open Platform
- [ ] 7 - Underground Structure
- [ ] 8 - Connective Structure
- [ ] 0 - Other

I2

Building Status

- [ ] 1 - Under Construction
- [x] 2 - In Normal Use
- [ ] 3 - Idle, Not Routinely Used
- [ ] 4 - Under Major Renovation
- [ ] 5 - Vacant and Secured
- [ ] 6 - Vacant and Unsecured
- [ ] 7 - Being Demolished
- [ ] 0 - Other
- [ ] U - Undetermined

I3

Building Height

2
Number of Stories At/Above Grade

1
Number of Stories Below Grade

I4

Main Floor Size

1900
Total Square Feet

OR

____ BY ____
Length (ft) X Width (ft)

J1

Fire Origin

1 [ ] Below Grade
Story of Fire Origin

J2

Fire Spread

- [ ] Confined to Object of Origin
- [ ] 2 - Confined to Room of Origin
- [ ] 3 - Confined to Floor of Origin
- [x] 4 - Confined to Building of Origin
- [ ] 5 - Beyond Building of Origin

J3

Number of Stories Damaged By Flame

____ Number of Stories w/Minor Damage (1-24%)
____ Number of Stories w/Significant Damage (25-49%)
____ Number of Stories w/Heavy Damage (50-74%)
____ Number of Stories w/Extreme Damage (75-100%)

*Count the roof as part of the highest story

K

Type of Material Contributing Most to Flame Spread

K1 __
Item Contributing Most to Flame Spread

K2 __
Type of Material Contributing Most To Flame Spread

L1

Presence of Detectors

- [ ] N - None Present
- [ ] 1 - Present
- [x] U - Undetermined

L2

Detector Type

- [ ] 1 - Smoke
- [ ] 2 - Heat
- [ ] 3 - Combination of Smoke and Heat
- [ ] 4 - Sprinkler, Water Flow Detection
- [ ] 5 - More Than One Type Present
- [ ] 0 - Other
- [ ] U - Undetermined

L3

Detector Power Supply

- [ ] 1 - Battery Only
- [ ] 2 - Hardwire Only
- [ ] 3 - Plug-In
- [ ] 4 - Hardwire With Battery
- [ ] 5 - Plug-In With Battery
- [ ] 6 - Mechanical
- [ ] 7 - Multiple Detectors & Power Supplies
- [ ] 0 - Other
- [ ] U - Undetermined

L4

Detector Operation

- [ ] 1 - Fire Too Small To Activate
- [ ] 2 - Operated
- [ ] 3 - Failed To Operate
- [ ] U - Undetermined

L5

Detector Effectiveness

- [ ] 1 - Alerted Occupants, Occupants Responded
- [ ] 2 - Alerted Occupants, Occupants Failed to Respond
- [ ] 3 - There Were No Occupants
- [ ] 4 - Failed to Alert Occupants
- [ ] U - Undetermined

L6

Detector Failure Reason

- [ ] 1 - Power Failure, Shutoff, or Disconnect
- [ ] 2 - Improper Installation or Placement
- [ ] 3 - Defective
- [ ] 4 - Lack of Maintenance, Dirty
- [ ] 5 - Battery Missing or Disconnected
- [ ] 6 - Battery Discharged or Dead
- [ ] 0 - Other
- [ ] U - Undetermined

M1

Presence of Automatic Extinguishing System

- [ ] N - None Present
- [ ] 1 - Present
- [ ] 2 - Partial System Present
- [x] U - Undetermined

M2

Type of Automatic Extinguishing System

- [ ] 1 - Wet-Pipe Sprinkler
- [ ] 2 - Dry-Pipe Sprinkler
- [ ] 3 - Other Sprinkler System
- [ ] 4 - Dry Chemical System
- [ ] 5 - Foam System
- [ ] 6 - Halogen-Type System
- [ ] 7 - Carbon Dioxide System
- [ ] 0 - Other
- [ ] U - Undetermined

Required if fire was within designed range of AES

M3

Operation of Automatic Extinguishing System

- [ ] 1 - Operated/Effective
- [ ] 2 - Operated/Not Effective
- [ ] 3 - Fire Too Small To Activate
- [ ] 4 - Failed To Operate
- [ ] 0 - Other
- [ ] U - Undetermined

Required if fire was within designed range

M4

Number of Sprinkler Heads Operating

_____

Required if system operated

M5

Reason for Automatic Extinguishing System Failure

- [ ] 1 - System Shut Off
- [ ] 2 - Not Enough Agent Discharged
- [ ] 3 - Agent Discharged But Did Not Reach Fire
- [ ] 4 - Wrong Type of System
- [ ] 5 - Fire Not In Area Protected
- [ ] 6 - System Components Damaged
- [ ] 7 - Lack of Maintenance
- [ ] 8 - Manual Intervention
- [ ] 0 - Other
- [ ] U - Undetermined

Required if system failed or not effective

NFIRS-1S Supplemental

A

FDID	State	Month	Day	Year	Station	Number	Exposure
62210	MN	08	11	2024	Station #18 (18)	SPFD240811039322	0

Primary Narrative:

Saint Paul fire crews were called for a report of a building fire. Crews arrived to find heavy smoke and fire on the first and second floors of a 2-story multi-occupancy structure. A restaurant occupied the first floor, and storage occupied the basement and second floor.

Fire crews performed forcible entry, made entry, and attempted to extinguish the fire. Squad 2 encountered high heat, fire, and heavy smoke in the stairwell leading to the second floor. Squad 2's hose line malfunctioned, and the crew backed out. Additional crews attempted to locate basement access.

Water supplies were established. Ladder 22 and Ladder 18 deployed their aerials for use and secured water supplies as well. Heavy smoke became visible from the entire Bravo side at the roofline, as well as just above ground level on the Delta side.

The decision was made to transition to a defensive strategy. All fire companies exited the structure and prepared for defensive operations. PAR was conducted and all crews were accounted for.

Ladder 22 employed their aerial master stream from the B side, into the second floor. A sizeable percentage of the fire was knocked down with the master stream use, and that was shut down.

After conferring with senior command staff, the decision was made to once again make entry with hand lines and conduct final extinguishment of the remaining fire. Ladder 6's crew and Ladder 18's crew made vent/inspection holes in the roof, and determined the roof was not involved in fire.

Searches were completed, and negative on all floors. The fire was controlled, overhaul completed, and a final washdown was conducted. Car 20-Fire Investigator Blank completed their investigation. DSI, Board-up, Department of Health, and gas/electric were all notified to respond.
Crews were placed back in service and command was terminated.