

The City Clerk needs the following to process your appeal:

\$25 filing fee payable to the City of Saint Paul

APPLICATION FOR APPEAL

RECEIVED
SEP 0 6 2011

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

Revised 3/7/2011

CITY CLERK

(if cash: receipt number)		YOUR HEARING Date and Time:
Copy of the City-issued orders or letter	which	0.2-77
are being appealed		Tuesday, 9-20-11
Attachments you may wish to include		8
This appeal form completed		Time
□ Walk-In OR ☑ Mail-In		Location of Hearing:
□ Walk-In OR		Room 330 City Hall/Courthouse
		mailed gla-11
Address Being Appealed	d:	
Number & Street: 1047 Jessa	mine Fity: 5	t. Paul State: MN Zip: \$5706
Appellant/Applicant: Paul Yung / F	Port- yang Er	mail change tu garga yar socon
Phone Numbers: Business)	Residence	Cell 657 387 /489
Signature: Pau Clayte you	ry/	Date: 9/30/01
Name of Owner (if other than Appellant):		
Address (if not Appellant's):		
Phone Numbers: Business	Residence	Cell
What Is Being Appealed	and Why?	Attachments Are Acceptable
Vacate Order/Condemnation/		
Revocation of Fire C of O		
☐ Summary/Vehicle Abatement		
☐ Fire C of O Deficiency List		
Fire C of O: Only Egress Windows	9	
¥		
□ Code Enforcement Correction Notice		
□ Vacant Building Registration		
C Other		

SAINT PAUL

BUILDING PERMIT

PERMIT #:

20 09 061272

Issued Date:

April 24, 2009

CITY OF SAINT PAUL

PARTMENT OF SAFETY AND INSPECTIONS 375 Jackson Street, Suite 220 Saint Paul, MN 55101-1806

> Phone: 651-266-9090 Fax: 651-266-9124

CONTRACTOR:	OWNER:
	1

MERIT BUILDING COMPANY INC 2393 COON RAPIDS BLVD NW #204 COON RAPIDS MN 55433-0000 POR YANG 1047 JESSAMINE AVE E ST PAUL MN 55106-2733

PERMIT ADDRESS: 1047 JESSAMINE AVE E

ST PAUL MN 55106-2733

SUB TYPE: Single Family Dwelling | WORK TYPE: Express Repair

Owner's First/Last Name por yang & mailee lee Owner's Address 1047 jessamine ave e 651-592-1845 st paul, mn Owner's Phone # w/Area Code Owner's City/State/Zip 8000 # of Existing Dwelling Units 1 State Valuation Windows (Framed Insert or Pocke Valuation Override No Yes # of Windows 20

FEES	
Permit Fee	186.34
Surcharge B	4.00
TOTAL	190.34

house new insert windows **Windows-Add Framed-Insert or "Pocket" Windows: For bedroom windows-egress must be maintained such that no additional frame or construction will be allowed that reduces the window operable opening more than 1 (one) inch on each side. Any deviation from this standard requires special, prior approval from this Office. Safety Glass is required within a tub or shower enclosure, within 2 feet of doors and adjacent to stairs and stair landings, when the glass is less than 60 inches above a walking or standing surface. See other specifics in Section R308 of the International Residential Code (1- and 2-family dwellings) or Chapter 24 of the International Building Code (multi-family and commercial).

NOTE: Smoke alarms shall be installed as specified in the Minnesota State Residential Code, Sec. R313. Call the Area Building Inspector between 7:30-9:00am (M-F) when work is complete or if any problems/questions arise. NOTE: Per Section 33.04 of the Legislative Code all exterior work must be completed within one year of permit issuance.



Section 8 Housing Choice Voucher, Project-Based, Moderate Rehabilitation, or RAFS Program

August 10, 2011

PAUL CHONG TU YANG 979 COOK AVE E #1 SAINT PAUL MN 55106

Inspection of: 1047 Jessamine Avenue, 55106 for (Chue Yang)

Inspection conducted on: August 9, 2011

Inspection conducted by: Pat C.

Type of inspection: New/Mover Initial

The following Housing Quality Standards deficiency(ies) must be repaired for the above unit to qualify for the rent assistance program:

The front bedroom closet door has peeling veneer/hole.

The egress window in the main level front bedroom measured 15-3/4" high by 30 1/2" wide. The minimal egress opening required is 24" high by 20" wide. Every bedroom must have at least one legal egress window. See attached.

3. The egress window in the main level middle bedroom measured 15 3/4" high by 30 1/2" wide. The minimal egress opening required is 24" high by 20" wide. Every bedroom must have at least one legal egress window. See attached.

4. The egress window in the main level rear bedroom measured 15 3/4" high by 30 1/2" wide. The minimal egress opening required is 24" high by 20" wide. Every bedroom must have at least one legal egress window. See attached.

5. The main level bathroom washbasin drain leaks.

6. The kitcher east wall electrical wall outlet to the right of the sink lacks a ground wire.

- 7. The unit has a fireplace. Complete, sign, and return the fireplace consent form. See attached.
- 8. The basement family room north wall electrical outlet is loose in the junction box.

9. The basement northwest area storeroom ceiling light fixture has an open socket.

10. The basement has an incinerator. Remove the incinerator, cap the gas line, and fill the opening to the chimney.

11. The basement bathroom window failed to open.

- 12. The basement northeast area ceiling light fixture has exposed electrical wires.
- 13. The basement laundry room has an unused/uncapped gas line.
- 14. The basement laundry room has an unused/uncapped dryer vent.
- 15. The rear yard has an accumulation of debris/trash. Remove from the premises.

Reinspection: The tenant or owner must call the Inspection Scheduler when the repair work has been completed. Housing Assistance Payments cannot begin before the unit has passed inspection. Payments will not be retroactive.



STAMP - Activity Detail

New Search

Help using this report

E-mail Service Desk

1047 Jessamine Ave E

Click here to access other applications using this address - GISmo, MapIT, and Ramsey County Info

Run

09/06/11 12:22 PM

Date:

Folder 09 061272

In Date:

04/24/09 Issued 04/24/09

ID#:

Date:

Status:

Finaled

Expiry Date: 10/21/09

Closed:

05/05/09

Type:

B - Building Permit - Single Family Dwelling - Express Repair

house new insert windows **Windows-Add Framed-Insert or "Pocket" Windows: For bedroom windows-egress must be maintained such that no additional frame or construction will be allowed that reduces the window operable opening more than 1 (one) inch on each side. Any deviation from this standard requires special, prior approval from this Office. Safety Glass is required within a tub or shower enclosure, within 2 feet of doors and adjacent to stairs and stair landings, when the glass is less than 60 inches above a walking or standing surface. See other specifics in Section R308 of the International Residential Code (1- and 2-family dwellings) or Chapter 24 of the International Building Code (multi-family and commercial). NOTE: Smoke alarms shall be installed as specified in the Minnesota State Residential Code, Sec. R313. Call the Area Building Inspector between 7:30-9:00am (M-F) when work is complete or if any problems/questions arise. NOTE: Per Section 33.04 of the Legislative Code all exterior work must be completed within one year of permit issuance.

Comment:

04/24/2009: 04/24/2009 Permit printed. **04/25/2009**: 04/24/2009 Placard printed.

05/04/2009: General Inspection - Partial Approval, no smoke or CO detectors installed

05/04/2009: Final Inspection - Approved.

Document:

Batch PDF: Insp Placard Document - Generated: 04/24/2009 - Sent: 04/24/2009 Batch PDF: Permit Document - Generated: 04/24/2009 - Sent: 04/24/2009

st Note: Clicking on above document links may not reflect the exact formatting of the original document.

People:

Owner:

Por Yang/Mailee Lee 1047 Jessamine Ave E St Paul MN 55106-2733

Contractor:

Gayle Mau

Merit Building Company Inc 2393 Coon Rapids Blvd NW - #204 Coon Rapids MN 55433-0000 763-323-7363 merit@meritbuildingco.com

Property:

1047 JESSAMINE AVE E, PIN: 282922210205

Info Value:

Owner's First/Last Name: por yang & mailee lee

Owner's Address: 1047 jessamine ave e Owner's City/State/Zip: st paul, mn

Owner's Phone # w/Area Code: 651-592-1845

Penalty Fee: No

of Existing Dwelling Units: 1 State Valuation: \$8,000.00 Valuation Override: No

Windows (Framed Insert or Pocket): Yes

of Windows: 20 Field Application?: No

Surcharge Report Valuation: \$8,000.00

Fee:

Building Permit Fee: \$186.34 - Paid in Full: Yes - Payment Type: VISA - Payment Date:

04/24/2009

Surcharge B: \$4.00 - Paid in Full: Yes - Payment Type: VISA - Payment Date: 04/24/2009 Parks Dedication Fee (DC 5): \$0.00 - Paid in Full: Yes - Payment Type: VISA - Payment

Date: 04/24/2009

Building Permit Inspection Assigned To: Thomas, Virgil **Inspection Date:** 05/04/09

Inspection 1:

Type: General Inspection Result: Partial Approval

Comment: no smoke or CO detectors installed

Closed: 05/01/09

Inspection Date: 05/04/09

Inspection 1:

Type: Final Inspection Result: Approved **Closed:** 05/05/09