

□ Other

# **APPLICATION FOR APPEAL**

## Saint Paul City Clerk

RECEIVED FEB 0 1 2012 310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

The City Clerk needs the following to process your appeal: CLERK		
\$25 filing fee payable to the City of Sa (if cash: receipt number)  Copy of the City-issued orders or letter are being appealed  Attachments you may wish to include	aint Paul er which	YOUR HEARING Date and Time:  Tuesday, 2-14-12
This appeal form completed		Time / 30 P M. Location of Hearing:
Walk-In OR   Mail-In		Location of Hearing: ` Room 330 City Hall/Courthouse
Address Being Appealed:		
Number & Street: 1398 Mechanic aveity: G. Daul State: MW Zip: 55/06		
Appellant/Applicant: Nancy O(SON Email dro(Son 96 dishmail.n		
Phone Numbers: Business 715273 4080 Residence 715273 60 Cell		
Signature: Mancy Jolaan		Date: 2-/-/2
Name of Owner (if other than Appellant): _	·	
Address (if not Appellant's):		
Phone Numbers: Business	Residence	Cell
What Is Being Appealed and Why? Attachments Are Acceptable		
Vacate Order/Condemnation/ Revocation of Fire C of O		
□ Summary/Vehicle Abatement		
□ Fire C of O Deficiency List		
Fire C of O: Only Egress Windows	Windows m	easure 20" High x 35" Wide
□ Code Enforcement Correction Notice		
□ Vacant Building Registration		



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

December 27, 2011

DARYL R OLSON NANCY L OLSON W8296 US HIGHWAY 10 W ELLSWORTH WI 54011-4867

#### FIRE INSPECTION CORRECTION NOTICE

RE:

1398 MECHANIC AVE

Ref. #113138

Residential Class: C

### Dear Property Representative:

Your building was inspected on December 27, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on January 27, 2012 at 10:45 A.M..

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

#### **DEFICIENCY LIST**

- 1. All Bedrooms MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.-Double hung windows. Openable height is 20inches. Openable width 36inches. Glazed 38 inches in height by 32inches in width. Sill 34inches.
- 2. Basement MSFC 605.1 Remove unapproved exposed wiring and install in accordance with the electrical code. This work may require a permit(s). Call DSI at (651) 266-9090.

  An Equal Opportunity Employer

- Basement SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.-Repair or replace the damaged or deteriorated ceiling. Paint the ceiling. Patch the holes and/or cracks in the ceiling.
- Dim Muh Plb. Basement SPLC 34.11 (4), 34.34 (1), MPC 4715.0900 MPC 4715.0220S Provide and maintain an approved waste trap.
- Basement SPLC 34.10 (1) Abate and maintain the basement reasonably free from dampness and free of mold and mildew.
  - 6. Bedroom North West Side - MSFC 605.4 - Discontinue use of all multi-plug adapters.
- 7. D. Door leading into garage SPLC 34.09 (3) i Provide and maintain an approved one-inch throw single cylinder deadbolt lock.
  - Rear Storm door SPLC 34.09 (3), 34.32 (3) Repair and maintain the window glass.

Boes Hestino

SPLC 34.11 (6), 34.34 (3) - Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.

SPLC 39.02(c) - Complete and sign the provided smoke detector affidavit and return it to this office.

- MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.
- SPLC 34.09 (3), 34.32 (3) Provide or repair and maintain the window screens.
  - 13. Territo 200.02 (a) No person shall own, harbor, keep or maintain in the City and dog over three months of age without a license. Provide written documentation of current license to the Fire Inspector. To obtain a dog license, contact DSI at 651-266-8989
- 14. JOMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work may require a permit(s). Call DSI at (651) 266-8989.-Cannot use duck tape on dryer duct

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: james.thomas@ci.stpaul.mn.us or call me at

651-266-8983 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

James Thomas Fire Inspector

Reference Number 113138