

□ Other

APPLICATION FOR APPEAL

RECEIVED

Saint Paul City Clerk

The City Clerk needs the following to process your appeal: \$25 filing fee payable to the City of Saint Paul (if cash: receipt number 95079) Copy of the City-issued orders or letter which are being appealed Attachments you may wish to include Telephone: (651) 266-8560 YOUR HEARING Date and Time: Tuesday, Feb. 7, 2012	JAN 25 2012	310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102	
The City Clerk needs the following to process your appeal: \$25 filing fee payable to the City of Saint Paul (if cash: receipt number 9000 M) Copy of the City: Sissued orders or letter which are being appealed Attachments you may wish to include This appeal form completed Walk-In OR Mail-In Address Being Appealed: Number & Street: 584 Lawsen Ave W City: 57 faw State: WW Zip. Appellant/Applicant: Tony Hoong Email hongtony gmach own Phone Numbers: Business Residence Signature: Date: 0725-12 Name of Owner (if other than Appellant): Zheng Lendul properties Address (if not Appellant's): 1570 Falcan or Fairment, MN 5631 Phone Numbers: Business Residence Cell 507 2095 What Is Being Appealed and Why? Attachments Are Acceptable Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement Fire C of O Deficiency List #2, 19 Fire C of O Conty Egress Windows Code Enforcement Correction Notice	CITY CLERK		
(if cash: receipt number 90507) Copy of the City-issued orders or letter which are being appealed Attachments you may wish to include This appeal form completed Walk-In OR Mail-In Address Being Appealed: Number & Street: 584 Lawsen Ave W City: 57 PAU State: WW Zip: SII7 Appellant/Applicant: Tony Hoong Email houghtny glacely coen Phone Numbers: Business Residence Signature: Date: 0725-12 Name of Owner (if other than Appellant): Zheng Rendul properties What Is Being Appealed and Why? Attachments Are Acceptable Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement Fire C of O Deficiency List #2.03 Fire C of O: Only Egress Windows Code Enforcement Correction Notice			
Number & Street: 584 Lawsen Ave W City: ST. PAUL State: WW Zip: 35117 Appellant/Applicant: Tony Hoong Email hongtony@gmail.com Phone Numbers: Business Residence 567 573 2095 Cell Signature: Date: 0/25-12 Name of Owner (if other than Appellant): Zheng Lenful proporties Address (if not Appellant's): 1570 Follow Nr. Fairment, MN 56031 Phone Numbers: Business Residence Cell 507 573 - 2095 What Is Being Appealed and Why? Attachments Are Acceptable Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement Fire C of O Deficiency List 12, 18 Ceiling hought, Variance for other items the property for Color of the Color of	\$25 filing fee payable to the City of Saint Paul (if cash: receipt number 1500) Copy of the City-issued orders or letter which are being appealed Attachments you may wish to include This appeal form completed Walk-In OR Mail-In	Tuesday, Feb. 7, 2012 Time 1.30 p.m. Location of Hearing: Room 330 City Hall/Courthouse	
Appellant/Applicant: Tony Hoong Email Mongtony @ gmail com Phone Numbers: Business Residence 50.7 573-2095 Cell Signature: Date: 01-25-12 Name of Owner (if other than Appellant): Zheng Lendul properties Address (if not Appellant's): 1570 Folian Mr. Fairmant, MN. 56031 Phone Numbers: Business Residence Cell 507-673 What Is Being Appealed and Why? Attachments Are Acceptable Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement Fire C of O Deficiency List 42, 18 Ceiling hought, -variance more for other items due for properties Fire C of O: Only Egress Windows Code Enforcement Correction Notice			
Phone Numbers: Business	Number & Street: 584 Lawson Ave W City: 5	T. PAUL State: WW Zip: SS117	
Name of Owner (if other than Appellant): Zheng Rendul properties Address (if not Appellant's): 1570 Federally sections, MN 56031 Phone Numbers: Business Residence Cell 507 73 What Is Being Appealed and Why? Attachments Are Acceptable Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement Fire C of O Deficiency List 12, 18 Ceiling height, -varience missions for other items ductor properties. Fire C of O: Only Egress Windows Code Enforcement Correction Notice			
Name of Owner (if other than Appellant): Zheng Rendul Proporties Address (if not Appellant's): 1570 Follow Mr. Facilment, MN 56031 Phone Numbers: Business Residence Cell 507 2095 What Is Being Appealed and Why? Attachments Are Acceptable Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement Fire C of O Deficiency List 42, 18 Ceiling height, -varion(c must for other items during pains) Fire C of O: Only Egress Windows Code Enforcement Correction Notice	Phone Numbers: Business Residence	773 28 (5 Cell	
Address (if not Appellant's): 1570 Follow Mr. Failment, MN 56031 Phone Numbers: Business Residence Cell 507 573 What Is Being Appealed and Why? Attachments Are Acceptable Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement Fire C of O Deficiency List \$\frac{1}{2}, \frac{1}{2}\$ Ceiling height, varience must for other items ductor for Code Enforcement Correction Notice			
Address (if not Appellant's): 1570 Follow Mr. Failment, MN 56031 Phone Numbers: Business Residence Cell 507 573 What Is Being Appealed and Why? Attachments Are Acceptable Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement Fire C of O Deficiency List \$\frac{1}{2}, \frac{1}{2}\$ Ceiling height, varience must for other items ductor for Code Enforcement Correction Notice	Name of Owner (if other than Appellant): Zheng Renful	properties	
Phone Numbers: Business Residence Cell 507 2095 What Is Being Appealed and Why? Attachments Are Acceptable Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement Fire C of O Deficiency List 42, 18 Ceiling height, -varience must for other items ductor production. Fire C of O: Only Egress Windows Code Enforcement Correction Notice			
Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement Fire C of O Deficiency List #2, 18 Ceiling height, -varience must for other items ductor for Other ite	Phone Numbers: Business Residence	Cell 507 573	
Revocation of Fire C of O Summary/Vehicle Abatement Fire C of O Deficiency List #2, 18 Ceiling height, -varience moretime for other items ducto peum Fire C of O: Only Egress Windows Code Enforcement Correction Notice	What Is Being Appealed and Why? Attachments Are Acceptable		
	Revocation of Fire C of O Summary/Vehicle Abatement Fire C of O Deficiency List 42, 18 Ceiling height, -vo	wience, movetime for other items ducto	
	. · · · · · · · · · · · · · · · · · · ·		

DEPARTMENT OF SAFETY AND INSPECTIONS Fire Inspection Division Ricardo X. Cervantes. Director



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

January 4, 2012

ZHENG RENTAL PROPERTIES LLC 1570 FALCON DRIVE FAIRMONT MN 56031-4551

FIRE INSPECTION CORRECTION NOTICE

RE: 584 LAWSON AVE W

Dear Property Representative:

Your building was inspected on January 4, 2012 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on February 10, 2012 at 11 am.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. Exterior Remove the accumulation of snow or ice from the public and private sidewalk abutting this property.
- Exterior SPLC 34.13 (1) Provide and maintain all habitable areas with a ceiling height of 7 feet over 1/2 the floor area. This home was remodeled without permits. The attic has been converted into bedrooms but due to low head space, is not approved.
- 3. Exterior-Garage and Shed SPLC 34.08 (5), 34.31 (3) Repair, replace and maintain all exterior surfaces on fences, sheds, garages and other accessory structures free from holes and deterioration. Provide and maintain exterior unprotected surfaces painted or protected from the elements.


Exterior-Garage/Shed - SPLC 34.09 (1) b.c, 34.32 (1) b.c - Provide and maintain all 4. exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner

free from chipped or peeling paint.-Secure the garage and shed, free from holes and paint.

Exterior-Throughout - SPLC 34.14 (2) f - Provide and maintain an minimum of 1 foot candle at the grade level of exterior exits and entryways for security. This work may require a permit(s). Call DSI at (651) 266-9090.-Maintain all fixtures with bulbs to provide adequate lighting.

> Interior-Basement - SPLC 34.11 (6), 34.34 (3) - Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.-Have a licensed contractor certify that the furnace and venting meet code, and complete an orsat test.

- Interior-Basement UMC 504.6 Provide, repair or replace the dryer exhaust duct. 7. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work may require a permit(s). Call DSI at (651) 266-8989.
- Interior-Basement MFGC Chapter 4 Provide or replace fuel equipment piping in 8. compliance with the mechanical code. This work require a permit(s). Call DSI at (651) 266-8989.-Repair the damaged ducts and piping in the basement that appears to be asbestos and is covered with duct tape and painted throughout the basement. Permit required.
- Interior-Basement SPLC 34.10 (2), 34.33 Repair and maintain the damaged structural 9. member. This repair requires a building permit, call DSI at (651) 266-9090.-The basement beams are cracked. Repair or replace under permit.
- Interior-Basement SPLC 34.10 (2), 34.33 Repair and maintain the damaged structural 10. member. This repair requires a building permit, call DSI at (651) 266-9090.
 - Interior-Throughout SPLC 34.19 Provide access to the inspector to all areas of the 11. building.
 - Interior-Throughout SPLC 34.14 (2), 34.34 (5) Provide an approved electrical service 12. adequate to meet the buildings needs. This work may require a permit(s), call DSI at (651) 266-9090.-Hire a licensed electrician to provide outlets to all appliances and certify that the panel and service meets code. It appears electrical work has been completed without permits. Permit required.
 - Interior-Throughout MSFC 605.5 Discontinue use of extension cords used in lieu of 13. permanent wiring.
 - Interior-Throughout MSFC 605.4 Discontinue use of all multi-plug adapters.-14. Discontinue use of adapters on the appliances. Hire a licensed electrician to provide adequate service to the building. Permit Required.



- 15. Interior-Throughout MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturer's instructions.-Immediately provide a co detector within 10 ft. of every sleeping area.
- 16. Interior-Throughout MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.-Replace the missing smoke detector on the main floor, and provide approved permit from a licensed electrician for the installation of hard wired smoke detectors. Have the permitted work inspected and approved.
- 17. Interior-Throughout MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651) 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-New egress windows installed without permit. Pull a permit, have inspected and approved. Immediately discontinue use of the attic area for sleeping rooms.
- 18. Interior-Throughout SPLC 34.13 (1) Provide and maintain all habitable areas with a ceiling height of 7 feet over 1/2 the floor area. The landing to the second floor measured 5ft 10 inches. As you approach the second floor on the stairs, the ceiling is slanted from 4ft 1 in to 5ft 8inch at the top of the stairs. The basement head space is 5ft 8 inches where all the heating ducts are located, and 6ft. 7 inches near the washer and dryer. This appears to be an attic space that was converted without approval or permits.

19.—SPLC 39.02(c) - Complete and sign-the provided smalle detector affidavit and return it to

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: lisa.martin@ci.stpaul.mn.us or call me at 651-266-8988 between 6:30 a.m. - 8:30 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Lisa Martin Fire Inspector