

APPLICATION FOR APPEAL

RECEIVED

FEB 0 7 2012

CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

Revised 3/7/2011

The City Clerk needs the following to pr	ocess your appeal:
\$25 filing fee payable to the City of (if cash: receipt number) Copy of the City-issued orders or le are being appealed Attachments you may wish to include This appeal form completed Walk-In OR Mail-In	YOUR HEARING Date and Time: Tuesday, Co. 21, 2012 Time 1:30 0 Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appeal	Emailed 2-7-12
Number & Street: 324 Van P	wen Aus City: Sto Paul State: UP Zip:57/03
Appellant/Applicant: Bosa Fu	Email BRUC Staracentoos soco
Signature: Name of Owner (if other than Appellant):	Residence Cell (05) 246 957(Date: 1/31/272
Phone Numbers: Business	Residence Cell
What Is Being Appeal Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement Fire C of O Deficiency List Fire C of O: Only Egress Windows Code Enforcement Correction Notice Vacant Building Registration Other	wingar in halrooms rewines (93") in height on any array in process of the former property. Bona Ku
	7018 128th Street Ct W

Apple Valley, MN 55124

TODAYS DATE

01/31/2012

TO WHOM THIS MAY CONCERN,

I OWN A 2 BEDROOM SINGLE FAMILY RESIDENTIAL PROPERTY LOCATED AT 324 VAN BUREN AVE SAINT PAUL MN 55103. I PURCHASED THIS PROPERTY OVER 4 YEARS AGO. THE BEDROOM WINDOWS REACHED A MAXIMUM HEIGHT OF 23" IN HEIGHT. THE WINDOWS WERE ALREADY IN PLACE BEFORE I PURCHASED THIS PROPERTY. THE RULE STATED IN THE DEFICIENCY LIST STATED WINDOWS NEEDED TO BE ATLEAST 24" IN HEIGHT. PLEASE MAKE THE CONSIDERATION FOR THIS SINGLE FAMILY PROPERTY.

THANK YOU VERY MUCH,

BONA KU



Ricardo X. Cervantes, Director



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

January 17, 2012

BONA KU 4618 STONECLIFFE DR EAGAN MN 55122-2798

FIRE INSPECTION CORRECTION NOTICE

RE: 324 VAN BUREN AVE

Residential Class: C

Dear Property Representative:

Your building was inspected on January 13, 2012 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on February 17, 2012 at 1:00 PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

2i w ar W C

2nd Floor - Bedrooms - MSFC1026.1 - Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.

-Both bedrooms have double hung replacement windows that measure 19.5 inches height by 22 inches width openable space and have a glazed area of 6.1 square feet.



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

January 17, 2012

BONA KU 4618 STONECLIFFE DR EAGAN MN 55122-2798

FIRE INSPECTION CORRECTION NOTICE

RE:

324 VAN BUREN AVE

Residential Class: C

Dear Property Representative:

Your building was inspected on January 13, 2012 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on February 17, 2012 at 1:00 PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. 2nd Floor Bedrooms MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.
 - -Both bedrooms have double hung replacement windows that measure 19.5 inches height by 22 inches width openable space and have a glazed area of 6.1 square feet.
- 2. 2nd Floor Bedrooms MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-9090.
 - -Repair non-grounded three prong outlets.
 - -Repair damaged outlet in North bedroom.

An Equal Opportunity Employer

- 3. 2nd Floor MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 4. Basement SPLC 34.11 (5), 34.34 (2) Contact a licensed contractor to properly install the water heater under permit. This work will require a permit(s). Call DSI at (651) 266-9090. The water heater has a manufactured date of 4/2011 and was improperly installed and without permit.
- 5. Basement SPLC 34.11 (4), 34.34 (1), MPC 4515, MPC 326 Connect or cap the sewer piping in accordance with the plumbing code. -Cap unused drains for washing machine.
- 6. Bathroom MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-9090. -Repair or replace improperly working GFI outlet.
- 7. Exterior West SPLC 34.08 (2) Provide and maintain the property grade to slope away from the building to minimize the accumulation of water near the building. This work may require a permit(s). Call DSI at (651) 266-9090.
- 8. Interior NEC 410-8 (b) (1) Provide for the incandescent fixtures in closets to have a completely enclosed lamp.
- 9. Kitchen SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 Repair or replace and maintain the plumbing fixture to an operational condition. -Repair leaking sink drain.
- 10. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit an approved completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 11. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: william.beumer@ci.stpaul.mn.us or call me at 651-266-8991 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

William Beumer Fire Inspector