

Date: February 08, 2012
File #: 12 - 020459
Folder Name: 555 SELBY AVE
PIN: 012823220114

HP District: HPL-Hill
Property Name: double residence
Survey Info: RA-SPC-3254



South and east sides



South side, postings



Front posting



Deteriorated window frame, open wall



Deteriorated masonry



Deteriorated masonry

Date: February 08, 2012
File #: 12 - 020459
Folder Name: 555 SELBY AVE
PIN: 012823220114

HP District: HPL-Hill
Property Name: double residence
Survey Info: RA-SPC-3254



Deteriorated foundation



Roof over the rear deck



Rear deck



North side