

Date: October 20, 2011  
File #: 11 - 290184  
Folder Name: 317 BAKER ST W  
PIN: 072822310010

HP District:  
Property Name:  
Survey Info:



North and east sides



Front (south side) posting



Shed



East side posting



South and east sides



South side

**Date:** October 20, 2011  
**File #:** 11 - 290184  
**Folder Name:** 317 BAKER ST W  
**PIN:** 072822310010

**HP District:**  
**Property Name:**  
**Survey Info:**



**South and west sides, posting**

Date: January 11, 2012  
File #: 11 - 290184  
Folder Name: 317 BAKER ST W  
PIN: 072822310010

HP District:  
Property Name:  
Survey Info:

The following photographs were taken on or about September 27, 2011, for a condemnation action.



Date: January 11, 2012  
File #: 11 - 290184  
Folder Name: 317 BAKER ST W  
PIN: 072822310010

HP District:  
Property Name:  
Survey Info:




Date: January 11, 2012  
File #: 11 - 290184  
Folder Name: 317 BAKER ST W  
PIN: 072822310010

HP District:  
Property Name:  
Survey Info:



**Date:** January 11, 2012  
**File #:** 11 - 290184  
**Folder Name:** 317 BAKER ST W  
**PIN:** 072822310010

**HP District:**  
**Property Name:**  
**Survey Info:**



Date: January 11, 2012  
File #: 11 - 290184  
Folder Name: 317 BAKER ST W  
PIN: 072822310010

HP District:  
Property Name:  
Survey Info:



**Date:** January 11, 2012  
**File #:** 11 - 290184  
**Folder Name:** 317 BAKER ST W  
**PIN:** 072822310010

**HP District:**  
**Property Name:**  
**Survey Info:**





**Date:** January 11, 2012  
**File #:** 11 - 290184  
**Folder Name:** 317 BAKER ST W  
**PIN:** 072822310010

**HP District:**  
**Property Name:**  
**Survey Info:**

The following pictures were taken on January 11, 2012



**Rot damaged, open eave**



**Deteriorated steps**



**Rot damaged window, rain leader drains onto window**



**South and east sides**



**Deteriorated roof covering**



**Rain leader drains over wall and at foundation**

**Date:** January 11, 2012  
**File #:** 11 - 290184  
**Folder Name:** 317 BAKER ST W  
**PIN:** 072822310010

**HP District:**  
**Property Name:**  
**Survey Info:**



**Rot damaged, open eave and wall**



**Rot damaged window, water staining on interior side of window**



**Rot damaged eave, missing siding**



**Improperly abandoned window, open wall, chipped/peeling paint**



**Date:** January 11, 2012  
**File #:** 11 - 290184  
**Folder Name:** 317 BAKER ST W  
**PIN:** 072822310010

**HP District:**  
**Property Name:**  
**Survey Info:**

**Rot and rodent damaged, open eave, deteriorated roof covering**