



CITY OF SAINT PAUL  
*Christopher B. Coleman, Mayor*

375 Jackson Street, Suite 220  
Saint Paul, Minnesota 55101-1806

Telephone: 651-266-8989  
Facsimile: 651-266-8951  
Web: [www.stpaul.gov/dsi](http://www.stpaul.gov/dsi)

March 20, 2012

DEL CO LIMITED PARTNERSHIP  
PO BOX 17122  
ST PAUL MN 55117-0075

### **Revocation of Fire Certificate of Occupancy**

RE: 1075 AVON ST N

Dear Property Representative:

Your building was determined to be a registered vacant building on March 20, 2012. Since certificates are for the occupancy of buildings, it has become necessary to revoke the Certificate of Occupancy.

Saint Paul Legislative Code provides that no building shall be occupied without a Certificate of Occupancy. In order to re-occupy the building, the following deficiencies (if applicable) must be corrected and a complete Certificate of Occupancy inspection will be required.

#### DEFICIENCY LIST

1. Exterior - SPLC 34.09 (3), 34.32 (3) - Repair and maintain the window glass.-Repair broken window-North side of home.
2. Exterior-Garage - SPLC 34.08 (5), 34.31 (3) - Repair, replace and maintain all exterior surfaces on fences, sheds, garages and other accessory structures free from holes and deterioration. Provide and maintain exterior unprotected surfaces painted or protected from the elements.-Secure the garage door.
3. Exterior-Throughout - SPLC 34.09 (3), 34.32 (3) - Provide or repair and maintain the window screens throughout.
4. Exterior-Throughout - SPLC 34.09 (3), 34.32 (3) - Repair and maintain the window frames.

5. Exterior-Throughout - SPLC 34.09 (1) b,c, 34.32 (1) b,c - Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.
6. Exterior-Throughout - SPLC 34.09 (3), 34.32 (3) - Repair and maintain the door in good condition.
7. Interior-Throughout - MSFC 1011.2 - Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.
8. Interior-Throughout - SPLC 34.19 - Provide access to the inspector to all areas of the building.
9. Interior-Throughout - SPLC 34.10 (5), 34.33 (4), 34.16 - Provide and maintain interior in a clean and sanitary condition.
10. SPLC 34.11 (6), 34.34 (3) - Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
11. SPLC 39.02(c) - Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: <http://www.stpaul.gov/cofo>

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: [lisa.martin@ci.stpaul.mn.us](mailto:lisa.martin@ci.stpaul.mn.us) or call me at 651-266-8988 between 6:30 - 8:30 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Lisa Martin  
Fire Inspector