

CITY OF SAINT PAUL

Christopher B. Coleman, Mayor

375 Jackson Street., Suite 220 Saint Paul, MN 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-1919 Web: www.stpaul.gov/dsi

361

May 17, 2012

Shua Khang/Vang Vang Khang US 1622 Young Ave c/o

Clearwater FL 33756

TCF National Bank Consumer Lending Dept 801 Marquette Avenue Minneapolis MN 55402 US Bank c/o Patrick Bradfield 800 Moreland Street Owensboro KY 42301

Family Housing Fund 801 Nicollet Mall #1825 Minneapolis MN 55402 Services & Securing 14156 Eleven Mile Road Warren MI 48089

Five Brother Mortgage

Usset Weingarden & Liebo 4500 Park Glen Road #300 Minneapolis MN 55416

HRA Pete McCall

1100 City Hall Annex City Attorney's Office

Saint Paul MN 55102 400 City Hall

Saint Paul MN 55102

Order to Abate Nuisance Building(s)

Dear Sir or Madam:

The Vacant/Nuisance Buildings Unit, Department of the Department of Safety and Inspections, Division of Code Enforcement, hereby declares the premises located at:

388 MINNEHAHA AVE W

With the following Historic Preservation information: NONE

and legally described as follows, to wit:

Johnstones Subdivision Ofblk E 1/2 Of Vac Alley Adj And Lots 1 And Lot 2 Blk 1

to comprise a nuisance condition in violation of the Saint Paul Legislative Code, Chapter 45.02, and subject to demolition under authority of Chapter 45.11.

On May 8, 2012 a Building Deficiency Inspection Report was compiled and the following conditions were observed.

This list of deficiencies is not necessarily all the deficiencies present at this time. This building(s) is subject to the restrictions of Saint Paul Ordinance Chapter 33.03 and shall not again be used for occupancy until such time as a Certificate of Compliance or a

Certificate of Occupancy has been issued. All repairs must be in accordance with appropriate codes. Changes or additions to the electrical system, mechanical system, or the plumbing system may necessitate updating or upgrading the systems involved.

This is a two-story, wood frame house with a two-stall detached garage.

The following Deficiency List is excerpted from the February 8, 2011, Fire Certificate of Occupancy Letter of Revocation, and Order to Vacate.

DEFICIENCY LIST

- 1. Exterior SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition.-Repair or replace storm doors.
- 2. Exterior SPLC 34.09 (1) b,c, 34.32 (1) b,c Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.-Repair all damaged siding and paint.
- 3. Exterior SPLC 34.09 (2), 34.32(2) Repair or replace the unsafe stairways, porch, decks or railings in an approved manner. This work may require a permit(s). Call DSI at (651) 266-9090.-Repair or replace the rear deck and steps under permit.
- 4. Exterior SPLC 34.08 (1), 34.31 (1) All exterior property areas shall be maintained free from any accumulation of refuse, garbage or feces.
- 5. Exterior MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.
- 6. Interior SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.-Repair bathroom and bedroom ceilings.
- 7. Interior SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls in an approved manner.-Repair bathroom walls and remove mold like substance and re-paint bathrooms throughout including the basement.
- 8. Interior SPLC 34.10 (3) 34.33(2) Provide an approved guardrail. Intermediate ballustrade must not be more than 4 inches apart. Intermediate rails must be provided if the height of the platform is more than 30 inches.
- 9. Interior SPLC 34.11 (6) Provide and maintain a minimum of 68 degrees F in all habitable rooms at all times.-Provide heat in the basement bedrooms. Permit required.
- 10. Interior SPLC 34.10 (3), 34.33(2) Repair or replace the damaged handrail in an approved manner.-Repair the handrail to the second floor.
- 11. Interior SPLC 34.14 (2), 34.34 (5) Provide an approved electrical service adequate to meet the buildings needs. This work may require a permit(s), call DSI at (651) 266-

- 9090.-Hire a licensed electrician to provide outlets to all freezers including the front porch and to certify the electric load meets code. Permit required.
- 12. Interior SPLC 34.14 (2) c Provide or replace the duplex convenience outlet with ground fault protection within 3 feet of the basin on an adjacent wall in all bathrooms. This work may require a permit(s). Call DSI at (651) 266-9090.-Hire a licensed electrician to repair the gfci outlets that have open ground wires. Permit required.
- 13. Interior SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 4715.0200.C Provide an approved number and type of plumbing fixtures.-Hire a licensed plumber to repair the broken toilet in the basement and check the shower that is filled with a mold like substance or remove under permit.
- 14. Interior SPLC 62.101 Use of this property does not conform to zoning ordinance. Discontinue unapproved use or call DSI Zoning at (651) 266-8989 to convert to legal use. Discontinue:-This property was converted to a single family home.
- 15. Interior SPLC 34.10 (7), 34.33 (6) Repair and maintain the cabinets in an approved manner.-Remove all kitchen cabinets, kitchen sink, and appliances from the second floor under permit.
- 16. Interior SPLC 34.13 (3), SPLC 34.17 (2) Reduce and maintain the number of occupants in the sleeping rooms to: 2 occupants.
- 17. Interior SPLC 34.13 (2), (3), SPLC 34.17 (2) Reduce and maintain the number of occupants in the unit.
- 18. Interior MSFC 1003.3.1.8 Remove unapproved locks from the unit doors. The door must be openable from the inside without the use of keys or special knowledge or effort.
- 19. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.

As owner, agent or responsible party, you are hereby notified that if these deficiencies and the resulting nuisance condition is not corrected by **June 16, 2012** the Department of Safety and Inspections, Division of Code Enforcement, will begin a substantial abatement process to demolish and remove the building(s). The costs of this action, including administrative costs and demolition costs will be assessed against the property taxes as a special assessment in accordance with law.

As first remedial action, a Code Compliance Inspection Report must be obtained from the Building Inspection and Design Section, 375 Jackson Street, Suite 220, (651) 266-8989. This inspection will identify specific defects, necessary repairs and legal requirements to correct this nuisance condition. You may also be required to post a five thousand dollar (\$5,000.00) performance bond with the Department of Safety and Inspections before any permits are issued, except for a demolition permit. Call the Department of Safety and Inspections for more information at 651-266-8989.

May 17, 2012 388 MINNEHAHA AVE W page 4

If this building is located in a historic district or site (noted on page 1, above, just below the property address) then you must contact Heritage Preservation (HPC) staff to discuss your proposal for the repairs required by this order and compliance with preservation guidelines. Copies of the guidelines and design review application and forms are available from the Department of Safety and Inspections web site (see letterhead) and from the HPC staff. No permits will be issued without HPC review and approval. HPC staff also can be reached by calling 651-266-9078.

As an owner or responsible party, you are required by law to provide full and complete disclosure of this "Order to Abate" to all interested parties, all present or subsequent renters and any subsequent owners. The property shall not be sold, transferred or conveyed in any manner until the Nuisance Conditions have been abated and the Certificate of Code Compliance or Certificate of Occupancy has been issued.

The Enforcement Officer is required by law to post a placard on this property which declares it to be a "nuisance condition", subject to demolition and removal by the City. This placard shall not be removed without the written authority of the Department of Safety and Inspections, Division of Code Enforcement. The department is further required to file a copy of this "Order to Abate" with the City Clerk's Office.

If corrective action is not taken within the time specified in this order, the Enforcement Officer will notify the City Council that abatement action is necessary. The City Clerk will then schedule dates for Public Hearings before the City Council at which time testimony will be heard from interested parties. After this hearing the City Council will adopt a resolution stating what action if any, it deems appropriate.

If the resolution calls for abatement action the Council may either order the City to take the abatement action or fix a time within which this nuisance must be abated in accordance with the provisions of Chapter 33 of the Saint Paul Legislative Code and provide that if corrective action is not taken within the specified time, the City shall abate this nuisance. The costs of this action, including administrative costs will be assessed against the property as a special assessment in accordance with law.

If you have any questions or request additional information please contact **Matt Dornfeld** between the hours of 8:00 and 9:30 a.m. at **651-266-1902**, or you may leave a voice mail message.

Sincerely,

Matt Dornfeld Vacant Buildings Enforcement Inspector

cc: Legistar Approval list and City Council