

Attn: Janie

# APPLICATION FOR APPEAL

MAY 23 2012 CITY CLERK

# Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

Manager Community of the Community of th	1elepnone: (651) 266-8560
The City Clerk needs the following to process your appeal:	
\$25 filing fee payable to the City of Saint Paul (if cash: receipt number) Copy of the City-issued orders or letter which are being appealed Attachments you may wish to include This appeal form completed  Walk-In OR Mail-In	YOUR HEARING Date and Time:  Tuesday, 6-12-12  Time 1:30 P.M,  Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appealed:	
Number & Street: 876 Wheelock Pkroy Exity: St. Paul State MN Zip. 55706	
Appellant/Applicant: Raymond Wyatt Email cheffie 23 @hotmail.com	
Phone Numbers: Business (763) 390-4888 ext-4  Cell	
Signature: Dyon Noght - Vay Hat	Date: 5/3/2012
Name of Owner (if other than Appellant):	
Address (if not Appellant's):	
Phone Numbers: Business Residence	Cell
What Is Being Appealed and Why? Attachments Are Acceptable	
Summary/Vehicle Abatement  Fire C of O Deficiency List  Fire C of O: Only Egress Windows  Code Enforcement Correction Notice  Vacant Building Registration  Other  Summary/Vehicle Abatement  Africa and and and and and and and and and an	to affect the window as there out of egress dimensions.  Steve walter and I represent
The owner through his proporty manager!  I can be reached at (763) 390-4188 ext. 4	
Thankyon . It with	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

April 25, 2012

MINNESOTA HOME RENTAL INC 3344 -- 76TH ST E INVER GROVE HEIGHTS MN 55076-3026

## FIRE INSPECTION CORRECTION NOTICE

RE:

876 WHEELOCK PKWY E

Ref. #116436

Residential Class: C

### Dear Property Representative:

Your building was inspected on April 25, 2012 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on May 25, 2012 at 11:30 AM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

#### **DEFICIENCY LIST**

- 1. Exterior SPLC 34.09 (1) b,c, 34.32 (1) b,c Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.-Repair siding near the upper floor on the West side of the building.
- 2. Exterior SPLC 34.09 (2) 34.32 (2) Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.-Provide handrails on front and rear stairs.

- 3. Exterior SPLC 34.09 (3), 34.32 (3) Provide or repair and maintain the window screens throughout the building.
- 4. Interior 1st Floor Bedroom MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651) 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.-First Floor Bedroom Side slider style, 18 inches high by 22 inches wide openable with 53 inches of sill height.
- 5. Interior Basement UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work may require a permit(s). Call DSI at (651) 266-8989.
- 6. Interior Kitchen MSFC 605.1 Repair or replace damaged electrical fixture over sink. This work may require a permit(s). Call DSI at (651) 266-9090.
- 7. Interior SPLC 34.09 (3), 34.32 (3) Repair and maintain the door latch.-Provide deadbolt on front entry door in an approved manner.
- 8. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
  - 9. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: benjamin.ellis@ci.stpaul.mn.us or call me at 651-266-8946 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Benjamin Ellis Fire Inspector

Reference Number 116436