

are being appealed

APPLICATION FOR APPEAL

JUN 0 4 2012

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

YOUR HEARING Date and Time:

CITY CLERK

The City Clerk needs the following to process your appeal:

\$25 filing fee payable to the City of Saint Paul

Copy of the City-issued orders or letter which

(if cash: receipt number 105361)

Attachments you may wish to includeThis appeal form completed	Time_ 1:30 Pm
Walk-In OR Mail-In	Location of Hearing:
	Room 330 City Hall/Courthouse
Address Being Appealed:	
Number & Street: 469 Emaryland City:	: St. Paul State: MN Zip: 55/03
Appellant/Applicant: Houa Loe	_ Email
Phone Numbers: Business 651-734-8908 Residence	Cell
Signature: Hora Lec	Date: 6/4/12
Name of Owner (if other than Appellant):	hel
Address (if not Appellant's): 469 Emany land	
Phone Numbers: Business 651-734-8908 Residence	
What Is Being Appealed and Why? Attachments Are Acceptable	
Vacate Order/Condemnation/	
Revocation of Fire C of O	
Summary/Vehicle Abatement	
□ Fire C of O Deficiency List	
Fire C of O: Only Egress Windows	
Code Enforcement Correction Notice	
□ Vacant Building Registration	
□ Other	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

May 30, 2012

HOUA LEE MEE LEE 3543 AUGER AVE WHITE BEAR LAKE MN 55110-5344

FIRE INSPECTION CORRECTION NOTICE

RE:

469 MARYLAND AVE E

Ref. #113690

Residential Class: C

Dear Property Representative:

Your building was inspected on May 30, 2012 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on July 30, 2012 at 1:00 PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. <u>Exterior SPLC 34.09 (3), 34.32 (3)</u> Provide or repair and maintain the window screens throughout the building.
- 2. <u>Interior Porch SPLC 34.10 (7), 34.33 (6)</u> Repair and maintain the walls in an approved manner.-Patch the holes and/or cracks in the walls and paint as necessary.
- 3. <u>Interior Porch SPLC 34.10 (7), 34.33 (6)</u> Repair or replace and maintain the Unit 1 threshold in an approved manner.

- 4. <u>Interior Unit 1 SPLC 34.09 (3), 34.32 (3)</u> Repair and maintain the window lock in West bedroom.
- 5. <u>Interior Unit 1 MSFC1026.1</u> Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651) 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.-South bedroom emergency egress window does not discharge directly into public way and no alternate window available.
- 6. <u>Interior Unit 2 MSFC 605.1</u>- All light fixtures shall be maintained with protective globes if originally equipped.-Top of stairway.
- 7. <u>Interior SPLC 34.10 (3), 34.33(2)</u> Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.-Provide handrail in basement stairway and stairway leading to Unit 2.
- 8. <u>Interior MN State Statute 299F.50</u> Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 9. <u>SPLC 34.11 (6), 34.34 (3)</u> Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 10. <u>SPLC 39.02(c)</u> Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: benjamin.ellis@ci.stpaul.mn.us or call me at 651-266-8946 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Benjamin Ellis Fire Inspector

Reference Number 113690