Date: June 23, 2011 11 - 243267 File #:

Folder Name:

PIN:

HP District: Property Name: 1132 CENTRAL AVE W **Survey Info:** 342923410028



North and west sides, posting



North and east sides, postings




CO UHH posting on front of house



VB/KO plac's posted on front of house



Posting on east side door



Cats in house

Date: June 23, 2011 File #: 11 - 243267

Folder Name: 1132 CENTRAL AVE W

PIN: 342923410028



Wood frame shed



South and east sides



Metal shed



North side, postings

Date: **April 11, 2012** 11 - 243267 File #:

Folder Name: 1132 CENTRAL AVE W

342923410028 PIN:



Roof damage from tree



Gentleman who was renting 1 of the 3 bedrooms

04/11/2012

HP District:

Property Name: Survey Info:



Common kitchen area



Common dining area



Water damaged ceiling and wall



Water damaged ceiling

Folder Name: 1132 CENTRAL AVE W

PIN: 342923410028



Water damaged ceiling



Common storage



Common use refrigerator/freezer



Common use refrigerator/freezer



Common use refrigerator/freezer



Rented bedroom

Folder Name: 1132 CENTRAL AVE W

PIN: 342923410028



Rented bedroom



Rented bedroom



Contents of rented bedroom



Rented bedroom



Rented bedroom



Common bathroom

Date: **April 11, 2012** 11 - 243267 File #:

Folder Name: 1132 CENTRAL AVE W

PIN:





HP District:

Property Name: Survey Info:

Common bathroom

04/11/2012



Fire damaged electrical outlet in common bathroom



Damaged door frame



Unapproved hand rail



Unapproved hand rail



Common area food storage

Folder Name: 1132 CENTRAL AVE W

PIN: 342923410028



Refuse and debris



Open kitchen ceiling



Water heater missing overflow tube



Standing water on the basement floor



Upper pipe joint leaking, mold on wall



Damaged, open dry vent

Folder Name: 1132 CENTRAL AVE W

PIN: 342923410028



North and west sides



South and east sides