

The City Clerk needs the following to process your appeal:

# **APPLICATION FOR APPEAL**

RECEIVED NOV 0 8 2012

## Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

CITY CLERK

Z D Z	\$25 filing fee payable to the City of Sai (if cash: receipt number) Copy of the City-issued orders or letter are being appealed Attachments you may wish to include This appeal form completed Walk-In OR D Mail-In		YOUR HEARING Date and Time:  Tuesday, November 13  Time
Address Being Appealed:			
Number & Street: 1947 Roblyn City: 5t, PAUL State: MV Zip: 55104			
Appellant/Applicant: Ronald S. Smith Email flyer 431K@Gmail.co			
Pho Sign	nature: Republic Smith	Residence	Cell 612 386 6964  Date: 11-8-2012
Name of Owner (if other than Appellant):			
Address (if not Appellant's):			
Pho	one Numbers: Business	Residence	Cell
What Is Being Appealed and Why? Attachments Are Acceptable			
$\mathbb{X}_{I}$	Vacate Order/Condemnation/ Revocation of Fire C of O	4.1-08	une a sopera
	Summary/Vehicle Abatement	Donandia 1	Sandon.
	Fire C of O Deficiency List	primiting.	JW KW C
_ F	Fire C of O: Only Egress Windows		
	Code Enforcement Correction Notice		
□ <b>\</b>	Vacant Building Registration		
<b>(</b>	Other		



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

October 1, 2012 Ronald S Smith 5935 2nd Ave S Minneapolis MN 55419-2503

## Revocation of Fire Certificate of Occupancy and Order to Vacate

RE:

1947 ROBLYN AVE

Ref. # 12006

### Dear Property Representative:

Your building was inspected on October 1, 2012, for the renewal of the Certificate of Occupancy. Since you have failed to comply with the applicable requirements, it has become necessary to revoke the Certificate of Occupancy in accordance with Section 40.06 of the Saint Paul Legislative Code. A reinspection will be made on October 31, 2012 at 1030am or the property vacated.

The Saint Paul Legislative Code further provides that no building shall be occupied without a Certificate of Occupancy. Failure to immediately complete the following deficiency list or the building vacated may result in a criminal citation.

#### **DEFICIENCY LIST**

- 1. 1947 Upper floor SPLC 34.23, MSFC 110.1 This occupancy is condemned as unfit for human habitation. This occupancy must not be used until re-inspected and approved by this office.-Room off the kitchen is not to be use as a bedroom.
- 2. 1947 lower Bathroom SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls in an approved manner.
- 3. 1947 lower Bathroom SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.
- 4. 1947 lower Throughout SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls in an approved manner.
- 5. 1947 lower Throughout SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.

- 6. 1947 lower MSFC 906.1, MN Stat. 299F.361 Provide approved fire extinguishers in accordance with the following types, sizes and locations.-Provide one minimum 1A10BC fire extinguisher within each apartment unit or a minimum 2A10BC not be more than 50' travel distance from each apartment entrance. They must be permanently mounted between 3 and 5 feet high in readily visible and easily accessible locations
- 7. 1947 lower MSFC 703 Provide, repair or replace the fire rated door and assembly. The minimum rating must be:
- 8. 1947 upper Bathroom SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls in an approved manner.
- 9. 1947 upper Bathroom SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.
- 10. 1947 upper Unit SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls in an approved manner.
- 11. 1947 upper Unit SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.
- 12. 1947 upper stairway SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls in an approved manner.
- 13. 350 Prior SPLC 34.09 (2), 34.32(2) Repair or replace the unsafe stairways, porch, decks or railings in an approved manner. This work may require a permit(s). Call DSI at (651) 266-9090.-Exterior stairs to unit 350 must be replaced attempted repairs did not work. The unsafe stair way must be repaired by a licensed mason or replaced this work must be done under permit and approved.
- 14. 350 Prior SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls in an approved manner.
- 15. 350 Prior SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.
- 16. 350 Prior SPLC 34.10 (7), 34.33 (6) Repair and maintain the floor in an approved manner.-Kitchen floor. Repair the kitchen floor and threshold to the exterior in an approved manner.
- 17. 350 Prior SPLC 34.10 (7), 34.33 (6) Repair or replace and maintain the closet doors in an approved manner.
- 18. Basement Stairs MSFC 703 Provide and maintain fire rated floor and/or ceiling construction with approved materials and methods. This work may require a permit(s). Call DSI at (651) 266-9090. The minimum rating must be:
- 19. Basement MSFC 703 Provide, repair or replace the fire rated door and assembly. The minimum rating must be:-Repair and maintain the door closer.

- 20. Basement MSFC 315.2.3 Remove combustible storage from the fuel burning equipment rooms.
- 21. Carriage House bathroom SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.
- 22. Carriage House bathroom SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls in an approved manner.
- 23. Carriage House MSFC 605.4 Discontinue use of all multi-plug adapters.
- 24. Carriage House MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Repair or replace the damaged egress window in both bedrooms. windows were found boarded and with broken hardware and did not work at time of inspection. replacement will require a permit and approval.
- 25. Exterior SPLC 34.08 (5), 34.31 (3) Repair, replace and maintain all exterior surfaces on fences, sheds, garages and other accessory structures free from holes and deterioration. Provide and maintain exterior unprotected surfaces painted or protected from the elements.
- 26. Exterior SPLC 34.09 (1) b,c, 34.32 (1) b,c Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.
- 27. Exterior SPLC 34.09 (2), 34.32(2) Repair or replace the unsafe stairways, porch, decks or railings in an approved manner. This work will require a permit(s). Call DSI at (651) 266-9090.-After repair is complete scrap and repaint all unprotected surfaces.
- 28. Exterior SPLC 34.09 (3), 34.32 (3) Repair and maintain the window glass.
- 29. Exterior SPLC 34.09 (3), 34.32 (3) Repair and maintain the window frame.
- 30. Exterior SPLC 34.09 (3), 34.32 (3) Provide or repair and maintain the window screen.
- 31. Exterior SPLC 34.09 (1) a, 34.32 (1) a Provide and maintain foundation elements to adequately support this building at all points.-Contact a licensed mason to repair and tuck point the buildings foundation all work must be done under permit and approved.
- 32. Exterior MN Rules 1300.0180 Immediately discontinue use of unsafe heating appliance until repaired or replaced by a licensed contractor. This work may require a permit(s). Call DSI at (651) 266-9090. Red tags may not be removed except by fire

department inspector.-Masonry chimneys with open mortar joints which missing bricks or cracked as to be dangerous, shall be repaired in an approved manner under permit and approved in accordance with the requirements of the International Building Code.

- 33. Throughout and Carriage House SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 34. SPLC 34.09 (1) e, 34.32 (1) d Provide and maintained the roof weather tight and free from defects.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: mike.urmann@ci.stpaul.mn.us or call me at 651-266-8990 between 7:30 - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Michael Urmann Fire Inspector

Ref. # 12006