Photos Taken 1/16/13

Exhibit 8

549 Nevada Ave E

Upstairs door with 2x4 screwed in

SE Bedroom Ceiling

upstairs door

South Bedroom Ceiling





Ceiling in NE Bedroom and light fixture

SE BEDROOM CEILING



Dining Room Ceiling

Living Room Window

Living Room Windows



Upstairs Bedroom Windows

Upstairs window

~~Extra~~
Dining Room
Ceiling

Bedroom Ceiling

Bedroom Ceiling

Kitchen Ceilings after trespasser Removed and stole kitchen cabinets

2 - Living Room Windows

SE
Bedroom
Ceiling

Living Room Ceiling Corrected

East living Room window –
Glass Broken by trespasser
when he Removed and stole window airconditioner

Outside window sash/ vinyl clad
and frame

Outside Window Sash - Vinyl CLAD
and frame

Outside window sashes – vinyl clad
and frames

sliding glass door frame

outside window sash/vinyl-clad and frame

Top of sliding glass door frame