

We need the following to process your appeal:

APPLICATION FOR APPEAL

Saint Paul City Council - Legislative Hearings

RECEIVED JAN 15 2014

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

Revised 5/31/2013

CITY CLERK

\$25 filing fee payable to the City of (if cash: receipt number \(\sqrt{652} \) Copy of the City-issued orders/lette \(\text{Attachments you may wish to include the completed } \)	r being appealed	HEARING DATE & TIME (provided by Legislative Hearing Office) Tuesday, January 21, 2014 Time
Walk-In OR Mail-In for abatement orders only: Email	1 OR □ Fax	Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appealed:		
Number & Street: 96 Manitoba City: 5t. Paul State: Zip:		
Appellant/Applicant: Robert	Rani Em	ail rrange favi com
Phone Numbers: Business Residence Cell _651-208-6828		
		Date: 1/15/14
Name of Owner (if other than Appellant):	Same	
Mailing Address if Not Appellant's:		
Phone Numbers: Business	Residence	Cell 65/-208-6828
What Is Being Appealed and Why? Attachments Are Acceptable		
Vacate Order/Condemnation/	1 am regu	esting partial occupancy
□ Summary/Vehicle Abatement	For Unit 2	0
□ Fire C of O Deficiency List	New Farnage was put in.	
Code Enforcement Correction Notice Clutter all removed		
□ Vacant Building Registration	Water service restored.	
□ Other	Smoke (Carbon Monoxide installed	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

January 8, 2014 ROBERT G RANI ANTOINE G IRANI 172 RED OAKS DR VADNAIS HEIGHTS MN 55127-6128

NOTICE OF CONDEMNATION UNFIT FOR HUMAN HABITATION ORDER TO VACATE

RE:

96 MANITOBA AVE

Ref. # 119762

Dear Property Representative:

Your building was inspected on January 7, 2014.

The building was found to be unsafe, unfit for human habitation, a public nuisance, a hazard to the public welfare or otherwise dangerous to human life. A Condemnation Placard has been posted on the building.

The following deficiency list must be completed or the building vacated by the re-inspection date.

CONDEMNATION OF THE BUILDING REVOKES THE CERTIFICATE OF OCCUPANCY.

Failure to complete the corrections may result in a criminal citation. The Saint Paul Legislative Code requires that no building be occupied without a Fire Certificate of Occupancy.

DEFICIENCY LIST

- 1. Unit 1 SPLC 34.23, MSFC 110.1 This occupancy is condemned as unfit for human habitation. This occupancy must not be used until re-inspected and approved by this office.
 - -Lack of basic facilities. (Water/Heat)

- Unit 1 SPLC 34.10 (7), 34.34 (6) Repair and maintain the walls in an approved 2. manner.
- Unit 1 SPLC 34.10 (7), 34.34 (6) Repair and maintain the ceiling in an approved 3. manner.
- Unit 1 SPLC 34.11 (6) Provide and maintain a minimum of 68 degrees F in all 4. habitable rooms at all times.
- Unit 2 SPLC 34.10 (7), 34.34 (6) Repair and maintain the walls in an approved 5. manner. -Throughout
- Unit 2 SPLC 34.10 (7), 34.34 (6) Repair and maintain the ceiling in an approved 6. manner.
- 7. Basement - MN Stat 299F.18 - Immediately remove and discontinue excessive accumulation of combustible materials. -Reduce clutter by 75 %.
- Basement SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 4715.0200.C Provide an 8. approved number and type of plumbing fixtures. -Numerous broken water lines due to the frozen pipes.
- 9. Basement - SPLC 34.11(4), 34.34(1) SPC 4715.0200A - Provide an adequate water supply to all water closets, sinks, showers and tubs. -Water was shut off to the property due to the pipes freezing.
- Basement MSFC 1003.3.1.8 Remove unapproved locks from the unit doors. The door 10. must be openable from the inside without the use of keys or special knowledge or effort. -Remove chain lock from the basement door.
- Furnace MN Rules 1300.0180 Immediately discontinue use of unsafe heating 11. appliance until repaired or replaced by a licensed contractor. This work may require a permit(s). Call DSI at (651) 266-9090. Red tags may not be removed except by fire department inspector.
 - -Furnace was condemned by Standard Heating
- Unit 1 Side Storm door MSFC 1028.3 Remove the materials that cause an exit 12. obstruction. Maintain a clear and unobstructed exitway. -Screen door blocked by ice.
- Unit 1 SPLC 34.09 (3), 34.32 (3) Repair and maintain the window frame. 13. -Window in the bedroom is stuck in the open position.
- Unit 1 SPLC 34.23, MSFC 110.1 This occupancy is condemned as unsafe or 14. dangerous. This occupancy must not be used until re-inspected and approved by this office.

- -Using open flame propane heater for the interior of the property.
- Unit 1 MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.
 There was not a working smoke detector in the unit.
- 16. Unit 1 MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 17. Unit 2 MSFC 1028.3 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.
 -Remove shoes and all materials to allow full function of the entry way door at the top of the stairs.
- Unit 2 MN Stat 299F.18 Immediately remove and discontinue excessive accumulation of combustible materials.
 -Reduce clutter by 25%
- 19. Unit 2 MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.
 -Smoke detectors were chirping.
- 20. Unit 2 MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- Unit 2 SPLC 34.23, MSFC 110.1 This occupancy is condemned as unfit for human habitation. This occupancy must not be used until re-inspected and approved by this office.
 Lack of basic facilities. (Water and Heat)
- 22. SPLC 34.09 (3), 34.32 (3) Repair and maintain the window glass.
 -Numerous broken window panes throughout.
- 23. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 24. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse,

 $15~\mathrm{W}$ Kellogg Blvd, Saint Paul MN $55102~\mathrm{Phone}$: (651-266-8585) and must be filed within $10~\mathrm{days}$ of the date of the original orders.

If you have any questions, email me at: brian.tonnancour@ci.stpaul.mn.us or call me at 651-266-8955 between 7:30 - 9:00 a.m. Please help make Saint Paul a safer place in which to live and work.

Sincerely,

Brian Tonnancour Fire Inspector Ref. # 119762

cc:

Housing Resource Center

Force Unit