Saint Paul Public Hearing Documentation For Time Allowance Of Property 444 Beacon Ave.

Amaya, Jose A
J & A ENTERPRISES
3/24/2014

Work Plan and Time Projection

Timetable of Project Progress and Projection

02/19/2014

- Purchased Property from Federal Home Mortgage Loan.
- Set \$5,000 Bond for release of permits.

3/25/2014

 Attend Public Hearing in regards to the city allowance of the rehabilitation of the subject property.

4/16/2014

Projected date by which the city will render its verdict regarding the subject property.

4/17/2014-6/17/14

Triwest Renovations, Haro Electric Solutions, and Prairie Plumbing Co. have given the most fiscally reasonable bids for work required of the code compliance report. Their individual bids can be found attached to this document.

All of the servicing companies are in accordance that city permits will be pulled and work on the property will commence as soon as permission has been granted by city. All companies have stated that the amount of work required to bring the subject property up to the compliance of the city will take no more than 2 months to complete; barring unforeseen delays. As the property will not be lived in until the work is complete, all work will be done every day of the week as allowed by the schedule of the craftsman.

We beseech the city for no more than the customary six month time allowance in order to bring the subject property up to code.

Bids

TRIWEST RENOVATIONS, INC.

1687 131st LN NW Coon Rapids, MN 55448 Phone:612-246-1241 Fax:

Estimate

Customer		Misc		
Name	Jose Amaya	Date		3/13/2014
Address	444 Beacon Ave	Order No.		AMA444
City	St Paul State MN ZIP 55448	Rep		Marion
Phone	612-246-1241	Job Descri	ption	Remodel
				····
Work area	Description	. Pr	ice	TOTAL
Interior	replace any damaged/rotten wood found in/out of building, protect with appropriate product.			
	Fill pit, tuck point any/all broken/missing concrete throughout basement and exposed exterior walls			
	Will replace correct any doors, windows and apply screens propertly where requiered.			
	Patch, prime and paint walls, celings, trim, doors, eves, fascia as per code.	· ·		
	Framing will be inspected and corrected to meet current code. Provide basement repairs for all code compliances, fire walls, insulation, air-seal of attick area as well.			
	install all safety equipment as per code, Smoke/fire detectors, handrails, address numbers and all			
	as specified by code compliance report.			
	Garage will be gutted and repaired with all new wood, siding, soffit, fascia, shingles to code.			
	Install new carpet and flooring throughout, new appliances.	s	16,000.00	\$ 16,000.00
	Electrical, Plumbing, Heating mechanicals will be worked and brought up to code as per			
	City of St Paul's Code Compliance Report dated Nov. 19, 2013	\$	11,500.00	\$ 11,500.00
	Proper Disposal and clean out of all construction debry according to code.		.,,	\$ 1,200,00
	Vacant Building fees must be paid prior to commencement of work.			
	City Permites	\$	850.00	\$ 850.00
	Appliances(range, fridge, dishwasher, OH micro) and electrical fixtures allowance as agreed.	\$	3,325.00	\$ 3,325,00
	All materials will be provided from local vendors(Homedepot & Menards) if higher quality product is			
	desired and upgrade will be signed for the difference prior to change of plans and change order doc.			
		ļ		
	·			
	and the state of t			
	All amounts balances are due and payable not later than 30 days after completion of final			
	clean-up. A finance charge of 18% per month will be charge after 30 days.			
	Triwest Renovations, Inc. to Supply all Necessary materials, labor, equipment, and supervision to	i		
	complete the work in remodeling plan as provided above and its references.	1 .		
	complete the work in removeling plan as provided above and its relevances.	-		
	This bid is good for 60 days only			
		1		
		1.		
				<u>ki ilogoji, side A. a. ¹</u>
		İ		
				<u>remisku ju najr</u>
•	Paradia Provide		Subtotal	\$ 32,875.00
	s Promotion Discounts		0%	\$
Danis and	Select One Tax Rate(s)			
Payment	Select One Tax Rate(s)	 		Process deduction of the con-
Comments			TOTAL	\$ 32,875.00
Name				52,010.00
CC#	Cust Signature.			1
Expires	Date.			
	Sales Rep.			

The undersigned authorizes and agrees to have Triwest Renovations, Inc. to perform the work according to the above specifications and price and also according to the terms and conditions that the above work to be performed in a professional manner this is legal binding contract. Any deviation or alteration from above specifications or plans given, involving extra costs, will be executed only upon written orders and will become an extra charge over and above the estimate.

FROM : PRAIRIE PLUMBING	FAX NO. : 285 8027	Mar. 14 2014 11:48AM P1
	Proposal	Page No
Prairie Plumbing (BOB STOLP 3134 Colorado Ave. So St. Louis Park MN. 55 PHONE: 952-544-8934 OR 952- FAX: 952-245-935-935-935-935-935-935-935-935-935-93	REPAIRS REMODELING
PROPOSAL SUBMITTED		6-0814 3-14-19
hame Hector a	Fred JOB HAME: COC	1- Compliance
STREET:		BEACON STATE: MALL
слу.	ARCHITECT:	DAGI MING
STATE:	ites for: 1 p.v.) water	
Raise Meter Laurdry Tub & Fixtures & FA Outside Spige Permit + Ins	ucets As Nies	Herster ??) ded.
		in accordance with the above specifications, for the sum of:
M = = = = = = = = = = = = = = = = = = =	All work to be completed in a warkmanlike monner of extre dests, will be executed only upon written orders, a strikes, assidents or delays beyond our control. Owners Compensation Insurance. Authorized Signature NOTE: This proposal may be withdressed to the control of the co	er to carry fire, tarnada and other necessary insur
	Acceptance of Proposal	
The above prices, specifications and work as specified. Payment will be	d conditions are satisfactory and are hereby	accepted. You are authorized to do the
Accented:	\$ignature	

Signature ._



Haro Electric Solutions, Inc 2004 Olson Memorial Highway Minneapolis, MN 55411

(612)245-4516 haro.electric.solutions@gmail.com http://www.haroelectric.com/

Estimate

Date	Estimate No.
02/11/2014	2815
	Exp. Date

Address	
MARLON AMAYA 444 Beacon Ave St Paul, MN 55104	

Ship To MARLON AMAYA 444 Beacon Ave St Paul, MN 55104 B 1068

Item	Description	Quantity	Rate	Amount
Wiring	• PERMIT FOR COMPLETE ELECTRICAL PER LIST GIVEN 6 CIRCUITS	1	3,600.00	3,600.00
	FURNISH PARTS AND LABOR TO COMP[LETE THE ELECTRICAL LIST PROVIDED BY THE ST PAUL INSPECTOR PROVIDE PARTS EXEPT NEW FIXTURES FANS AND		·	
	BULBS THIS MUST BE PROVIDED BY OTHERS.			
	INCLUDES ARCK FAULT PROTECTION PER CODE CHANGE AS OF 1/1/14			
	ASUMES NOT TO HAVE ANY MORE WALLS OPENED OR DRY WALL REMOVED			
	THE NEW SERVIOCE TO GARAGE WILL BE OVERHEAD (THE PRICE DOES NOT CHANGE IF THE SERVICE IS UNDERGROUND, BUT THE 24 INCH DEEP TRENCH MUST BE DONE BY OTHERS)			
				-
				·
Additional charges for	r alteration or additions. A service fee of \$25 will be imposed on all invoice		Total	\$3,600.00

Additional charges for alteration or additions. A service fee of \$25 will be imposed on all invoice not paid within Terms. The hiring party also agrees to pay all costs of collections, including lien and legal fees. "Any person or company supplying labor or materials for this improvement to your property may file for a lien against your property if that person or company is not paid for the contributions. MN statues 514.011."

Accepted By

Accepted Date

Financing of Project

Transaction History

Search Criteria	<u> </u>				
Customer Name	J & A ENTERPRISES LLC				
	568 WESTERN AVE N				
	SAINT PAUL MN 55103-192	8			
Product Name	Business Basic Checking (06	53)			
Bank	Minnesota 733	Account Number	Court vil 3		
Range Amount	Low	High	DB/CR	All	
Check Number	Start #	End #	Statement Date	02/28/2014 - 00/00/0000	
Range Date	Start Date 03/17/2014	End Date 03/24/2014	Sort	Date	
			Sort Order	Ascending	

Search Res	earch Results							
Post Date	Effective Date	Check Number TC	Description	Amount Debit/Credit	Balance	Reference Number		
03/17/2014	03/17/2014	061	DDA PUR HOLIDAY ST ST. PAUL MN 407200772413	\$ 54.88 Debit	\$ 14,542.60	5		
03/21/2014	03/21/2014	010	CUSTOMER DEPOSIT	\$ 1,000.00 Credit	\$ 15,542.60	, 6		
03/24/2014	03/24/2014	MD	HOLIDAY ST ST. PAUL MN	\$ 50.40 Debit	\$ 15,492.20	7		
						e e		



MAR 2 - 2014

Branch 082

Remember to click Sign out to end your session

Home

Add to Favorites

Print This Advice View a Different Paychec

\$1,172.25

03/14/2014

03/01/2014 03/15/2014

Sign out

Favorites

Main Menu

Self Service

Payroll and Compensation

View Paycheck

Usbank

Jose Amaya

US Bank National Assoc

4000 W Broadway

Robbinsdale, MN 55422

Employee Service Center: 1-800-806-7009

Pay Group:

Exception Hourly

Net Pay:

Pay Period:

Check Date:

Vacatic

Employee ID: Address:


568 Western Avenue Saint Paul, MN 55103 Department:


* 3000008013 - RMBS RISK MANAGEM

Location Code:

EP-MN-WS1I

							1 CAA-MIIAI-43		
		-			Job	Title:	aralegal 2		
Paycheck Sum	ımary								
	Tot	al Gross	Fed Taxable	Gross	7	Total Taxes	Total De	ductions	Net Pay
Current	1	1,626.73	1,5	91.79		415.71		38.77	1,172.25
YTD	8	3,274.42	8,0	99.72		2,131.39		193.85	5,949.18
Earnings				Parison and 17 17 17 17 17 17 17 17 17 17 17 17 17		Taxes	A	and the transport of the control of	
Description	Hours	Rate	Amount	А	YTD mount	Description	elika en	Amount	YTD Amount
Regular	78.67 18	3.769231	1,476.58	7,3	382.89	Fed Withho	oldng S-0	205.80	1,061.18
2/22 Holiday Py	8.00 18	3.769231	150.15	4	450.45	Fed MED/E		23.09	117.45
Sick Pay				4	450.46	Fed OASD		98.69	502.18
Lost Time					-9.38	MN Withho	ldng S-0	88.13	450.58
						Total:		415.71	2,131.39
Total:	86.67		1,626.73	8,2	274.42	£		•	
Before-Tax De	ductions		After Tax	After Tax Deductions			Employer-Paid Benefit Subsidy		
Description	Amount	YT Amou		n An	nount	YTD Amount	Description	n Amount	YTD Amount
Health	28.82	144.1	O LTD		2.70	13.50	Health	124.76	623.80
Dental	6.25	31.2	25				Dental	5.50	27.50
AD&D	1.00	5.0	ю				EE Life	0.72	3.60
			*******				LTD*	1.13	5.65
			Annual Communication of the Co			į	* Taxable	•	
Total:	36.07	180.3	5 Total:		2.70	13.50	Total:	132.11	660.55
Net Pay Distrib	oution	¥ .							
Payment Type		Paycheck	Numbe <u>r</u>	Account 1		Acco	ilut Mrimpell	*	Amount
Direct Deposit				Checking					1,172.25





Big Card Credit Application

Date:

03/24/2014

Name:

JOSE A AMAYA

Reference#:

140324201019

Credit Limit:

\$3500

Congratulations! You have been provided a conditional offer for a Big Card.

You must accept the offer within thirty (30) days of today otherwise Capital One will consider your application for the Big Card to be withdrawn and you will need to reapply.

To accept the conditional offer please proceed to the checkout line when you are ready to make a purchase. Your acceptance of the conditional offer will be fulfilled when you present a valid photo identification to the cashier for ID verification and self-enter your Social Security Number.

Periodically, we offer special financing plans to our valued guests. Please find below a description of the plans periodically available. After the expiration of the period described below, a variable APR of 24.99% will apply to your reomotional purchases. Thank you for shopping Menards; we appreciate your business.

CREDIT PLAN DESCRIPTION 6 Months "Same as Cash"/Monthly Payments SUMMARY OF CREDIT PLAN TERMS

No interest charges on the promotional item(s) if paid in full in 6 months. If the balance attributable to the promotional item (s) is not paid in full in 6 months, interest charges will be imposed from the date of purchase at the variable rate described above.

CREDIT PLAN DESCRIPTION
12 Months "Same as
Cash"/Monthly Payments
SUMMARY OF CREDIT PLAN
TERMS
No interest charges on the
promotional item(s) if paid in full in
12 months. If the balance

Property Status and Misc. Documents



By:

RECEIPT

CITY OF SAINT PAUL

Department of Safety & Inspections 375 Jackson Street, Suite 220 Saint Paul, MN 55101-1806

Phone: 651-266-8989 Fax: 651-266-9124 www.stpaul.gov/dsi

Payment #: 986191

Payment Date: February 19, 2014

Paid JOSE AMAYA

568 WESTERN AVE N SAINT PAUL MN 55103-1928 Amount Paid:

\$5,000.00

Payment Type:

Check

Transaction Description

Project Location: 444 BEACON AVE ST PAUL MN 55104-3529

12 - 213800

TYPE: VACANT BUILDING

vb

SUB TYPE: CATEGORY 3

WORK TYPE: SINGLE FAMILY RESIDENTIAL

is there a lock box?

Yes

Lock Box combination

PAS

FEES

Performance Deposit


5,000.00

TOTAL

5.000.00

^{**} To schedule a Vacant Building Code Compliance Inspection, call Jim Seeger at 651-266-8989 between 7:30 and 9:00 AM, Monday - Friday. **


^{**} Questions regarding Vacant Building Performance Deposits can also be directed to Jim Seeger. **































CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-9124 Web: www.stpaul.gov/dsi

* * This Report must be Posted on the Job Site * *

Code Compliance Report

November 19, 2013

TALBOT REALTY 6043 HUDSON ROAD SUITE 140F WOODBURY MN 55125

Re: 444 Beacon Ave File#: 12 213800 VB3

Dear Property Owner:

The following is the Code Compliance report you requested on October 24, 2013.

Please be advised that this report is accurate and correct as of the date November 19, 2013. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from November 19, 2013. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected:

ZONING

- 1. This property is in a(n) RM2 zoning district.
- 2. This property was inspected as a Single Family Dwelling.

BUILDING Inspector: Jim Seeger Phone: 651-266-9046

- Cover water meter pit with concrete or decay resistant, screwed-down cover. Cleanouts to be flush with floor slab.
- Remove or encapsulate asbestos in an approved manner.
- Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary.
- Provide complete storms and screens, in good repair for all door and window openings.
- Provide functional hardware at all doors and windows
- Exit doors shall be capable of being opened from the inside, easily and without the use of a key. Remove all surface bolts.
- Repair or replace damaged doors and frames as necessary, including storm doors.

Page 2

BUILDING Inspector: Jim Seeger Phone: 651-266-9046

- Weather seal exterior doors, threshold and weather-stripping.
- Repair walls, ceiling and floors throughout, as necessary.
- Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present.
- Any framing members that required repair or do not meet code (where wall and ceiling covering is removed, members that are over-spanned, over-spaced, not being carried properly, door and window openings that are not adequately supported, etc.) are to be reconstructed in an approved manner.
- Provide fire block construction as necessary and seal chases in basement ceiling.
- Where wall and ceiling covering is removed install full thickness or code-specified insulation.
- Air-seal and insulate attic/access door.
- Install Smoke Detectors/Carbon Monoxide Detectors per MN Conservation Code and the MN Dept. of Labor and Industry: Install per code where feasible.
- Provide major clean-up of premises.
- Repair siding, soffit, fascia, trim, etc. as necessary.
- Provide proper drainage around house to direct water away from foundation of house.
- Provide proper drainage around house to direct water away from foundation of garage.
- Provide general rehabilitation of garage.
- Install address numbers visible from street and on the alley side of garage.
- Remove drywall from basement ceiling or properly install.
- Install handrail and guardrail to code on basement stairs.
- Install safety glass in window at both stair landing windows.
- Repair flooring under carpet in northwest bedroom.
- Attic room needs egress window to meet code if bedroom.
- Install handrail and guardrail to code on 3rd floor stairs.
- Install safety glass in window at 3rd floor stair landing.
- Front porch aluminum wrap on freeze board needs slope away from building and flashing for siding to seal out water.
- Install deck flashing at house connection to deck.
- Replace all roof covering, siding, trim and soffits on garage.
- A building permit is required to correct the above deficiencies.

ELECTRICAL Inspector: Randy Klossner Phone: 651-266-9032

- Ground the electrical service to the water service with a copper conductor within 5 feet of the entrance point of the water service
- Bond around water meter with a copper wire sized for the electrical service per Article 250 of the NEC
- Provide a complete circuit directory at service panel indicating location and use of all circuits
- Ground bathroom light in first floor bathroom and kitchen sink light.

Page 3

ELECTRICAL Inspector: Randy Klossner Phone: 651-266-9032

- Remove all cord wiring
- Repair or Replace all broken, missing or loose light fixtures, switches and outlets, covers and plates
- Check all outlets for proper polarity and verify ground on 3-prong outlets
- Install hard-wired, battery backup smoke detector and other smoke detectors as required by the IRC. Also, Install carbon monoxide detector(s) within 10 feet of all bedrooms
- Install receptacle for garage door opener
- Remove and or/ re-wire all illegal, improper or hazardous wiring in garage and 3rd level (wired without permits).
- Replace all painted-over receptacles.
- Remove/rewire dishwasher to current NEC.
- Insure old hot tub branch circuit disconnected and all boxes terminated and closed per NEC.
- Install NM cable connectors in panel where required by the NEC.
- Remove/rewire overhead garage feeder to current NEC.
- Based on repair list purchase permit for 6 circuits minimum.
- All added receptacles must be grounded, tamper-resistant and be on an Arc-Fault Circuit Interrupter-protected circuit.
- Any open walls or walls that are opened as part of this project must be wired to the standards of the current NEC.
- All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

PLUMBING Inspector: Rick Jacobs Phone: 651-266-9054

- Basement Water Heater Vent must be in chimney liner (MFGC 501.12)
- Basement Water Heater gas venting incorrect (MFGC 503)
- Basement Water Heater not fired or in service (MPC 2180)
- Basement Water Meter corroded piping; incorrect piping (MPC 0200 0.)
- Basement Water Meter raise meter to a minimum 12 inches above floor (MPC 2280)
- Basement Water Meter remove meter from pit (SPRW 94.04)
- Basement Water Meter service valves not functional or correct (MPC 1800 Subp 3,4)
- Basement Water Meter support meter properly (MPC 2280)
- Basement Water Piping boiler fill water line requires backflow assembly or device (MPC 2100)
- Basement Water Piping pipe sizing incorrect (MPC 4715.1730)
- Basement Water Piping provide water piping to all fixtures and appliances (MPC 1700)
- Basement Water Piping repair or replace all corroded, broken or leaking piping (MPC 4715.1720)
- Basement Water Piping run 1 inch water line from meter to first major take off (SPRWS Water Code)
- Basement Gas Piping add appropriate metal hangers (MFGC 407.2)
- Basement Gas Piping dryer gas shutoff; connector or piping incorrect (MFGC 411)

Page 4

PLUMBING Inspector: Rick Jacobs Phone: 651-266-9054

- Basement Gas Piping replace improper piping or fittings (MFGC 411)
- Basement Gas Piping run dryer vent to code (MFGC 614.1 614.7)
- Basement Soil and Waste Piping add appropriate hangers (MPC 1430 Subp. 4)
- Basement Soil and Waste Piping improper connections, transitions, fittings or pipe usage (MPC 2420)
- Basement Soil and Waste Piping improper pipe supports (MPC 1430 Subp. 4)
- Basement Soil and Waste Piping no front sewer clean out (MPC 1000)
- Basement Soil and Waste Piping no soil stack base clean out
- Basement Soil and Waste Piping replace the floor drain cover or clean out plug (MPC 1300)
- Basement Soil and Waste Piping unplugged or open piping; back pitched piping (MPC 1000)
- Basement Laundry Tub faucet is missing, broken or parts missing (MPC 0200. P.)
- Basement Laundry Tub fixture is broken or parts missing (MPC 0200 0.)
- Basement Laundry Tub incorrectly vented (MPC 2500)
- Basement Laundry Tub provide a vacuum breaker for the spout (MPC 2000 B)
- Basement Laundry Tub waste incorrect (MPC 2300)
- Basement Laundry Tub water piping incorrect (MPC 0200 P.)
- First Floor Secure the lavatory on the first floor to the wall properly.
- First Floor Gas Piping range gas shut off; connector or piping incorrect (MFGC 411)
- First Floor Lavatory waste incorrect (MPC 2300)
- First Floor Sink waste incorrect (MPC 2300)
- First Floor Tub and Shower Provide access (MPC 0900)
- First Floor Tub and Shower provide stopper (MPC 1240)
- Exterior Lawn Hydrants Requires backflow assembly or device (MPC 2000)
- All the above corrections to waste, vent, water, and gas piping shall be per the Minnesota Plumbing Code Chapter 4715 & Chapter 326, the Minnesota Mechanical Code, the Minnesota Fuel Gas Code, and the Saint Paul Regional Water Code. All plumbing must be done by a plumbing contractor licensed in the State of Minnesota and the City of St. Paul under an approved permit.

HEATING Inspector: Kevin Chapdelaine Phone: 651-266-9042

- Install approved level handle manual gas shutoff valve on boiler and remove unapproved valve.
- Clean and Orsat test boiler burner. Check all controls for proper operation. Provide documentation from a licensed contractor that the heating unit is safe
- Install approved metal chimney liner
- Replace boiler flue venting to code and seal ununsed openings in chimney.
- Connect boiler and water heater venting into chimney liner
- Provide adequate combustion air and support duct to code
- Plug, cap and/or remove all disconnected gas lines

Page 5

HEATING Inspector: Kevin Chapdelaine Phone: 651-266-9042

- Provide a window in the bathrooms with an aggregate glazing area of not less than 3 square feet, one-half of which must be openable or provide exhaust system vented to outside.
- A mechanical ventilation permit is required if an exhaust system is installed.
- Conduct witnessed pressure test on hot water heating system and check for leaks
- Install back flow preventer on city water fill line to hot water heating system and pipe vent as required.
- Repair or replace radiator valves as needed
- Install isolation valves on boiler supply and return.
- Remove wood stove and chimney from garage and seal openings.
- Mechanical gas and hydronic permits are required for the above work.

Notes:

- See attachment for permit requirements and appeals procedure.
- This property is designed by the Vacant Buildings Department as a Category #3 which requires a \$5000.00 Performance Bond or Deposit at the time the permit is issued.
- Most of the roof covering could not be inspected from grade. Recommend this be done before rehabilitation is attempted.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected in accordance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34) and all required permits must receive final approval within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Jim Seeger between 7:30 - 9:00 AM at 651-266-9046 or leave a voice mail message.

Sincerely,

James L. Seeger, Code Compliance Officer

Phone: 651-266-9046

Email: jim.seeger@ci.stpaul.mn.us

JLS:ml

Attachments