

□ Other

We need the following to process your appeal:

\$25 filing fee payable to the City of Saint Paul

APPLICATION FOR APPEAL

Saint Paul City Council - Legislative Hearings

310 City Hall, 15 W. Kellogg Blvd.

RECEIVED Saint Paul, Minnesota 55102

Telephone: (651) 266-8585

HEARING DATE & TIME

JUL 03 2014

CITY CLERK

(it cash: receipt number <u>Check 5577</u>)	(provided by Legislative Hearing Office)			
Copy of the City-issued orders/letter being appealed	Tuesday, July 22, 2014			
Attachments you may wish to include	,			
This appeal form completed	Time			
Malk-In OR - Mail-In	Location of Hearing:			
for abatement orders only: Email OR Fax	Room 330 City Hall/Courthouse			
•				
Address Being Appealed:				
Number & Street: 360 Spring Street City: St Paul State: MN Zip: 55102				
Appellant/Applicant: Riverview at Upper En	nail Aleskunski at Stuarte			
Phone Numbers: Business (651) 228 980 Residence Cell				
Signature: agent Laskassi	Date:			
Name of Owner (if other than Appellant):				
Mailing Address if Not Appellant's:				
Phone Numbers: Business 651.778.9800 Residence	Cell			
What Is Being Appealed and Why? Attachments Are Acceptable				
What is being Appealed and Why? Attachments Are Acceptable				
Vacate Order/Condemnation/ Revocation of Fire C of O				
□ Summary/Vehicle Abatement				
	e attached			
□ Code Enforcement Correction Notice				
□ Vacant Building Registration				
- vacant building Kegistration				

We are appealing item #14

SPLC 34.11 (6)- Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the St. Paul Fire Marshal's Existing Fuel Burning Saftey Test Report to his office. —Contact mechanical contractor to provide test for each individual heating system.

Our apartment community is comprised of 344 apartments at two buildings located at 360 Spring Street and 400 Spring Street. Each apartment home has its own individual heating/cooling system located in the apartment called a MagicPak system. We are objecting to the necessity to conduct an individual inspection on each apartment for the following reasons:

- In 2009 the City Of St Paul required carbon monoxide detectors to be placed in every apartment. Some apartments required multiple detectors. We installed the required equipment per the City requirement with a cost of \$8945 for the equipment, which did not include installation labor charges or battery charges. It is our understanding the carbon monoxide detectors would alert us in the event of monoxide output. Why does the City feel we need to have a test when we've already solved the issue by installing Carbon Monoxide detectors back in 2009? What has changed since our last inspection in 2009 when this test was not required?
- The cost of testing each apartment is very high. We are estimating a \$30,000 expense to complete the testing. We have a vendor bid which estimates \$19,780 for testing, which accounts for an estimated ½ hour total test time per unit. This estimate would not include our own labor time of estimated \$5,000 for our staff to oversee testing in each home. The bid does not account for any additional time beyond ½ hour or any other fees that may be required. Requiring this test for every apartment is so costly we find it to be unreasonable.
- We are currently not in heating season and our residents are using their air-conditioning, which is part of the MagicPak system.
- We provide annual preventative maintenance to our Magic Pak systems and are considered Allied Partners by Xcel Energy center for conducting heating system tune ups and conducting system analysis testing.

We propose the inspection affidavit should be sufficient to satisfy the City's' objective in verifying the heating equipment is not producing monoxide.



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

June 19, 2014

ATTN. ANGELA RIVERVIEW AT UPPER LANDING 400 SPRING ST ST PAUL MN 55102

FIRE INSPECTION CORRECTION NOTICE

RE.

360 SPRING ST Ref. #100418

Residential Class: A

Dear Property Representative:

Your building was inspected on June 19, 2014 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on July 9, 2014 at 12:00 PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. 1st Floor Bathroom MSFC 703 Provide, repair or replace the fire rated door and assembly. Repair and maintain the woman's bathroom door closer.
- 2. Garage Storage MSFC 315.2.5 Fueled equipment, including but not limited to motorcycles, mopeds, lawn-care equipment and portable cooking equipment, shall not be stored, operator or repaired within a building. Remove fueled equipment from electrical room.

- 3. Garage Storage room MSFC 3404.3.5.1 Immediately remove and discontinue storage of all Class 1 Flammable liquids in the electrical room. Remove gasoline storage in electrical room
- 4. Garage MSFC 3404.3.3.4 Provide approved Flammable/Combustible liquid storage cabinet for quantities of Class 1 and 2 liquids exceeding 10 gallons used for maintenance purposes and operation of equipment.
- 5. Garage Level Storage Room NEC 110-26 Provide and maintain a minimum of 36 inches clearance in front of all electrical panels. Remove storage in front of electrical panels.
- 6. Stair C MSFC 703 Provide, repair or replace the fire rated door and assembly. -Repair and maintain the door closer.
- 7. Stairway D MSFC 1010.5 Provide and maintain an approved emergency lighting system. Repair emergency lighting in approved manner.
- 8. Unit 117 MSFC 605.4 Discontinue use of all multi-plug adapters.
- 9. Unit 120 MSFC 703 Provide, repair or replace the fire rated door and assembly.
 Repair and maintain the door closer.
- 10. Unit 141 MSFC 605.4 Discontinue use of all multi-plug adapters.
- 11. Unit 141 MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.
- 12. Unit 141 MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 13. Unit 230 MSFC 703 The fire door must not be obstructed or impaired from its proper operation at any time. Remove rug and adjust door sweep to clear obstruction from door swing.
- 14. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.

 Contact mechanical contractor to provide test for each individual heating system.

15. MSFC 506.2 - Call Fire Department communication center at (651) 224-7371 to make arrangements to have the keybox opened when you have the correct keys on site.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: jeremy.hall@ci.stpaul.mn.us or call me at 651-266-8987 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Jeremy Hall Fire Inspector

Reference Number 100418



DATE:

6/9/2009

_!NVQICE NUMBER: JOB NUMBER: 64036 292074

PURCHASE ORDER:

4921 Babcock Trail • Inver Grove Heights, MN 55077 • Phone (651) 450-0352 Fax (651) 450-9740

Sold To: Riverview at Upper Landing c/o Stuart Co 400 Spring St St Paul MN 55102 Complex: Riverview at Upper Landing

400 Spring St St Paul MN

1 TE	EM.					
						PRICE
Market Name of the						
DIDEO	TSALE				경찰 가는 가는 것이 없다.	· 企业等的工具经验的基础设计。
DIKEU	TOALE	(897) 1	sattery Operated	I CO Detectors	2) \$17.75 ea:	\$7,046.75
	19年的公司政府保险				A 411 4 1 4 1 4 1 4 1 4 1	
30 00000000000000000000000000000000000						
	人工。自己的经济重					
	. To E (()					

DELIVERED

By Roberta S.

\$15.00

DATE OF JOB

6/4/09

PLEASE PAY ON THIS INVOICE - NO STATEMENT WILL BE SENT

TERMS Net 30 Subtotal \$7,061.75

Tax \$511.99

Total \$7,573.74



DATE 7/28/2009

INVOICE NUMBER: JOB NUMBER:

64685 292610

PURCHASE ORDER:

4921 Babcock Trail • Inver Grove Heights, MN 55077 • Phone (651) 450-0352 Fax (651) 450-974

Sold To: Riverview at Upper Landing c/o Stuart Go 400 Spring St St Paul MN 55102

Complex: Riverview at Upper Landing

400 Spring St St Paul MN

<u>ITEM</u>		<u>PRICE</u>
DIRECT SALE	(71) Battery Operated CO Detectors @ \$17	775 ea \$1,26025
DELIVERED	By Roberta S.	\$15.00

DATE OF JOB

7/7, 7/17

PLEASE PAY ON THIS INVOICE - NO STATEMENT WILL BE SENT

TERMS Net 30 Subtotal	\$1,276.26
Tax Total	\$97.25 \$1,372.50

PROPOSAL

PLUMBING • HEATING • HIGH PURITY PIPING • AIR CONDITIONING • PROCESS PIPING • REFRIGERATION • SHEET METAL • SERVICE



Date of Acceptance_

Figure 4401 Quebec Ave. N., New Hope, MN 55428 Construction: 763.533.1900 Fex: 763.235.9810 Service: 763.235.9833 Fex: 763.235.9834 Formultz-mal.com

Stuart Company 1000 West 80th Street	Proposal Number:	July 1 , 2014 M14-108
Bloomington , MN Attn : Darren Jakel	Regarding:	Riverview at Upper Landing – Fuel Burner testing on Magic-Pak units
Darren,		
Per your request we have put together pricing to perform a f at the Riverview Landing location at 400 Spring Street in St F testing and carbon monoxide test for each individual unit. It is the heating startup season as these units are occupied and v	Paul , MN . This inspe s our recommendatio	ection will include the city required orsat- n that this inspection be completed during
Proposed total cost: \$19,780.00		
We figure it to be about $\frac{1}{2}$ hour per unit for the inspection. The will be a city fee per unit or if this would be a bulk fee on this		he permit fees as we are not aware if there
Please feel free to give me a call if you have any additional q	uestions or concerns	5.
Exclusions: 1. Overtime 2. Additional work required by code authority		
PAYMENT to be made as the work progresses to the value The entire amount of contract to be paid within 30 days after		complete and material on job site.
	Authorized Signature:	Mark Tolero
	Please note this proposal m	Mark Totino hay be withdrawn by us if not accepted within 30 days.
Acceptance of Proposal The above prices, specifications and conditions are satisfactory and are hereby accepted. You are authorized to do the work as specified. Payment will be made as outlined above.	Signature:	

Signature: __

RESIDENTIAL HEATING

Chapter 34 of the Saint Paul Legislative Code, known as the "Housing Code", sets minimum standards for health and life safety for occupants of all residential property in Saint Paul.

Many owners have confused the legal dates of Xcel shut-off requirements (October to April) with the code requirement to provide heat. To clarify this specific requirement, please note that a building owner or manager is responsible to maintain the heat in a dwelling unit to 68 degrees five feet above the floor in any occupied room at any time, throughout the year. Failure to do so may result in enforcement action. The laws not allow tenants to remain in a dwelling that lacks basic services (heat, light, water).

Please cooperate with Fire Prevention efforts to maintain a high level of health and life safety for occupants of all Saint Paul rental property.

Chapter 34 (Revised January, 1993) provides for assurance of safe heating equipment by allowing The enforcement officers to require proof of current service of any heating or space heating facility by a licensed contractor. The documentation of the service must include a carbon monoxide reading. We have furnished you with a form (see back of this page) to furnish your service contractor. Please have the contractor fill out the form and return it to the inspector during the Certificate of Occupancy renewal inspection (or referral inspection if a problem is apparent). This will expedite the inspection process and help assure the safety of tenants and protection of your property.

Department of Safety and Inspections Fire Inspection Division