We need the following to process your appeal:



APPLICATION FOR APPEAL

Saint Paul City Council – Legislative Hearings RECEIVED 310 City Hall, 15 W. Kellogg Blvd.

OCT 06 2014

Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

CITY CLERK

A PPP X	\$25 filing fee (non-refundable) (payable to the City of Saint (if cash: receipt number <u>Check 4598</u>) Copy of the City-issued orders/letter being appealed Attachments you may wish to include This appeal form completed Walk-In OR Mail-In for abatement orders only: Email OR Fax	HEARING DATE & TIME (provided by Legislative Hearing Office) Tuesday, 10 / 14 / 14 Time / 1:30 av Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appealed: Ref # 14594		
Number & Street: 429 Robert st S. City: St. Paul State: MN Zip: 55107 Appellant/Applicant: HARRY "Ditch" Exceptande Email dutch Quest. Net		
Phone Numbers: Business 651-224-444 Residence 763-767-0754 Cell 612-751-2928 Signature: Date:		
Name of Owner (if other than Appellant): Mailing Address if Not Appellant's:		
What Is Being Appealed and Why? Attachments Are Acceptable Vacate Order/Condemnation/		
□ R □ S □ S □ V □ O	in spection of Fire C of O in spection of Sire C of O ummary/Vehicle Abatement ire C of O Deficiency List/Correction ode Enforcement Correction Notice in condemne in co	f condition when we purchased the f they weren't up to code thang e been corrected prior to purchus
a	and paid for by John Votales to effected the SAle prices at the resources to do this was Roprieve on our SAles taxe	125 111 8 1 1d / a 118 Revised 8/11/2014



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

September 29, 2014

429 INC. 429 ROBERT ST S ST PAUL MN 55107

FIRE INSPECTION CORRECTION NOTICE

RE:

429 ROBERT ST S

Ref. #14584

Dear Property Representative:

Your building was inspected on September 29, 2014 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on October 30, 2014 at 10:30 am.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. Basement Commercial Space UMC 1346.703 Provide 30 inches clearance around all mechanical equipment.-Remove chair and other storage next to or by furnace and water heater.
- 2. East Entry Commercial Space MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.-Missing light cover.
- 3. East Exterior Bedroom Window SPLC 34.09 (3), 34.32 (3) Repair and maintain the window glass.-Replace cracked bedroom window.

- 4. East Exterior Upper Awnings SPLC 34.08(5), 34.32(3) All accessory structures including, but not limited to, detached garages, sheds and fences shall be maintained structurally sound and in good repair. Provide and maintain exterior unprotected surfaces painted or protected from the elements.-Remove or replace damaged awnings.
- 5. Kitchen Residential Unit MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes were missing.-Missing cover plate on south kitchen wall.
- 6. Kitchen Residential Unit SPLC 34.10 (7), 34.33 (6) Repair and maintain the cabinets in an approved manner.-Missing panel cover of cabinet underneath countertop.
- 7. Living Room Residential Unit MSFC 1028.3 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exit way.-Cover cord or remove cord running along floor.
- 8. Men's Restroom Commercial Space MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.-Missing light fixture cover.
- 9. Middle Bedroom Residential Unit SPLC 34.12 (2), SPLC 34.36 (1) Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code. -Missing door knob and assembly.
- 10. South Exterior Outlet MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes were missing.-Install missing weatherproof cover on south exterior outlet.
- 11. Women's Restroom Walls next to sink SPLC 34.10 (7), 34.34 (6) Repair and maintain the walls in an approved manner. -Repair damaged wall next to and behind sink.
- 12. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: sean.westenhofer@ci.stpaul.mn.us or call me at 651-266-8982 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Sean Westenhofer Fire Inspector Ref. # 14584