

CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

October 29, 2014

Del Co Limited Partnership Po Box 17122 Saint Paul MN 55117-0122

Revocation of Fire Certificate of Occupancy and Order to Vacate

RE: 1084 EUCLID ST

Ref. # 122293

Dear Property Representative:

Your building was determined to be a registered vacant building on October 29, 2014. Since certificates are for the occupancy of buildings, it has become necessary to revoke the Certificate of Occupancy.

Saint Paul Legislative Code provides that no building shall be occupied without a Certificate of Occupancy. In order to re-occupy the building, the following deficiencies (if applicable) must be corrected and a complete Certificate of Occupancy inspection will be required.

DEFICIENCY LIST

- 1. Exterior North Entrance SPLC 34.09 (3), 34.32 (3) Repair and maintain the door frame. Repair porch door frame free from damage.
- 2. Exterior Rear of house SPLC 34.08 (7) All parking spaces shall be paved with asphalt, concrete, or durable dustless surfacing. Before any existing spaces may be paved, site plan approval must be obtained as specified in the St. Paul Zoning Code. Contact DSI Zoning at 651-266-9090.
- 3. Exterior Throughout SPLC 34.09 (1) b,c, 34.33 (1) b, c Provide and maintain all exterior walls free from holes and deterioration. Repair and maintain all surfaces including but not limited to window trim, porch, and eaves and chimney.
- 4. Exterior Throughout SPLC 45.03(b) All exterior surfaces must remain free of any initials, marks, symbols, designs, inscriptions or other drawings, scratched, painted, inscribed or otherwise affixed. Remove all graffiti and markings throughout exterior of house and fence.

- 5. Interior Permits MSBC -Section 105.1 Permits Required. Have Permit #2012-223745 approved. Contact Nate Bruhn @ for inspection.
- 6. Interior Throughout SPLC 34.10 (6), 34.33 (5) Exterminate and control insects, rodents or other pests. Provide documentation of extermination. Report of rat infestation throughout property, provide documentation of extermination.
- 7. Interior Throughout SPLC 34.19 Provide access to the inspector to all areas of the building. Inspector was refused access by building representative when investigating complaint.
- 8. Interior Throughout MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area. Inspector could hear smoke alarms chirping on exterior inspection.
- 9. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 10. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: jeremy.hall@ci.stpaul.mn.us or call me at 651-266-8987 between 7:30 - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Jeremy Hall Fire Inspector

Ref. # 122293