
## Picture of living Room Before and After:

## Before:





Quote for repairs at 297 Aurora Ave:

F R O M	TOM LENNARTSO 9353 71 <sup>ST</sup> Street Nortl Stillwater, MN 55082 651-429-4871 612-868-4258 MN Builders License		ION, INC.	POSTS CATAGO	PRO	OPOSAL
1755		HOTER SPENNING	10.00	DATE	5-14	SATI
NAM	PROPOSAL SL	IBMITTED TO:		7/-2		Duskex
INFAIN	John Sc	hoenhe	29	200 >	+ RALL	DODKER
STR	EET 31,29 TROT	Hers Lane	0/	XX SHETT	NO EL YO LINNIN	407
CITY	( )	has		Jeli .	1 14	
	WOOD BURY	11/10				
	Kitchen CA Bak Room Painting & Replace 120	UNNEOWY				2600 - 31
	FRONT & BACK	& Poach + ST	leps		4	.2200 - 3/
	FRONT & BACK	K Peach + ST	reps	Dumpster Fe		.2600
mate	hereby propose to furnish	Add P  labor and materials  down at accept for proposal at labor and proposal at labor and project be as specified. Alleviation from above the proposal subject.	ermit and  c, complete in  otance of project  Il work to be e specification d above the to acceptant	Dumpster Fe accordance with oosal.  completed in a ns, involving extensionale. All agree within 30 days	workmanlike ra costs will be saments contings and it is void	ecifications to be time and
mate	hereby propose to furnisherial	Add P  labor and materials  down at accept of proposal at work of proposal minus of project be as specified. Alleviation from above the proposal subject of the proposal subje	ermit and  c, complete in  stance of project  If work to be e specificate d above the to acceptance  Authorized S	Dumpster Fe accordance with oosal.  completed in a ns involving ext estimate. All agre within 30 days	workmanlike ra costs will be saments contings and it is void	ecifications to be time and
All r prace order dela under	hereby propose to furnisherial	Add P  labor and materials  down at accept of proposal at down of proposal minus of project be as specified. All deviation from above the proposal subject of the proposal sub	ermit and  i, complete in  otance of project  il work to be e specification d above the to acceptance  Authorized S	Dumpster Fe accordance with oosal.  completed in a ns, involving ext estimate. All agn e within 30 days gnatureTom Lennai	workmanlike ra costs will be ements conting and it is void	ecifications to be time and manner according to star e executed only upon, w gent upon strikes, accide thereafter at the option of
All r practice order dela under the made	hereby propose to furnisherial  material is guaranteed to tices. Any alteration or cars, and will become an eys beyond our control. The ersigned.	Add P  labor and materials  down at accep  for proposal at  dof proposal mi  vend of project  be as specified. Aleviation from abov  tra charge over an  its proposal subject  Acceptance	ermit and  c, complete in  otance of project  If work to be a specification d above the to acceptant  Authorized S  CEPTANCE	Dumpster Fe accordance with oosal.  completed in a ns, involving ext estimate. All agn e within 30 days gnatureTom Lennai	workmanlike ra costs will be ements continue and it is void	ecifications to be time and manner according to star e executed only upon, w gent upon strikes, accide thereafter at the option of

DEPARTMENT OF SAFETY AND INSPECTIONS Fire Inspection Division Ricardo X. Cervantes, Director



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: <u>www.stpaul.gov/dsi</u>

November 21, 2014

JOHN SCHOENHERR Catherine Schoenherr 9129 TROTTERS LANE ST PAUL MN 55125-8673

RE: RE-INSPECTION FIRE CERTIFICATE OF OCCUPANCY WITH DEFICIENCIES 295 AURORA AVE

Ref. # 105549

Dear Property Representative:

Your building was re-inspected for the Fire Certificate of Occupancy on October 30, 2014. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected immediately. A reinspection will be made on January 5, 2015 at 10:00am.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

## DEFICIENCY LIST

- 295 Aurora MSFC 1003.3.1.8 Remove unapproved locks from the exit doors. The door must be open able from the inside without the use of keys or special knowledge or effort. -Remove the hook and loop lock from the attic door.
- 2. 295 Aurora SPLC 34.10 (7), 34.34 (6) Repair and maintain the walls in an approved manner. -Paint the walls.
- 3. 295 Aurora MSMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter and installed in accordance with the mechanical code. This work may require a permit(s). Call DSI at (651) 266-8989.

- 4. 297 Aurora SPLC 34.23, MSFC 110.1 This occupancy is condemned as unfit for human habitation. This occupancy must not be used until re-inspected and approved by this office.-297 has been condemned by DSI and was emergency boarded by SPPD due to multiple code violations and gross unsanitary conditions. Unit must be fully rehabbed under permit and cannot be occupied until inspected and approved. Contact DSI at 651-266-8989.
- 5. 297 Aurora SPLC 34.10 (5), 34.33 (4), 34.16 Provide and maintain interior in a clean and sanitary condition.
- 6. EXTERIOR SPLC 34.09 (1) b,c, 34.33 (1) b, c Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.
- 7. EXTERIOR SPLC 34.08 (1), 34.31 (1) All exterior property areas shall be maintained free from any accumulation of refuse, garbage or feces.
- 8. EXTERIOR SPLC 34.09 (2), 34.32(2) Repair or replace the unsafe stairways, porch, decks or railings in an approved manner. This work will require a permit(s). Call DSI at (651) 266-9090. -Front and rear stairs.
- 9. EXTERIOR SPLC 34.09 (3), 34.32 (3) Repair and maintain the window in good condition. -Broken windows.
- 10. EXTERIOR SPLC 34.09 (3), 34.33 (3) -Provide or repair and maintain the window screen. -Broken screens.
- 11. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 12. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at adrian.neis@ci.stpaul.mn.us or call me at 651-266-8992 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

A.J. Neis Fire Inspector Ref. # 105549