

We need the following to process your appeal:

(if cash: receipt number 794175

Attachments you may wish to include

Copy of the City-issued orders/letter being appealed

# APPLICATION FOR APPEAL

Tuesday,

## Saint Paul City Council - Legislative Hearings

RECEIVED

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102

(provided by Legislative Hearing Office)

MAY 15 2015

Telephone: (651) 266-8585

Revised 8/11/2014

CITY CLERK

\$25 filing fee (non-refundable) (payable to the City of Saint Paul) HEARING DATE & TIME

☐ This appeal form completed	Time
<b>★</b> Walk-In OR □ Mail-In	Time/· 30 pm <u>Location of Hearing:</u> Room 330 City Hall/Courthouse
for abatement orders only:     Email OR   Fax	Noom ood ong zamm oom oo
Address Being Appealed:	
Number & Street: 1062 Forest 5+ City: 5	
Appellant/Applicant: Chue Feng Thao En	nail Chuefthao@smail.co
Phone Numbers: Business <u>651-399-1817</u> Residence	Cell
Signature:	Date: <u>5/15/15</u>
Name of Owner (if other than Appellant):	Thao
Mailing Address if Not Appellant's: 3654 Oak Te	M, WB1, MN 55110
Phone Numbers: Business <u>651-355-1817</u> Residence	Cell
What Is Being Appealed and Why?	Attachments Are Acceptable
Vacate Order/Condemnation/ Revocation of Fire C of O	
Summary/Vehicle Abatement	
Fire C of O Deficiency List/Correction / 2 5	6.78
☐ Code Enforcement Correction Notice	
□ Vacant Building Registration	
□ Other (Fence Variance, Code Compliance, etc.)	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

May 8, 2015

CHUE FENG THAO 3654 OAK TERRACE WHITE BEAR LAKE MN 55110-3224

### FIRE INSPECTION CORRECTION NOTICE

RE:

1062 FOREST ST

Ref. #114417

Residential Class: C

### Dear Property Representative:

Your building was inspected on May 8, 2015 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on June 8, 2015 at 12NOON.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

#### DEFICIENCY LIST

- 1. B Unit 2nd floor SPLC 34.13 (3), SPLC 34.17 (2) Reduce and maintain the number of occupants in the sleeping rooms to: 2-Bedroom Northside
- 2. Building UMC 1346.703 Provide 30 inches clearance around all mechanical equipment.-

- 3. Unit A SPLC 34.09 (3), 34.33 (3) -Provide or repair and maintain the window screen. Front storm door screen-
  - 4. Unit B MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring. Stop using extension cords.-
- 5. Unit B SPLC 34.11, MSBC 2902.1, SPLC 34.17, MSPC 415.0220 Repair or replace and maintain all parts of the plumbing system to an operational condition.-Repair or replace and maintain an approved private toilet. Secure toilet to floor
- 6. Unit B SPLC 34.13 (2), (3), SPLC 34.17 (2) Reduce and maintain the number of occupants in the unit to: 5-
- 7. Unit B 3rd floor SPLC 34.13 (3), SPLC 34.17 (2) Reduce and maintain the number of occupants in the sleeping rooms to: 2-Bedroom third floor has bedroom on the southside overcrowded
- 8. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 9. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.
- 10. MSMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter and installed in accordance with the mechanical code. This work WILL require a permit(s). Call DSI at (651) 266-8989.-Dryer duct is not code compliant material.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: james.thomas@ci.stpaul.mn.us or call me at 651-266-8983 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

James Thomas Fire Inspector

Reference Number 114417