

CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

June 17, 2015

Omobolaji N Shadrack 286 Winthrop St S Saint Paul MN 55119-5300

## Revocation of Fire Certificate of Occupancy and Order to Vacate

RE: 2203 GLENRIDGE AVE

Ref. # 105801

Dear Property Representative:

Your building was inspected on June 1, 2015, for the renewal of the Certificate of Occupancy. Since you have failed to comply with the applicable requirements, it has become necessary to revoke the Certificate of Occupancy in accordance with Section 40.06 of the Saint Paul Legislative Code.

Per Legislative Hearing Officer recommendation a re-inspection will be made on July 17, 2015 at 1:00pm or the property vacated on August 1, 2015, and the property transferred to vacant buildings.

The Saint Paul Legislative Code further provides that no building shall be occupied without a Certificate of Occupancy. Failure to immediately complete the following deficiency list or the building vacated may result in a criminal citation.

## **DEFICIENCY LIST**

- 1. 2203 Basement SPLC 34.12 (2), SPLC 34.36 (1) Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code.-There was an empty smoke detector bracket in the basement.
- 2. 2203 First floor bathroom Door SPLC 34.09 (3), 34.33 (3) Repair and maintain the door in good condition.-
- 3. 2203 First floor bathroom SPLC 34.11, MSBC 2902.1, SPLC 34.17, MSPC 415.0220 Repair or replace and maintain all parts of the plumbing system to an operational condition. The cold water knob was broken off and the drain was leaking.

- 4. 2203 Master bathroom SPLC 34.14 (3), MPC 4715.200.T Provide and maintain a window or approved ventilation system in all bathrooms.-
- 5. 2203 Second floor bathroom Door SPLC 34.09 (3), 34.33 (3) Repair and maintain the door in good condition.-
- 6. 2203 Second floor bathroom SPLC 34.14 (3), MPC 4715.200.T Provide and maintain a window or approved ventilation system in all bathrooms.-Vent fan was not working.
- 7. 2203 Second floor hallway MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.-
- 8. 2203 Second floor north east bedroom SPLC 34.10 (7), 34.34 (6) Repair and maintain the walls in an approved manner.
- 9. 2203 Second floor south center bedroom Door SPLC 34.09 (3), 34.33 (3) Repair and maintain the door in good condition.-
- 10. 2203 Second floor south center bedroom SPLC 34.09 (3), 34.32 (3) Repair and maintain the window frame.-The window sill is rotting off of the bedroom window.
- 11. 2203 Second floor south center bedroom SPLC 34.10 (7), 34.34 (6) Repair and maintain the walls in an approved manner.
- 12. 2203 Second floor south east bedroom Door SPLC 34.09 (3), 34.33 (3) Repair and maintain the door in good condition.-
- 13. 2203 Second floor south east bedroom SPLC 34.10 (7), 34.34 (6) Repair and maintain the walls in an approved manner.
- 14. 2203 South screen door Ext. Door SPLC 34.09 (3), 34.33 (3) Repair and maintain the door in good condition.-The south screen door was missing a closer.
- 15. 2205 Interior SPLC 34.19 Provide access to the inspector to all areas of the building.-Allow access for a C of O inspection. Failure to comply will result in enforcement action.
- 16. Exterior By driveway SPLC 34.12 (2), SPLC 34.36 (1) Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code. -There is a missing section of downspout missing off of the gutter system.
- 17. Exterior Drive Way SPLC 34.08 (7) All parking spaces shall be paved with asphalt, concrete, or durable dustless surfacing. Before any existing spaces may be paved, site plan approval must be obtained as specified in the St. Paul Zoning Code. Contact DSI Zoning at 651-266-9090.-Replace deteriorated drive way under permit.

- 18. Exterior Rear yard SPLC 34.08 (1), 34.31 (1) All exterior property areas shall be maintained free from any accumulation of refuse, garbage or feces.-Clean up dog feces in back yard.
- 19. Exterior Throughout SPLC 34.09 (1) e, 34.32 (1) d Provide and maintained the roof weather tight and free from defects.-
- 20. Garage Siding SPLC 34.08(5), 34.32(3) All accessory structures including, but not limited to, detached garages, sheds and fences shall be maintained structurally sound and in good repair. Provide and maintain exterior unprotected surfaces painted or protected from the elements.-Repair and paint deteriorating garage siding.
- 21. Garage trees MSFC 304.1 Remove excessive combustible storage and/or vegetation from exterior property areas.-Cut back trees from around the garage.
- 22. Work Plan Driveway Send a comprehensive and detailed work plan on all exterior repairs to include start and finish dates for all exterior repairs.-On 6/16/15 tenant appealed and was granted until 7/17/15 for owner to have a driveway plan submitted and approved by the legislative hearing officer.
- 23. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 24. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: george.niemeyer@ci.stpaul.mn.us or call me at 651-266-8991 between 7:30 - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

George Niemeyer Fire Inspector

Ref. # 105801