Page 1 of 2 STAMP - Activities

STAMP - Activities

Help using this report New Search

E-mail Service Desk

Run Date:

08/14/15 01:24 PM

728

Sort by Most Recent Date V Folder Type: All Folder Types

Starting Date: **Ending Date:**

House#: Street Name: OAKDALE

Folder Count: 24

Click on address link to access

Click on ID# link below to view detail

Click on address link to access Click on ID# link below to view detail					
GISmo, MapIT,	and Ramsey In Date		Status	Туре	Description
Address		10 #	Status		
728 Oakdale	05/26/2015	<u>15</u> 103993	Open	RE - Real Estate Assessments	Owner Del Co Limited Partnership
- mag	05/04/2015		Closed	RF - Referral - Citizen Complaint	Owner Del Co Limited Partnership - garage door unattached and leaning against the garage
/	04/30/2015	<u>15</u> 031519	Resolved	CS - CSO Complaint - Exterior - Complaint	garage door unattached and leaning against the garage
	04/03/2015	<u>15</u> 023700	Open	BW - Building Warning - Double/Penalty Fee	Owner Del Co Limited Partnership - Double Fee Plumbing Permit for Water Heater witnessed by Fire Inspector G.N. per R.J. 4/3/15
	03/20/2015	019781	Closed	PA - Parks Summary Abatement - Garbage Rubbish	Owner Del Co Limited Partnership - Remove bags of garbage near garage and all scattered misc rubbish in back yard (bottles, cans, plastic containers, etc.)
THIS CASE	03/11/2015	5 <u>15</u> 017106	Closed	RF - Referral - Citizen Complaint	Owner Del Co Limited Partnership - CODE: mattresses stacked on the front porch & loose trash and toys and what- not in the front & back yard FIRE: garage door unattached and garage filled with stuff & front doors on the house are not attached
	03/11/201	5 <u>15</u> 01710	Closed <u>4</u>	CS - CSO Complaint - Exterior - Complaint	CODE: mattresses stacked on the front porch & loose trash and toys and what-not in the front & back yard FIRE: garage door unattached and garage filled with stuff & front doors on the house are not attached
	11/04/201	4 <u>14</u> <u>34358</u> W ()	sento	PA - Parks Summary Abatement - Garbage Rubbish	Owner Del Co Limited Partnership - Remove: By garage near alley; two large wooden drawers, artificial tree, large cardboard box full of
1			DON'T BI	paptes	refuse. In yard; sofa, white waste basket. SA was sent. Photos.
V =	10/29/20	14 <u>14</u> 34180	Resolved 02	CS - CSO Complaint - Garbage Rubbish - Complaint	Trash in back near garage, no hauler service for weeks. They have a garbage can, but there are two drawers filled with things sitting there; cardboard boxes sitting out there (empty?); and an artificial tree;
	09/10/20	14 <u>14</u> 3276		pled	Responsible Party Del Co Ltd Partnership

Page 2 of 2 STAMP - Activities

