



275 Bates Avenue northwest (top)
and northeast (bottom) elevations






275 Bates Avenue southeast elevation (top), c. 1935
asbestos cement and asphalt shingle exterior walls
(below) with exposed original clapboard (below left)





C. 1935 asphalt and asbestos cement shingle detail on north elevation (above), c. 1884 Eastlake style balusters and newel post detail in front hallway (below)






C. 1884 baluster detail in front hall (above), downstairs kitchen (below left) and upstairs kitchen (below right)





Downstairs bathtub (above) c. 1884
baseboard detail in first floor
southwest room (below)





Transom and trim detail of front door in first floor vestibule (above), similar trim detail in upstairs front room (below)

