

700 4th St E northwest elevations (above) and neighborhood context (below)





700 4th St E northeast elevations





East elevation window well dated October 14, 1889 (above), with west elevation stucco fill (below left) and front door (below right)










Front stairwell balusters and newel post (above), trim detail in front hall (below left), and east elevation projecting bay window in Dining Room (below right)








Living Room (above), Eastlake style hinge detailing (below left) and enclosed back porch (below right)







Kitchen (above) and basement (below)







Front door with transom in front hall (above left), scale of 2nd floor doorways (above right), 2nd floor front bedroom (below)





C. 1931 rear addition living area (above) and rear addition elevations (below)

