



767 4<sup>th</sup> St E southwest elevations  
(above) and west elevation (below)





767 4<sup>th</sup> St E northeast elevations (above), west chimney (below left) and exposed portion of front porch (below right)





Exposed section of enclosed turned spindlework from original front porch (above), south wall of front room looking into enclosed front porch (below)





Interior curved wall and trim detail in first floor hallway (above), enclosed front stair (below left) and front room trim and door detail (below right)





Dining Room projectin

[Type a quote from the document or the summary of an interesting point. You can position the text box anywhere in the document. Use the Drawing Tools tab to change the formatting of the pull quote text box.]

f Dining Room (below)





Trim detail in Dining Room (above) and view of the kitchen, located in the c. 1902 addition.





Basement conditions (above), exposed section of original Eastlake style balusters and newel posts (below left), and mortise & tenon detail of upstairs door.

