

☐ Other (Fence Variance, Code Compliance, etc.)

APPLICATION FOR APPEAL

Saint Paul City Council - Legislative Hearings

RECEIVED

MAY 01 2017 Saint Paul, M

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

Revised 8/11/2014

	*
We need the following to process your appeal:	
\$25 filing fee (non-refundable) (payable to the City of Saint Paul (if cash: receipt number 950314) Copy of the City-issued orders/letter being appealed Attachments you may wish to include This appeal form completed	(provided by Legislative Hearing Office) Tuesday, May 16, 2017 Time_11:30 a.m.
Walk-In OR □ Mail-In	Location of Hearing: Room 330 City Hall/Courthouse
for abatement orders only: Email OR Fax	·
Address Being Appealed:	
Number & Street: 939 Bur St. City.	state: Main: 5513 (
Phone Numbers: Business Residence	Cen (51) 424-3158 Yah
Signature: MY Si	Date: 4-30-17
Name of Owner (if other than Appellant):	a retern
Mailing Address if Not Appellant's: 939 BUTT	\
Phone Numbers: Business Deceased Residence	Cell
What Is Being Appealed and Why?	Attachments Are Acceptable
Vacate Order/Condemnation Revocation of Fire C of O Summary/Vehicle Abatement Vacate Order/Condemnation Revocation of Fire C of O TOST GOT	out of Tail on April &
□ Fire C of O Deficiency List/Correction 10 Fix NP	nouse after someone
□ Code Enforcement Correction Notice Trashed 1	and broke in I am
□ Vacant Building Registration +\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	private visione tai and



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web: www.stpaul.gov/dsi

April 21, 2017

MARTHA TEICH C/O MARK MCCLELLAN 7885 RIMBLEY RD WOODBURY MN 55125-1643

Revocation of Fire Certificate of Occupancy and Order to Vacate

RE:

939 BURR ST

Ref. # 124383

Dear Property Representative:

Your building was determined to be unoccupied on March 28, 2017. Since certificates are for the occupancy of buildings, it has become necessary to revoke the Certificate of Occupancy.

Re-Inspection in on April 28th at 10am.

Saint Paul Legislative Code provides that no building shall be occupied without a Certificate of Occupancy. In order to re-occupy the building, the following deficiencies (if applicable) must be corrected and a complete Certificate of Occupancy inspection will be required.

DEFICIENCY LIST

- 1. EXTERIOR SIDING SPLC 34.09 (1)(2), 34.33 (1) Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.-Replace the missing siding on house
- 2. INTERIOR BASEMENT MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-8989.-Repair or replace the open wires in the basement area, needs to be maintained
- 3. INTERIOR BASEMENT NEC 110.26 Provide and maintain a minimum of 36 inches clearance in front of all electrical panels.
- 4. INTERIOR BASEMENT MSFC 603.5.3 Provide clearance around all mechanical equipment.-Remove items stored by furnace and water heater

- 5. INTERIOR EXTENSION CORDS MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.-
- 6. INTERIOR EXTRA LOCK MSFC 1008.1.9.3 The maximum number of locks on unit doors is two. Remove all locks in excess of two.-Remove the top lock on entry door
- 7. INTERIOR MULTI PLUGS MSFC 605.4 Discontinue use of all multi-plug adapters.
- 8. LOWER UNIT DOOR KNOB SPLC 34.09 (4), 34.32 (3) Repair and maintain the door latch.-Repair or replace the damaged door knob
- 9. LOWER UNIT DOOR TRIM SPLC 34.09 (4), 34.32 (3) Repair and maintain the door frame.-Repair or replace the missing trim on door in kitchen area
- 10. LOWER UNIT ENTRY DOOR SPLC 34.33 (3) Repair and maintain the door in good condition.-Repair or replace the damaged door to lower unit, hole on exterior side and cracked
- 11. LOWER UNIT GAS CAN MSFC 313.1 Fueled equipment, including but not limited to motorcycles, mopeds, lawn-care equipment and portable cooking equipment, shall not be stored, operator or repaired within a building.-Remove the gas can from the back patio area
- 12. LOWER UNIT KITCHEN CABINET SPLC 34.10 (7) Repair and maintain the cabinets in an approved manner.-Repair or replace the damaged framing, where the dish washer was. Needs to be maintained
- 13. LOWER UNIT COVERS MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.-Provide covers to switches and panel box cover is missing
- 14. UPPER UNIT BEDROOM CARPET SPLC 34.10 (7), 34.17(5) Repair and maintain the floor in an approved manner.-Repair or replace the carpeting, that's missing in the upper bedrooom
- 15. UPPER UNIT CRACKS IN WALL SPLC 34.10 (7), 34.17 (5) Repair and maintain the walls in an approved manner.-Patch the holes and/or cracks in the walls, in the upper unit entrance and hallway area
- 16. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: Jonathan.Gaulke@ci.stpaul.mn.us or call me at 651-266-8994 between 7:30 - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Jonathan Gaulke Fire Inspector Ref. # 124383



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

March 28, 2017

MARTHA TEICH C/O MARK MCCLELLAN 7885 RIMBLEY RD WOODBURY MN 55125-1643

Revocation of Fire Certificate of Occupancy and Order to Vacate

RE:

939 BURR ST

Ref. # 124383

Dear Property Representative:

Your building was determined to be unoccupied on March 28, 2017. Since certificates are for the occupancy of buildings, it has become necessary to revoke the Certificate of Occupancy.

Saint Paul Legislative Code provides that no building shall be occupied without a Certificate of Occupancy. In order to re-occupy the building, the following deficiencies (if applicable) must be corrected and a complete Certificate of Occupancy inspection will be required.

Re-Inspection in on April 28th at 10am.

DEFICIENCY LIST

- 1. INTERIOR BASEMENT MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-8989.-Repair or replace the open wires in the basement area, needs to be maintained
- 2. INTERIOR BASEMENT NEC 110.26 Provide and maintain a minimum of 36 inches clearance in front of all electrical panels.
- 3. INTERIOR BASEMENT MSFC 603.5.3 Provide clearance around all mechanical equipment.-Remove items stored by furnace and water heater
- 4. INTERIOR EXTENSION CORDS MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.-Default

- 5. INTERIOR EXTRA LOCK MSFC 1008.1.9.3 The maximum number of locks on unit doors is two. Remove all locks in excess of two.-Remove the top lock on entry door
- 6. INTERIOR MULTI PLUGS MSFC 605.4 Discontinue use of all multi-plug adapters.
- 7. LOWER UNIT DOOR KNOB SPLC 34.09 (4), 34.32 (3) Repair and maintain the door latch.-Repair or replace the damaged door knob
- 8. LOWER UNIT DOOR TRIM SPLC 34.09 (4), 34.32 (3) Repair and maintain the door frame.-Repair or replace the missing trim on door in kitchen area
- 9. LOWER UNIT ENTRY DOOR SPLC 34.33 (3) Repair and maintain the door in good condition.-Repair or replace the damaged door to lower unit, hole on exterior side and cracked
- 10. LOWER UNIT GAS CAN MSFC 313.1 Fueled equipment, including but not limited to motorcycles, mopeds, lawn-care equipment and portable cooking equipment, shall not be stored, operator or repaired within a building.-Remove the gas can from the back patio area
- 11. LOWER UNIT KITCHEN CABINET SPLC 34.10 (7) Repair and maintain the cabinets in an approved manner.-Repair or replace the damaged framing, where the dish washer was. Needs to be maintained
- 12. LOWER UNIT COVERS MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.-Provide covers to switches and panel box cover is missing
- 13. UPPER UNIT BEDROOM CARPET SPLC 34.10 (7), 34.17(5) Repair and maintain the floor in an approved manner.-Repair or replace the carpeting, that's missing in the upper bedrooom
- 14. UPPER UNIT CRACKS IN WALL SPLC 34.10 (7), 34.17 (5) Repair and maintain the walls in an approved manner.-Patch the holes and/or cracks in the walls, in the upper unit entrance and hallway area
- 15. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: Jonathan.Gaulke@ci.stpaul.mn.us or call me at 651-266-8994 between 7:30 - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Jonathan Gaulke Fire Inspector

Ref. # 124383