moke detectors(s) $\frac{M}{M}$	C(D	fice Use, ONLY; nte Recived.	
roperly located <u>M</u> Hard-Wired * M	St	. Paul Truth-In-Sale of (Carefully read this entire r	nousing	yment Ref.	
if N or H see note on p THIS REPORT USEFUL LIFE	S IS NOT A WARRANTY OR THE FUTURE CON	CATERINITY FRACTIONS ENTITY ANDITION OF ANY BUILDI icly displayed at the premises ovided to the buyer prior to th	AUL OR EVALUATO NG COMPONENT O	Page 1 of R OF THE FUTURE R FIXTURE.	
	valuated Dwelling: 1.	1464 MINNEH			
	2.				-64
Owner's Nam					Mi
Owner's Add		AHA AVE W			nne
Realtor/Cont	act:				hał
Current <u>Usage</u> of this dwelling:	Single Family	🔲 Townhouse 🛛 🗌 🤇	Condo* *For condominium only those located and does not inclu	units, this evaluation includes d within the residential units ude the common use area,	1464 Minnehaha Ave West
Comments:	Duplex usage may not be legal. See belo		or other residentia	al areas of the structure.	e We
		OSSIBLE RESTRICTI apply to this dwelling. This info	ON INFORMATI ormation is <u>not gua</u>	ON <u>ranteed</u> by the evaulator	St
	ormation provided to Truth	I-In-Sale of Housing Evaluato	ž ž	al Office this property:	
		itions applicable to a sale are differ g may <u>become</u> a vacant building befor		f this report	
		building and pay all outstan		-	
	e	y of Saint Paul is required	0	1 5	
-		ter/re-register the building, 2. rehab cost estimate from a liculation from the second second second second second second second second second s			e of
		ain a Certificate of Occupan			
* <u>NOTICE: A VI</u>	B status and / or category can o	change at any time. You must con	tact the City's Vacant Bui	ldings divison at	
<u>651-266-1900</u>) to be sure you are fully infor	med of all the conditions and requ	irements that may affect t	he sale of this property.	ч.
	(excluding painting), modificatio	District or it is individually designate ns, additions and demolition is require Heritage Preservation contact the City	ed by the Heritage Preservation	on Commission and city staff).	
		v) click on "Look Up Property Inform ents may apply. Call 651-266-9090 for			Date Viewed
for the most recent inf	formation. Research into a propert		Ũ		ă
5 1	2	isiting the DSI website, then enter the A Inspections, then click on "Lool	1 1 5		5/9/2011
the requirements of the requirements for	the Legislative Code; however, t or a hard-wired smoke detectors.	ne buyer and seller prior to the time his evaluation form will be used by the	e Fire Department to determi	ne it there is compliance with	011
Administration (F 3. is not warranted, b 4. covers only the item heating plant(except	HA) or Veterans Administration (by the City of St. Paul nor by the e is listed on the form and only those t during the heating season), use a	uator Guidelines and is based upon di VA) evaluator for the condition of the build e items <u>visible at the time of the evalu</u> ladder to observe the condition of the or the owner named on this report.	ling component, nor of the ac ation. The Evaluator is not re-	curacy of this report.	Page 1 of 4
Questions regarding Complaints regarding	this report should be directed to g this report should be directed	1	tions, Truth-in-Sale of Hou	ising Program,	of4
Phone No. (651) 266- Evaluator: Guy Bor		Dhone: (612 950 1662	5/0/201	1 Rev 3/2009	
	<u>,</u>	Phone: (612-859-4663	5/9/201	1 NOV 5/2009	

1464 MINNEHAHA AVE WEST

RATING"M" = Meets minimum"B" = Below minimum"C" = Comment"H" = Hazardous"Y" = Yes"N " = No"NV" = Not Visible/Viewed"NA" = Not ApplicableKEYWhere there are multiple rooms to a category. The Evaluator must specify the room to which a Comment is related.					
		(B) less than 6"8' headroom			
	2	(P) gracks			
BASEMENT/CELLAR	3	2 (B) cracks 3(B) scale and patching, loose dirt around porch			
	4	4 (y) past stains			
1. Stairs and Handrails	- D				
2. Basement/cellar floor	p	 (C)mostly covered (B) adjustable post in use, not welded or peened 			
 Foundation	$\frac{2}{Y}$				
5. First floor, floor system	C				
6. Beams and columns	В				
ELECTRICAL SERVICE(S) # of Services	1 8	(B) water meter missing grounding loop			
7. Service size:		9(B) no GFCI in basement bathroom, metal pull chain over bath			
Amps: 30 60 100 x 150 Other	200 ^{ta}	aucet			
Volts: 115 115/230 X					
8. Electrical service installation/grounding	B				
9. Electrical wiring, outlets and fixtures	<u> </u>	1 (D) and the type fittings on waste piece			
	!	1 (B) saddle type fittings on waste pipes (C) corrosion on joints,laundry s trap leaks			
PLUMBING SYSTEM		2 (B) No back flow protection on side faucet, no back flow on aundry tubs (C) plastic water pipes in use			
10. Floor drain(s) (basement)	1	3(C) kink in gas line on kitchen stove			
	$\frac{1}{BC}$ 1	6 (B) unvented bath and sinks			
11. Waste and vent piping (all floors)	BC				
12. Water piping (all floors)	B				
13. Gas piping (all floors)	M				
14. Water heater(s) installation	[1	7a(H) no backflow valve on water supply (B) off season ,heater shut off			
15. Water heater(s) venting		(H) corrosion on vent pipe, clearances from combustibles			
16. Plumbing fixtures.(basement)	<u> </u>				
HEATING SYSTEM(S) #.of	1				
17. Heating plant(s): Fuel: naturalgas Type: hot water		Garage heater18a(B) loose pipe and hangers			
a. Installation and visible condition	b	off season, heater shut off			
b. Viewed in operation (required in heating season)	· · · · ·	H) vent pipe rusted through, loose			
c. Combustion venting.	Н				
The Evaluator is not required to operate the heating plant(s) , ex during the heating season, between October 15 and April 15.	kcept				
18. Additional heating unit(s): Fuel: natural ga Type: for	ced air				
a. Installation and visible condition	В				
b. Viewed in operation	N				
c. Combustion venting	Н				
-	NONE	17. C Heating Plant/s Carbon Monoxide and Heat Exchanger are not tested.			
		Check with professionals in the field that meet your requirements.			

Evaluator: Guy Borglund

Property Addres	^{s:} 1464 MINNEHAH4	A AVE	F WEST		
RATING "M" = Me KEY	eets minimum "B" = Below minimum "C" = See Com	ment "H" = Ha	zardous "Y" = Yes "N " = No "NV" = Not Visible/Viewed "NA" = Not Applicable		
		ory. The Evaluator must specify the room to which a Comment is related.			
KITCHEN		М	Item # Comments		
	0. Walls and ceiling		21 (B) not covered with waterproof flooring		
	21. Floor condition and ceiling height				
	22. Evidence of dampness or staining23. Electrical outlets and fixtures				
		M MC	24 (C) extra faucet in kitchen, not working		
-	xtures				
		<u>M</u> C	26 (C) exhaust vent through wall, not hooked up, up stairs vent in		
	e/openable area/mechanical exhaust		kitchenet not working 27 (B) windows painted shut		
	f windows/doors/mech.exhaust	В	28(C) ceiling patched		
LIVING A	ND DINING ROOM(S)				
28. Walls and c	eiling	С			
29. Floor condit	tion and ceiling height	М	30 (y) ceiling patched		
	dampness or staining	Y	31 (B) minimual outlets		
	utlets and fixtures	В	33 (B) broken sash cords and top windows painted shut throughout		
32. Window siz	e and openable area	М			
	d door condition	В	34-35 patching and fresh paint throughout		
HALLWAY	YS, STAIRS AND ENTRIES				
	igs and floors	С	36 (B) front stairs handrail low		
		<u> </u>			
	dampness or staining	B			
	andrails to upper floors	<u>В</u> М			
	utlets and fixtures	M			
	d door condition				
	ctor(s)	<u>M</u> M	40 (B) walls tile buckling		
	cated				
*if N or H in a single	(HWSD)********************************	М	43 (B) GFCI(S) trip manualy, outlet with open ground		
BATHROC	OMS		44(B) Main floor bath, stool overflow s/b 1" lower than valve		
40. Walls and c	eiling	B			
41. Floor condit	tion and ceiling height	M			
	dampness or staining	N			
43. Electrical ou	utlets and fixtures	В			
44. Plumbing fi	xtures	В			
45. Water flow.	5. Water flow		48 (C) patching on walls and fresh paint		
46. Window siz	46. Window size/openable area/mechaical exhaust				
	f windows/doors/mech.exhaust	M			
		101	51 (B) closet lights lack protective covers 50 (B) sleeping rooms lack egrees size windows		
	G ROOM(S)	С			
	eiling	M			
	tion and ceiling height	M			
	dampness or staining	l			
	utlets and fixtures	В			
	e and openable area	В			
53. Window and	d door condition	М	58(C)covered with insulation and plastic		
ENCLOSED	PORCHES AND OTHER ROOMS		60(B) surface mounted wiring, extension cord light		
54. Walls ceilin	g and floor condition	NA			
55. Evidence of	dampness or staining	NA			
56. Electrical ou	utlets and fixtures	NA			
57. Window and	d door condition	NA			
ATTIC SPA	ACE (Visible Areas)	`			
	s and rafters	C			
59. Evidence of	dampness or staining	NA			
60. Electrical wiring/outlets/fixtures		B			
61. Ventilation.	-	Y			
62. ADDITIONAL COMMENTS(20 through 61)		NONE			
Evaluator:Guy Borgl	Lund CO Detector information reporated here	INDINE	5/9/2011 Rev 3/2009 Page 3 of 4		

Property Address: 1464 MINNEHAHA AVE WEST

RATING "M" = Meets minimum "	B " = Below	minimum "C" = Se	e Comment "H" = Hazardo	us "Y" = Yes	"N " = N o	"NV" = Not Visible/Viewed "N	A" = Not Apj	plicable
EXTERIOR (Visible	e Areas)			Item #			omment	ts
63. Foundation			В	63(B) miss	ing motar	and minor cracks		
64. Basement/cellar windo			B	64(B) miss	ing glazin	g, decay		
65. Drainage (grade)			B	65(B) low g		pots d, fresh paint		
66. Exterior walls			C	67(B) deca				
67. Doors (Frames/storms/			B			and decay on some tri	m and wir	ndows
68. Windows (frames/storr			B	69 (B) miss	sing steps	on west exit, low guard		
69. Open porches, stairway			B	70 (B) som	e decay o	on trim, fresh paint		
70. Cornice and trim			B					
70. Connec and thin			M					
71. Roof covering and cov 72. Gutters and downspout			NA	73(B) miss	ing motar	and metal flue liner no	t visible	
			B		0			
73. Chimneys 74. Outlets, fixtures and se			M					
						, rolled roofing , not app		
GARAGE(S)/ACCES						fire rated wall/ceiling c siding, no house num		aujustable
75. Roof structure and cov	-		B	77(B) crack			5013	
76. Wall structure and cove	-		B	78(B) non f				
77. Slab condition			B	79,(B) oper	ner not ho	ooked up		
78. Garage doors			B	80 (B) surfa	ace moun	ted wiring, Fuse box la	cks 'S' sa	ifety type
79. Garage opener(s)- (see			B	adapters/fuses, lights missing bulbs, main service wire low over garage with roof access			re low over	
80. Electrical wiring, outle			B	garage with		655		
81. ADDITIONAL COM	MENTS	63 through	80)					
FIREPLACE/WOOD	STOVI	E S #	1			proper clearance above		
82. Dampers installed in fin	replaces		Y			rst foot of chimney flue	above da	mper, could
-	-		В	not see ligh	nt to top			
84. Condition			С					
Nether items meet minimum INSULATION 85. Attic Insulation 86. Foundation Insulation	Y/N Y Y N	Type glass batts na	Inches/Depth					
			NA					
87. Kneewall Insulation	N	na	1					
88. Rim Joist Insulation	N	na	NA					
89. ADDITIONAL COM	MENTS	5 (82 through	88)					
I hereby certify that this report Guidelines, and I have utilized r diligence and I have noted all co minimum standards of mainten	easonable nditions	e and ordinary ca	re and					
Aug Byt-	.)	6	512-859-4663			5/9/2011		Page 4 of 4
Evaluator Signature		I	Phone Number			Date Viewed		•
Printed Name: Guy	Borglun	<u>d</u>						Rev 3/2009
 All single family residence in Sa located near sleeping rooms. For 2. Rainleaders connected to the s A house built before 1978 may h County Public Health, (651)266- Neither the City of Saint. Paul no 	more info anitary se ave lead p 1199. or the Eval	ormation call Fire F wer system must b paint on/in it. If chi uator is responsible	Prevention, (651) 266- e disconnected. For m ldren ingest lead paint e for the determination	9090. (Saint Pa fore information , they can be po n of the presenc	ul Legislati n call Public pisoned. For e of airborn	ve Code, Chapter 58) Works, Sewer Utility, 651- more information call Rame e particles such as asbestos,	266-6234 sey	
gases such as radon, or other com 5. If this building is used for any puy you determine legal uses under zo	rpose othe ning ordir	er than a single fam nance, contact the 2	nily dwelling, it may b Zoning Administrator	e illegally zone at (651) 266-90	d. To help 08.		1	1
6. An automatic garage door should	reverse u	pon striking an obi	ect. If it does not reve	rse, it poses a s	erious hazai	rd and should be repaired or	replaced im	mediately.