FCO 18.96

We need the following to process your appeal:

(if cash: receipt number #820.513

Attachments you may wish to include

Copy of the City-issued orders/letter being appealed



## APPLICATION FOR APPEAL

## Saint Paul City Council – Legislative Hearings

JUN 19 2018

CITY CLERK

\$25 filing fee (non-refundable) (payable to the City of Saint Paul) HEARING DATE & TIME

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

(provided by Legislative Hearing Office)

Tuesday, JUNE 26, 2018

This appeal form completed		Time	30
✓ Walk-In OR   ☐ Mail-In		Location of Hearing	
	□ Fax	Room 330 City Hal	l/Courthouse
for nontement orners only: \( \square \) Email \( \omega \) \( \text{N} \)	□ Fax		
Address Being Appealed:			•
Number & Street: 991 Galtier St.	City: <u>\$7</u>	Paul State:	MN Zip: 5547
Appellant/Applicant: Car Hon Linton  Phone Numbers: Business Res	Em	ail Carlon.li	ntonegmail, com
Signature: Land Simi		Date:	2/2018
Name of Owner (if other than Appellant):			
Mailing Address if Not Appellant's:			
Phone Numbers: Business Resi	idence	Cell	
What Is Being Appealed and Vacate Order/Condemnation/ Revocation of Fire C of O  Summary/Vehicle Abatement  Fire C of O Deficiency List/Correction  Code Enforcement Correction Notice  Vacant Building Registration  Other (Fence Variance, Code Compliance, etc.)			
			Revised 8/11/2014

Ricardo X. Cervantes, Director

SAINT PAUL

CITY OF SAINT PAUL

375 Jackson Street, Suite 220 St Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-9124 Web: www.stpaul.gov/dsi

June 13, 2018

CARLTON LINTON
P.O. BOX 40301
SAINT PAUL MN 55104-8301

# FIRE CERTIFICATE OF OCCUPANCY APPROVAL WITH CORRECTIONS

RE:

991 GALTIER ST

Ref. # 111163

Dear Property Representative:

Your building was inspected on June 12, 2018 for the renewal of the Fire Certificate of Occupancy and was approved. When the required fee has been paid you will receive your certificate. There are however seasonal or non-life safety deficiencies noted below which must be corrected prior to re-inspection. The following deficiencies must be corrected immediately.

## A reinspection will be made on July 9, 2018 at After 3:00 PM.

#### DEFICIENCY LIST

1. MSBC -Section 105.1 - Permits Required. Any owner or authorized agent who intends to construct, enlarge, alter, repair, move, demolish, or change the occupancy of a building or structure, or to erect, install, enlarge, alter, repair, remove, convert or replace any electrical, gas, mechanical or plumbing system, the installation of which is regulated by this code, or to cause any such work to be done, shall first make application to the building official and obtain the required permit. Work being done requires a permit.

A permit is required for the installation of the mini-boiler. There is no permit on file.

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

If you have any questions, email me at: Efrayn.Franquiz@ci.stpaul.mn.us or call me at 651-266-8955 between 7:30 a.m. - 9:30 a.m.

Sincerely,

Efrayn Franquiz Fire Inspector

Ref. # 111163



## CITY OF SAINT PAUL, MN

Christopher B. Coleman, Mayor

### DEPARTMENT OF SAFETY AND INSPECTIONS

Steve Magner, Manager of Code Enforcement Katie Larson, Truth- in- Sale of Housing Manager

375 Jackson Street, Suite 220 Saint Paul. MN 55101-1806 Phone: 651-266-8989 Fax: 651-266-1919 Web: www.stpaul.gov/dsi


## Truth- in- Sale of Housing Report

This is a visual disclosure report based on the current City of Saint Paul Truth-in-Sale of Housing Evaluator Guidelines and is valid for one year from the date of issuance and for the owner named.

Property Address: 991 GALTIER ST Date of Evaluation: Jul 18, 2017 Date of Expiration: Jul 18, 2018

This report is intended to provide basic information to the home buyer and seller prior to the time of sale.

This report WILL NOT be used to enforce the requirements of the Legislative Code; however, it will be used to determine if there is compliance with the requirements for sale within the City of Saint Paul, MN.



#### MAIOR NOTIFICATIONS AND WARNINGS

For questions on these items, call the City's Information and Complaint Line at 651-266-8989

- · Residential Type: Duplex
- Smoke Detectors:
  - · Smoke Detector Present: Y
  - · Smoke Detector Properly Located: Y
  - Smoke Detector Hard Wired (required in Single Family Homes): Y
  - · Smoke Detector Comments:
- · Open Permits:

This property has the following open permits:

B - 12 062094 - - Active/Issued

E - 14 313871 - \*\*You may also schedule an ins - Active/Issued

#### **HAZARDOUS**

#### Heating System(s)

· Installation and visible condition

#### **Plumbing System**

· Water and vent piping (all floors)

#### **BELOW MINIMUM**

#### Basement/Cellar

· Stairs and Handrails

#### Bathroom(s)

- · Condition of windows/doors/mechanical exhaust
- Walls and ceiling

#### **Exterior Space**

- · Doors (frames/storms/screens)
- · Windows (frames/storms/screens)

#### Garage(s)/Accessory Structure(s

- · Roof structure and covering
- · Wall structure and covering

#### Hallways, Stairs and Entries

· Stairs and handrails to upper floors

#### Kitchen

· Plumbing fixtures

#### Living and Dining Room(s)

· Floor condition and ceiling height

#### **Plumbing System**

- Gas piping (all floors)

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related)					
H: Hazardous Condition B: Below Minimum C: See Comments M: Meets Minimum					
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable		

#### CITY OF SAINT PAUL TRUTH- IN- SALE OF HOUSING REPORT

Address: 991 GALTIER ST

Date of Evaluation: Jul 18, 2017

Zoning District: RT1

Present Occupancy: R- Duplex

Number of Units Evaluated: Duplex

File Number: File#: 17-061118

Owner: Ranjani Perera

Client Name: Ranjani Parera Client Contact: 651-402-7412

Evaluator Name: Dave Kirwin The Kirwin Group

Evaluator Contact: Work: 612-991-1546

dikirwin@excite.com

Basement/Cellar

1. Stairs and Handrails

В

B - Steep stairway, uneven risers.

2. Basement/Cellar Floor

3. Foundation

М М Υ

4. Evidence of Dampness or

Staining

C - Evidence of water seepage

C - Indications of past or present dampness or staining (dampness, stains, efflorescence or decay)

C - Duplex: Both Units

5. First Floor, Floor System

6. Beams and Columns

М M

Electrical Services

7a. Number of Electrical Services 2

7b. Amps

100

7c. Volts

120-240

**Basement Only** 

8. Electrical service

М

installation/grounding

9. Electrical wiring, outlets and

fixtures

М

Plumbing System

10. Floor drain(s) (basement)

М Н

М

В

11. Water and vent piping (all

floors)

12. Water piping (all floors)

13. Gas piping (all floors)

H - No trap at the laundry stand pipe.

14. Water heater(s), installation М 15. Water heater(s), venting

16. Plumbing fixtures (basement)

M М

1

B - Improper flexible gas line - Lightweight gas appliance connector at the clothes dryer.

## Heating System(s)

The Evaluator is not required to operate the heating plant(s) except during the heating season, between October 15 and April 15.

17a. Number of Heating

Systems

17b. Type

Hot Water

991 GALTIER ST

Evaluator: Dave Kirwin The Kirwin Group

Jul 18, 2017 Page # 3

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related)					
H: Hazardous Condition B: Below Minimum C: See Comments M: Meets Minimum					
Y: Yes	N; No	NV: Not Visible	NA: Not Applicable		

Yes		N: No		NV: Not Visible	NA: Not Applicable
	17c. Fuel		Gas		
	18. Installation and condition	visible	H	H - Backflow preventer miss	sing at both boilers.
	19. Viewed in opera		N		
	(required in heating 20. Combustion ver		М		
	21a. Additional hea	ting unit(s):	Hot		
	Type	**	Water	•	
	21b. Additional hea Fuel		Electric		
	21c. Installation and condition	t visible	М		
	21d. Viewed in oper	ration	NA		
	21e. Combustion ve	enting	NA		
Kit	tchen				
	22. Walls and ceilin	a	М		
	23. Floor condition		M		
	height	_			
	24. Evidence of dan staining	ipness or	N		
	25. Electrical outlet	s and	M		
	fixtures 26. Plumbing fixtur	<b>A</b> ¢	В		
	20. Flambing fixtur	<b>C</b> 3	Ь	B - Unvented sink - S trap i	under the sink at the
				first floor kitchen.	
	27. Water flow		M		
	28. Window size/or area/mechanical ex		M		
	29. Condition of	Haust	М		
	doors/windows/me	chanical	1		
	exhaust				
Liv	ing and Dining R	oom(s)			
	30. Walls and ceilin	_	M		
	31. Floor condition	and ceiling	В		
	height			C - Floors are out- of- level C - Duplex: Both Units	
	32. Evidence of dam	npness or	N	C - Duplex. Both onits	
	staining		••		
	33. Electrical outlet fixtures	s and	M		
	34. Window size an	d openable	М		
	area 35. Window and do	or condition	М		•
Ц.		_	141		
П	allways, Stairs and		B.4		
	36. Walls, ceilings, 37. Evidence of dan		M		
	staining	iibiiess oi	N		
	38. Stairs and hand	rails to	В		
	upper floors			B - Stair(s) too narrow or st	eep at the front and
	39. Electrical outlet	s and	м	rear stairway.	
	fixtures	υ απα	IAI		
	40. Window and do	or conditions	М		

991 GALTIER ST

Jul 18, 2017 Page # 4

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related)					
H: Hazardous Condition B: Below Minimum C: See Comments M: Meets Minimum					
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable		
6 B	2				

#### Smoke Detectors

41a. Present	Υ
41b. Properly Located	Υ
41c. Hard-Wire	Υ

#### Bathroom(s)

42. Walls and ceiling **B** 

43. Floor condition and ceiling heiaht 44. Evidence of dampness or staining 45. Electrical outlets and fixtures 46. Plumbing fixtures М 47. Water flow М 48. Windows size/openable М area/mechnical exhaust 49. Condition of windows/doors/mechanical exhaust

B - Worn tilework at the tub surround at the first floor bathroom.

B - Worn wood window at the first floor bathroom.

## Sleeping Room(s)

50. Walls and ceilings	М
51. Floor condition, area and	M
ceiling height	
52. Evidence of dampness or	Ν
staining	
53. Electrical outlets and	М
fixtures	
54. Window size and openable	M
area	
55. Window and door condition	М

#### **Enclosed Porches and Other Rooms**

56. Walls, ceiling and floor	NA
condition 57. Evidence of dampness or	NA
staining 58. Electrical outlets and	NA
fixtures 59 Window and door condition	NΔ

### **Attic Space**

60. Roof boards and rafters	М
61. Evidence of dampness or	Ν
staining 62. Electrical wiring/outlets/fixtures 63. Ventilation	M Y

#### **Exterior Space**

64. Foundation	М
65. Basement/cellar windows	М

991 GALTIER ST Evaluator: Dave Kirwin The Kirwin Group

				<u>the room</u> to which a Comment is re
.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Below Minimu	m	C: See Comments	M: Meets Minimum
: Yes N	: No		NV: Not Visible	NA: Not Applicable
66. Drainage (grade)		М	line.	wall at the south property w surface water to drain
67. Exterior walls		М	array from banamy	
68. Doors		В		
(frames/storms/scree	ns)			ged door(s)/frame(s) - Worn door knob at the SW exterior
69. Windows		В		
(frames/storms/scree			B - Weathered window	ws.
70. Open porches, sta deck(s)		М		
71. Cornice and trim(s		М		
72. Roof structure and		M		
73. Gutters and down	spouts	M		
74. Chimney(s)		М		
75. Outlets, fixtures a entrance	ınd service	М		
Garage(s)/Accessory	Structure(:	5)		
76. Roof structure and	d covering	В	B - Worn wood framii	ng.
77. Wall structure and	l covering	В	B - Worn wood framii	ng.
78. Slab condition		M		
79. Garage door(s)		M		
80. Garage opener(s)		NA		
81. Electrical wiring, of fixtures	outlets and	NA		
Fireplace/Woodstove				
82. Number of Units		NA		
83. Dampers installed	i	NA		
84. Installation		NA		
85. Condition		NA		•
Insulation.				
86a. Attic Insulation:	Present	Υ		
86b. Attic Insulation:		Loose fiberglas		
86c. Attic Insulation:	Depth	s 3- 6 inches		
87a. Foundation Insul Present	lation:	NA		
87b. Foundation Insu Type	lation:	NA		
87c. Foundation Insul Depth		NA		
88a. Knee Wall Insula Present		NA		
88b. Knee Wall Insula		NA		
99c Vnoo Wall incula	tion. Donth	NIA -		

88c. Knee Wall Insulation: Depth NA

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related)					
H: Hazardous Condition B: Below Minimum C: See Comments M: Meets Minimum					
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable		

89a. Rim Joist Insulation:

NA

Present

89b. Rim Joist Insulation: Type

NA NA

89c. Rim Joist Insulation: Depth

NA

General

90. Carbon Monoxide Alarm

M

**General Comments** 

**Smoke Detectors** 

41a. Present

41b. Properly Located 41c. Hard-Wire

991 GALTIER ST Evaluator: Dave Kirwin The Kirwin Group

#### LEGAL NOTICES:

Chapter 189 of the Saint Paul Legislative Code requires all single family, duplex, condo, townhouse and co-op homes for sale in the city to have a Truth- in- Sale of Housing disclosure report prepared and available to prospective buyers. A Truth- in- Sale of Housing disclosure report must be done for Contract- For- Deed sales.

A Truth- in- Sale of Housing (TISH) Disclosure Report in the City of Saint Paul is intended to provide basic information to the home buyer and seller prior to the time of sale. Failure to obtain a Truth- in- Sale of Housing disclosure report or failure to make that disclosure report available to prospective buyers, is a violation of law and is punishable as a misdemeanor carrying up to 90 days in jail and/or a \$1,000.00 fine.

A valid Truth- in- Sale of Housing disclosure report must be conspicuously displayed at the premises for all prospective buyers. TISH disclosure reports are also available online: <a href="https://online.stpaul.gov/web/portal/public-search">https://online.stpaul.gov/web/portal/public-search</a>

- This report WILL NOT be used to enforce the requirements of the Legislative Code; however, this evaluation form will be used to determine if there is compliance with the requirements for a hardwired smoke detectors.
- This TISH report is based on the current Truth- in- Sale of Housing Evaluator Guidelines and is based upon different standards than the lender, Federal Housing Administration (FHA) or Veterans Administration (VA).
- This TISH is not warranted, by the City of Saint Paul nor by the evaluator for the condition of the building component, nor of the accuracy of this report.
- This TISH report covers only the items listed on the form and only those items visible at the time of the evaluation.
- The Evaluator is not required to operate the heating plant (except during the heating season), use a ladder to observe the condition of the roofing, disassemble items or evaluate inaccessible areas.
- This TISH report is valid for one year from the date of issue and only for the owner named on this report.
- If this building is used for any purpose other than a single family dwelling, it may be illegally zoned. To help you determine legal uses under the zoning ordinance, contact the Zoning Administrator at (651) 266-9008.
- Automatic garage doors should reverse upon striking an object. If it does not reverse, it poses a serious hazard and should be repaired or replaced immediately.
- All single family residences in Saint Paul must have at least one smoke detector connected to the electrical system (hard-wired). The detector must be located near sleeping rooms. For more information call Fire Prevention, (651)228-6230. (Saint Paul Legislative Code, Chapter 58.)
- Rainleaders connected to the sanitary sewer system must be disconnected. For more information call Public Works, Sewer Utility, and (651)266-6234.
- A house built before 1950 may have lead paint on/in it. If children ingest lead paint, they can be poisoned. For more information call Ramsey County Public Health, (651)292-6525.
- Neither the City of Saint Paul nor the Evaluator is responsible for the determination of the presence of airborne particles such as asbestos, noxious gases such as radon, or other conditions of air quality that may be present, nor the conditions which may cause the above.

Questions regarding this report should be directed to the evaluator. If you desire a reinspection and amended report, please contact your evaluator. They will perform a reinspection and file an amended report with the City of Saint Paul. The TISH evaluator may charge for this reinspection. Complaints regarding this report should be directed to Department of Safety and Inspections, Truth- in- Sale of Housing Program, Phone 651-266-8989.

#### **Evaluator Statement:**

I hereby certify I prepared this report in compliance with the Saint Paul Evaluator Guidelines, City of Saint Paul City Ordinance 189 and all other applicable policies and procedures of the Truth-in\_Sale of Housing Board. I have utilized reasonable and ordinary care and diliaence and I have noted all conditions found that do not conform to the minimum standards of maintenance. The report covers only those problems listed and reasonably visible at the time of my evaluation and does not warrent future useful life of any house component or fixture. I have included all required information pages with this report. Evaluator Name: Dave Kirwin The Kirwin Group

Phone: Work: 612-991-1546 Evaluation Date: Jul 18, 2017

991 GALTIER ST Page # 9 Evaluator: Dave Kirwin The Kirwin Group