

RLH FCO 18-65



APPLICATION FOR APPEAL

Saint Paul City Council – Legislative Hearings

RECEIVED

APR 26 2018

CITY CLERK

310 City Hall, 15 W. Kellogg Blvd.
Saint Paul, Minnesota 55102
Telephone: (651) 266-8585

We need the following to process your appeal:

- \$25 filing fee (non-refundable) (payable to the City of Saint Paul) (if cash: receipt number #10729)
 - Copy of the City-issued orders/letter being appealed
 - Attachments you may wish to include
 - This appeal form completed
 - Walk-In OR Mail-In
- for abatement orders only: Email OR Fax

HEARING DATE & TIME	
(provided by Legislative Hearing Office)	
Tuesday,	<u>MAY 1, 2018</u>
Time	<u>1:30</u>
Location of Hearing:	
<u>Room 330 City Hall/Courthouse</u>	

Address Being Appealed:

Number & Street: 132 Western Ave City: St. Paul State: MN Zip: 55102

Appellant/Applicant: LAVONNE LOUISMET Email: _____
Phone Numbers: Business _____ Residence _____ Cell Will Dahn 651-315-1738

Signature: Will Dahn Date: 4-26-2018

Name of Owner (if other than Appellant): NORMA LOUISMET / RO LAVONNE LOUISMET

Mailing Address if Not Appellant's: _____

Phone Numbers: Business _____ Residence _____ Cell _____

What Is Being Appealed and Why? Attachments Are Acceptable

- Vacate Order/Condemnation/Revocation of Fire C of O
 - Summary/Vehicle Abatement
 - Fire C of O Deficiency List/Correction
 - Code Enforcement Correction Notice
 - Vacant Building Registration
 - Other (Fence Variance, Code Compliance, etc.)
- Need more time to get loan to fix ROP



CITY OF SAINT PAUL

375 Jackson Street, Suite 220
St Paul, Minnesota 55101-1806

Telephone: 651-266-8989
Facsimile: 651-266-9124
Web: www.stpaul.gov/dsi

April 18, 2018

NORMA LOUISMET
C/O LAVONNE DEYO
132 WESTERN AVE S
ST PAUL MN 55102-2934

Revocation of Fire Certificate of Occupancy and Order to Vacate

RE: 132 WESTERN AVE S
Ref. # 124893

Dear Property Representative:

Your building was inspected on April 18, 2018, for the renewal of the Certificate of Occupancy. Since you have failed to comply with the applicable requirements, it has become necessary to revoke the Certificate of Occupancy in accordance with Section 40.06 of the Saint Paul Legislative Code.

A reinspection will be made on May 1st, 2018 or the property vacated.

The Saint Paul Legislative Code further provides that no building shall be occupied without a Certificate of Occupancy. Failure to immediately complete the following deficiency list or the building vacated may result in a criminal citation.

DEFICIENCY LIST

1. Class - SPLC 40.04 (5) - The owner of a building used for residential occupancy who is applying for their FIRST Fire Certificate of Occupancy, must complete the Department of Safety and Inspection Landlord 101 course, or other landlord training program approved by the Department of Safety and Inspections. The training must have occurred within the last two years and the owner must submit a certificate of attendance or provide verification of enrollment in the next scheduled class to the Fire Inspection Division-DSI. This requirement shall not apply to an owner who has held a Fire Certificate of Occupancy on another residential property in Saint Paul prior to April 30, 2009. For more information on Landlord 101, or to receive registration materials, please visit our webpage at: www.stpaul.gov/cofo Or, contact Fire Safety Inspector David Smith by email: david.smith@ci.stpaul.mn.us or phone: (651)266-8995-DSI created a course titled Landlord 101 for information on this see our website at <https://www.stpaul.gov/departments/safety-inspections/fire-inspections/landlord-101>. Owners have a full calendar year to complete either class.

2. Exterior - Back Door. - SPLC 34.09 (4), 34.32 (3) - Repair and maintain the door latch.- Replace missing door handle on back door.
3. Exterior - Front window - SPLC 34.09 (4), 34.33 (3) - Repair and maintain the window glass.-Provide glass and screens or storm windows for all windows.
4. Exterior - Garage - SPLC 34.08(5), 34.32(3) - All accessory structures including, but not limited to, detached garages, sheds and fences shall be maintained structurally sound and in good repair. Provide and maintain exterior unprotected surfaces painted or protected from the elements.-Repair roof, rotting wood and scrape and paint chipped and peeling areas.
5. Exterior - SPLC 34.33 (3) - Repair and maintain the door in good condition.-Repair or remove closer from front storm door.
6. Front Steps - SPLC 34.09 (3), 34.33(2) - Repair or replace the unsafe stairways, porch, decks or railings in an approved manner. This work may require a permit(s). Call DSI at (651) 266-8989.-Front steps to the public side walk are deteriorated. Please repair and maintain the front steps in an approved manner.
7. Interior - Basement - MMC 504.6 - Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter and installed in accordance with the mechanical code. This work will require a permit(s). Call DSI at (651) 266-8989.-**Have a licensed contractor pull a permit and provide a code compliant dryer vent. Current one is not vented to the exterior.**
8. Interior - Bathroom - SPLC 34.10 (7), 34.17 (5) - Repair or replace and maintain the woodwork in an approved manner.-Repair or replace door with several holes.
9. Interior - Living Room - MSFC 605.6 - Provide electrical cover plates to all outlets, switches and junction boxes where missing.
10. Interior - Throughout - MSFC 605.5 - Discontinue use of extension cords used in lieu of permanent wiring.
11. Interior - Throughout - MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.
12. Interior - Throughout - MN Stat. 299F.362 - Immediately provide and maintain a smoke detector located outside each sleeping area.-Repair disabled and non-working smoke detectors.
13. Interior - Throughout - SPLC 34.10 (6), 34.34 (5) - Exterminate and control insects, rodents or other pests. Provide documentation of extermination.
14. Interior - SPLC 34.33 (3) - Repair and maintain the door in good condition.-Replace door on bedroom.

15. Interior - MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
16. SPLC 39.02(c) - Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: <http://www.stpaul.gov/cofo>

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: daniel.klein@ci.stpaul.mn.us or call me at 651-266-8988 between 7:30 - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Daniel Klein
Fire Inspector

Ref. # 124893