RLH FCO 18-188



APPLICATION FOR APPEAL

Saint Paul City Council - Legislative Hearings

RECEIVED OCT 22 2018

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

We need the following to process your	appeal: CITY CLER	RK
S25 filing fee payable to the City of (if cash: receipt number ** Y Copy of the City-issued orders/lett Attachments you may wish to include This appeal form completed Walk-In OR Mail-In for abatement orders only: Email: Em	of Saint Paul	HEARING DATE & TIME (provided by Legislative Hearing Office) Tuesday, NOV. 6, 2018 Time 1-30 Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appea	led:	
Number & Street: 869 Al	semant City:	57P State: MN Zip: 55117
Appellant/Applicant: Dak Wok		nail rockbegone omso, com
Phone Numbers Signature:		Cell (651-274-3887) Date: 10-17-18
Name of Owner (if other than Appellant): Mailing Address if Not Appellant's:		
Phone Numbers: Business	Residence	Cell
What Is Being Appeale	ed and Why?	Attachments Are Acceptable
Vacate Order/Condemnation/ Revocation of Fire C of O		
Summary/Vehicle Abatement		
Fire C of O Deficiency List		
□ Code Enforcement Correction Notice	Ref # 108056	Received pertinate of occopancy
□ Vacant Building Registration □ Other -	, , , , , , ,	(noork has been completed Satisfactor) Revised 5/31/2013.

Ricardo X. Cervantes, Director

SAINT PAUL

CITY OF SAINT PAUL

375 Jackson Street, Suite 220 St Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-9124 Web: www.stpaul.gov/dsi

October 10, 2018

Dale Wobbe 1112 Selby Ave St Paul Park MN 55071-1341

CORRECTION NOTICE - RE-INSPECTION COMPLAINT

RE:

869 ALBEMARLE ST

Ref. # 108056

Dear Property Representative:

A re-inspection was made on your building on October 9, 2018, in response to a complaint. You are hereby notified that the following deficiencies must be corrected prior to re-inspection date.

A reinspection will be made on November 1, 2018 at 1:45 PM.

Failure to comply may result in a criminal citation or the revocation of the Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

DEFICIENCY LIST

- 1. Exterior Back Stairs SPLC 34.09 (3), 34.33(2) Repair or replace the unsafe stairways, porch, decks or railings in an approved manner. This work may require a permit(s). Call DSI at (651) 266-8989. The back stairs are in disrepair. Repair and bring the stairs up to code.
- 2. Exterior Back of Property SPLC 34.08(5), 34.32(3) All accessory structures including, but not limited to, detached garages, sheds and fences shall be maintained structurally sound and in good repair. Provide and maintain exterior unprotected surfaces painted or protected from the elements. -The fence is in disrepair.
- 3. Exterior Back of Property SPLC 34.08 (10) Repair, replace and maintain exterior sidewalks, walkways and stairs. -The sidewalk at this property is in disrepair.

- 4. Exterior Parking Surface SPLC 34.08 (7) All parking spaces shall be paved with asphalt, concrete, or durable dustless surfacing. Before any existing spaces may be paved, site plan approval must be obtained as specified in the St. Paul Zoning Code. Contact DSI Zoning at 651-266-8989. The parking surface is in disrepair.
- 5. Unit 1 Bathroom SPLC 34.10 (4), 34.34 (3) Provide a bathroom floor impervious to water. -In between the bath tub and vanity cabinet there is an opening in the floor and the wall is not complete.
- 6. Unit 1 Bathroom SPLC 34.14 (2) c Repair or replace the duplex convenience outlet with ground fault protection within 3 feet of the basin on an adjacent wall in all bathrooms. This work may require a permit(s). Call DSI at (651) 266-8989.-The GFCI outlet in the bathroom has been painted over and the buttons are jammed.
- 7. Unit 1 Door SPLC 34.33 (3) Repair and maintain the door in good condition. -The bedroom door does not fit properly within its frame. The door must close tighter.
- 8. Unit 1 Front Room MSFC 1014.2 Egress through intervening spaces. Egress through intervening spaces shall comply with this section. 3. Means of Egress from *dwelling unit or sleeping areas* shall not lead through other sleeping areas, toilet rooms or bathrooms. The very front room is not a legal bedroom.
- 9. Unit 1 Light Fixture MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-8989.-The light fixture near the front entry door does not work.
- 10. Unit 1 Throughout MSFC 605.4 Discontinue use of all multi-plug adapters. -
- 11. Unit 1 Windows SPLC 34.09 (4), 34.33 (3) Repair and maintain the window in good condition. -The kitchen windows are not properly installed and have improperly installed insulation.
- 12. Unit 1 Small Bedroom MSFC 1030.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exit path. -The bed is preventing the bedroom door from fully opening.
- 13. Unit 1 Smoke Alarm MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area. -A smoke alarm is required in the small bedroom.
- 14. SPLC 34.19 Provide access to the inspector to all areas of the building.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: 651-266-8585 and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at Efrayn.Franquiz@ci.stpaul.mn.us or call me at 651-266-8955 between 7:30 a.m. - 9:00 a.m.

Please help to make Saint Paul a safer city in which to live and work.

Sincerely,

Efrayn Franquiz
Fire Inspector

Ref. # 108056