



CITY OF SAINT PAUL

375 Jackson Street, Suite 220
Saint Paul, Minnesota 55101-1806

Telephone: 651-266-8989
Facsimile: 651-266-8951
Web: www.stpaul.gov/dsi

November 9, 2018

CORRIDOR PROPERTIES LLC
1343 THOMAS AVENUE
SAINT PAUL MN 55104

FIRE INSPECTION CORRECTION NOTICE

RE: 926 ARMSTRONG AVE
Ref. #120320
Residential Class: B

Dear Property Representative:

Your building was inspected on October 3, 2018 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on May 1, 2019 at 3:15 PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional re-inspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

1. Exterior - Chimney - MSFC 603.6 - Have the chimneys, fireplaces, and vents inspected for soundness, freedom from deposits, and correct clearances. Cleaning, maintenance, and repairs shall be done if indicated by the inspection. -The chimney has openings and missing mortar. The chimney also has a slight lean towards the house.
2. Exterior - Doors - SPLC 34.33 (3) - Repair and maintain the door in good condition. The back-entry door does not fit properly within it frame and the garage door is damaged. The screen doors are missing the door closer and one of them has a broken latch.

3. Exterior - Garage - SPLC 34.08(5), 34.32(3) - All accessory structures including, but not limited to, detached garages, sheds and fences shall be maintained structurally sound and in good repair. Provide and maintain exterior unprotected surfaces painted or protected from the elements.
Inside the garage there is a section of the wall and roofing that is rotted and damaged. The garage floor has some very large and deep cracks.
4. Exterior - Window Screens - SPLC 34.09 (4), 34.33 (3) -Provide or repair and maintain the window screen.
5. Exterior - Interior - Throughout - MSFC 605.6 - Provide electrical cover plates to all outlets, switches and junction boxes where missing.
6. Exterior - Interior - Throughout - MSFC 605.4 - Discontinue use of all multi-plug adapters.
7. Interior - Basement - MFGC 503 - Provide, repair or replace the fuel equipment vent or vent liner to develop a positive flow adequate to convey all products of combustion to the outside. This work may require a permit(s). Call DSI at (651) 266-8989.-There is a large crack and hole on the wall near the exhaust duct. Properly seal the cracks and openings.
8. Interior - Ceiling - SPLC 34.10 (7), 34.17 (5) - Repair and maintain the ceiling in an approved manner. -The living room ceiling is sagging and has openings in it.
9. Interior - Floor - SPLC 34.10 (7), 34.17(5) - Repair and maintain the floor in an approved manner. -The tiles floor is cracked, damaged and missing tiles.
10. Interior - Kitchen - SPLC 34.14 (2) c - Repair or replace the duplex convenience outlet with ground fault protection within 3 feet of the basin on an adjacent wall in all bathrooms. This work may require a permit(s). Call DSI at (651) 266-8989.-The kitchen GFCI outlet does not trip when tested.
11. Interior - Kitchen - MMC 504.6 - Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter and installed in accordance with the mechanical code. This work may require a permit(s). Call DSI at (651) 266-8989.-The bottom section of the exhaust duct has screws on it.

12. MSBC -Section 105.1 - Permits Required. Any owner or authorized agent who intends to construct, enlarge, alter, repair, move, demolish, or change the occupancy of a building or structure, or to erect, install, enlarge, alter, repair, remove, convert or replace any electrical, gas, mechanical or plumbing system, the installation of which is regulated by this code, or to cause any such work to be done, shall first make application to the building official and obtain the required permit. Work being done requires a permit. -A permit is required for the construction of the new deck and stairs at the front of the house.
13. **SPLC 40.06 - Uncertified portions of the building must not be occupied until inspected and approved by this office. -Contact Inspector Efrayn Franquiz at 651-266-8955 when the permits have been final and the work has been completed. The house and the garage cannot be rented out.**

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: <http://www.stpaul.gov/cofo>

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: Efrayn.Franquiz@ci.stpaul.mn.us or call me at 651-266-8955 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Efrayn Franquiz
Fire Inspector

Reference Number 120320