

MINNESOTA HISTORIC PRESERVATION OFFICE

May 11, 2017

Samantha Langer City of St. Paul – PED 1400 City Hall Annex 25 W 4th Street Saint Paul, MN 55102

RE:

Demolition of 412 Goodrich Avenue

St. Paul, Ramsey County SHPO Number: 2017-1698

Dear Ms. Langer:

Thank you for the opportunity to comment on the above project. It has been reviewed pursuant to the responsibilities given the State Historic Preservation Officer by Section 106 of the National Historic Preservation Act of 1966 and implementing federal regulations at 36 CFR 800.

Based on available information, we conclude that **no properties** listed in or eligible for listing in the National Register of Historic Places will be affected by this project.

Please contact our Compliance Section at (651) 259-3455 if you have any questions regarding our review of this project.

Sincerely,

Sarang. Banwa

Sarah J. Beimers, Manager Government Programs and Compliance

cc: Inventory File RA-SPC-1548



Saint Paul Department of Planning and Economic Development Historic Review Form

Please type or pri	nt legibly. (Illegible form	ns will be returned.)			
Project Address: 412 GOODRICH AVE		Original Construction Year: ca. 1890			
Building Name: house		Planning District Number: 9			
Brief Project Description: Der	nolish house				
· · · · · · · · · · · · · · · · · · ·					
Funding: CDBG x NSP	II Other Funding (1	ist)	Production and the second seco		
Form Completed by: Matt	Dornfeld	Date:	March 24, 2017		
Title/Organization:		Phone no:	651-266-1902		
Revie	ews will not be processed w • Photo of buildi • Map clearly showing	ng attached below	•		
Completed review will be ret Form submitted by: City of Sa		conomic Developme	nt (PED)		
Contact Person: Bill Derm	Bill Dermody, City Planner (651-266-6617)				
Street Address: 1400 City	ess: 1400 City Hall Annex, 25 W. Fourth St., Saint Paul, MN 55102				
Please complete Historic Review Fourth Street, Saint Paul, MN 551		send to Samantha Lang	ger, 1400 City Hall Annex, 25 W.		
To be completed by authorized PI Name: SAMMINA W Date: 3 28 17 Located within a Saint Paul Histor Located within a National Register Has the property been inventoried If yes, #RA-SPC- 1548	ric District? Yes No	1850-1869 recommende	s: Constructed 5. In 2011, was ded for intensive- ey, in order to historic designation attached.)		

St. Paul Heritage Preservation Commission - Building Inventory Form

Droporty and	Owner Information	
Historic Name	John Lewis House	PIN: 012823340008
Common Name	John Lewis House	State Inventory # RA-SPC-1548
Other Name	DOM LOWIS Floude	Report Number: RA-81-2H
Street Number:	412 Street GOODRICH AVE	Property RSN: 106608
Neighborhood:	West 7th Street Zip	Ward: 2 District: 9
•	JUANA G ARELLANO	County Ramsey Public - Local Ownership
Current Owner	412 GOODRICH ÄVE	Zoning: RT2 Public - State Ownership
Address	ST PAUL MN 55102-2909	✓ Private Ownership Public - Federal Ownership
City/State/Zip	51 FAOL MIN 35102-2-909	F I Treate Ownership
Locational Inf	ormation	
ZONE 15	E 490739 N 4976023	Quad Saint Paul East
Blk	Lot(s)	TWP 28 RG 23 Sec. 1
Addition		Quarter/Quarters SE SW
Survey/Photog	graphy Information	
		Z4
		Surveyor(s) Mead & Hunt
		Survey Date 05/10/2011 Survey Level Reconnaissance
		Updated Survey? ■ Building ■ Publicly ■ Accessible? ■
		Photographer Mead & Hunt
		Photo Date 5/10/2011
		Frame 6702 Facing SW Frame Facing
		Frame 6703 Facing SE Frame Facing
		Frame Facing Frame Facing
		Frame Facing Frame Facing
	Total Control of the	Neter
		Notes:
0::		
Property Category:	and Nomination Information : Building	Property Type:
Period of Significat		Level of Significance: L L=Local; S=State; N=National
Local Status	NRHP Status	NUI Date Entered
Entered Date:	Date Entered:	Date Removed:
Eligible Date:	Date Entered:	processor and the second secon
Not Eligible Date	Date Entered:	NRHP District Nam
Removed Date:	Date Entered:	Local District Name:
Significant Person	And the state of t	© Contributing Noncontributing
Local Criterion:	Its character, interest, or value as part of the	Cultural Affiliation
	development, heritage, or cultural characteristics of the City of Saint Paul, State of Minnesota, or the United States.	
	O INCO O O O O O O O O O O O O O O O O O O	State Context: Urban Centers 1870-1940
Local Contexts:	Pioneer Houses: 1854-1880	
Note on Significance:		
Threats:		
Consultant Recommendation:	This property has been identified as having been con residences in Saint Paul. As a result, this property is and/or National Register designation.	structed from 1850 through 1865 and is one of the earliest constructed recommended for intensive-level research to determine eligibility for local

St. Paul Heritage Preservation Commission - Building Inventory Form

State Inventory #	: RA-SPC-1548	Street Number: 412	Street: GOODRICH A	VE
Building Infor	mation/Historical	Background		
Architect/Enginee	r:		Other Designer	
Builder/Contracto	,		Landscape Architect:	
Biographical Info:			, , , , , , , , , , , , , , , , , , , ,	
Original Owner:			Other Owners and	
Original Function/	Use: Domestic, Single	Dwelling	Biographies:	
Other Functions/L	lses:		Current Function/Use:	Domestic, Single Dwelling
Property Date:	1860 Da	ate Source Key RCT	. '	Date Event: ✓ Construction ☐ Demolition
Date:				Addition Move Alteration
Oral Histories:			Sanborn/Atlas Info:	
Bldg. Permit Info:		properties constructed	City Directory Info:	
Location of Architectural Drawings:			Historical Photos:	
Other Sources:	1992 survey; 1983	survey		
Historical Background:	Constructed in 1850	5 per 1992 survey		
Architectural I	nformation	•		
Style: Greek R	and and	Primary	Secondary Element	Stories: 1 Bays: 1
***************************************	evivai		Secondary Element	Plan Shape: Rectangular
			Secondary Element	Roof Shape: Gable
Materials	***************************************		Integrity	
Structure:	Wood Frame	·	Material Condition:	· : Good
Foundation:	Poured Concrete		– Design Integrity:	Poor
Wall (Primary):	Vinyl/Aluminum		Alterations	windows, siding, elevated with basement
Wall (Secondary	\.			added, new vestibule
Roofing	Asphalt Shingles		Original Site?	j
Dormer Style(s):	None	Number:	0 Lo	cations(s)
Chimney Style(s)	None	Material(s):	Lo	cations(s):
Window Type	Double-hung		Window Condition	Windows replaced/openings intact
Site Features			Surrounding Land U	se Residential
Outbuildings			Integrity of Setting:	Good
Site Features			Importance of Setting	g: Somewhat Important
	a side gable roof and h		Γhe house has had window re	it an early house for the area. The house has placements, siding replacement, and the
Notes on Interior:	mentendrumguntunguntungkan kemanjun sebahan mentendruk kan lang antak ayan paga pagangan pagangan pagangan pag		TO PARAMETERS AND A THE ANGEST AND A SECURITY AND A	
General Property Notes:				