


## **PIG'S EYE SITE**

We continue to use this site, and to work with St. Paul Parks and Recreation to obtain a larger site for long-term use.



#### **HYDRO-SEEDING**

We have completed the hydroseeding (May 31). The grass is taking root in those areas and appears to be healthy.



# **MATERIAL RE-USE**

We continue to haul material to a company for re-use, which further reduces the number of trips to Sandy Lake.



### **HAULING**

We have reduced our hauling. Compared to our peak average last year of 38-56 trips a day, our current average is 3.5 trips a day from May 11 to June 14.



#### **CAMERA INSTALLATION**

We are installing two cameras on the site to monitor the site entrance and recycling area. The cameras will be mounted on a wooden pole on the northeast corner of the site.

The pole is up and the fiber-optic cables along the southern side of the site have been installed. We will be mounting the cameras and pulling the cable to complete the project.

# **HAULING TRIPS**

Weekly Trips to Sandy Lake







