

Vang, Mai (CI-StPaul)

From: Martin, Lisa (CI-StPaul)
Sent: Monday, October 7, 2019 6:37 AM
To: Moermond, Marcia (CI-StPaul); Vang, Mai (CI-StPaul)
Subject: 1122 Jackson Street

We met the owner at the property to verify the boiler has been disconnected and the electric has been disconnected to the greenhouse.

Thanks!



Lisa Martin, CFI

Code Enforcement Supervisor

Pronouns: She/her

Department of Safety & Inspections (DSI)

375 Jackson Street, Suite 220

Saint Paul, MN 55101

P: 651-266-1940

F: 651-266-1919

Lisa.Martin@ci.stpaul.mn.us



The Most Livable
City in America

General Information & Complaints 651-266-8989

*Mission: To preserve and improve the quality of
Life in Saint Paul by protecting and promoting
Public health and safety for all.*