Ricardo X. Cervantes, Director



CITY OF SAINT PAUL

375 Jackson Street, Suite 220 Saint Paul, MN 55101-1806

Telephone: 651-266-8989 Facsimile: 651-266-9124 www.stpaul.gov/dsi

Code Compliance Report

September 24, 2018

* * This Report must be Posted on the Job Site * *

3PACKET.COM INC 3111 W POLK AVE ANAHEIM CA 92801

Re: 1802 Ross Ave File#: 10 799492 VB2

Dear Property Owner:

The following is the Code Compliance report you requested on September 04, 2018.

Please be advised that this report is accurate and correct as of the date September 24, 2018. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from September 24, 2018. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected. A Legislative Code exemption (Chapter 33.03(f)) allows a Category 2 Vacant Building to be sold "as is" providing the buyer, prior to closing, completes an approval process. For further information, call Reid Soley at 651-266-9120.

ZONING

- 1. This property is in a(n) R4 zoning district.
- 2. This property was inspected as a Single Family Dwelling.

BUILDING Inspector: Jim Seeger Phone: 651-266-9046

- 1. Dry out basement and eliminate source of moisture. SPLC 34.10 (10)
- 2. Provide major clean-up of premises. SPLC 34.34 (4)
- 3. Repair siding, soffit, fascia, trim, etc. as necessary. SPLC 34.09 (1)
- 4. Provide proper drainage around house to direct water away from foundation of house. SPLC 34.08 (2)

- 5. Provide proper drainage around house to direct water away from foundation of garage. SPLC 34.08 (2)
- 6. Install flashing in an approved manner at the intersection of the roof with walls, chimneys, and other conjoined surfaces. SPLC 34.09 (1)
- 7. Install address numbers visible from street and on the alley side of garage. SPLC 70.01
- 8. Provide ground cover capable of controlling sediment and erosion. SPLC 34.08 (3)
- 9. Grade must drain away from foundation of dwelling. Maintain 6 inch clearance between wood and soil. MNRC Ch 1309-Sect. 404.1.6
- 10. Rebuild front foundation for porch to code and replace all decayed or damaged framing. re-level porch.
- 11. Remove illegal basement bedrooms or install egress windows.
- 12. Remove mold, mildew and moldy or water damaged materials. SPLC 34.10 (1)
- 13. Replace west side entry door and rear patio door.
- 14. Replace house roof covering to code.
- 15. Install safety cables on overhead garage door,
- 16. 2nd. floor front bedroom, replace ceiling with inspections.
- 17. Repair hole in garage roof where chimney pipe was.
- 18. Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary. SPLC 34.09 (3)
- 19. Provide complete storms and screens, in good repair for all door and window openings. SPLC 34.09 (3e)
- 20. Repair or replace damaged doors and frames as necessary, including storm doors. SPLC 34.09 (3f)
- 21. Install floor covering in bathroom and kitchen that is impervious to water. SPLC 34.10 (4)
- 22. Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present. SPLC 34.33 (1)
- 23. Where wall and ceiling covering is removed install full thickness or codespecified insulation. MN Energy Code Ch. 1322.1101 (exept. 4)
- 24. Install Smoke Detectors/Carbon Monoxide Detectors per MN Conservation Code and the MN Dept. of Labor and Industry: Install per code where feasible. MNRC Ch 1309 Sect 313.2.1
- 25. A building permit is required to correct the above deficiencies. All work is to be done in a workmanship like manner. SPLC 33.03 (a)

ELECTRICAL Inspector: Gary Koehnen Phone: 651-266-9039

- 1. No power at time of inspection. Test all electrical outlets and ensure all luminaires (light fixtures) are working properly when power is restored.
- 2. Install hard-wired, battery backup, Carbon Monoxide smoke detector as specified in Chapter 58 of the Saint Paul Legislative Code, and other smoke detectors and carbon monoxide detectors as required by the Minnesota State

Building Code. SPLC 58, IRC

- 3. Properly support/wire exterior luminaire (light fixture) at entry door. Articles 110.3 (B), 314.20, NEC
- 4. Install correct feedr to garage and verify all wiring in garage is safe. Article 400.8, NEC
- 5. Remove and/or rewire all illegal, improper or hazardous wiring to current NEC.
- 6. Cables, smaller than 8 AWG, run at angles on the bottom of joists in unfinished basements, shall be run in either bored holes in joists or on running boards. Article 334.15 (C), current NEC
- 7. Replace electrical service mast/meter socket due to excessive corrosion. Article 110.12 (B), NEC
- 8. Properly wire furnace to current NEC.
- 9. Repair the electrical service grounding conductor to the metallic water piping system. Install a conductor sized to Table 250.66 (NEC) from the electrical service to within 5' of the entrance point of the water service, and bond around the water meter. Article 250, NEC
- 10. Provide a complete circuit directory at service panel indicating location and use of all circuits. Article 408.4, NEC
- 11. Close openings in service panel/junction boxes with knockout seals, breaker blanks, proper cable clamps, and/or junction box covers. Article 110.12 (A), NEC
- 12. Properly strap and support cables and/or conduits. Including all low voltage on exterior. Chapter 3, NEC
- 13. Remove all cord wiring used as a substitute for fixed wiring. Article 400.8, NEC
- 14. Repair or replace all broken, painted over, corroded, missing or loose receptacles, luminaires (light fixtures), switches, covers and plates to current code. Article 406.4(D) & Article 410, NEC
- 15. Check all receptacles for proper polarity (including 2-prong) and verify ground on 3-prong receptacles. Ensure all GFCI receptacles are functioning properly. Rewire and/or replace receptacles that are improperly wired or not functioning properly. Article 406.4(D), NEC
- 16. Install box extensions on devices mounted in wood paneling. Article 314.20, NEC
- 17. All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

PLUMBING Inspector: Steve Fernlund Phone: 651-266-9052

- 1. Basement -Gas Piping -(MFGC 614.1-614.7) Vent clothes dryer to code.
- 2. Basement -Gas Piping -(MFGC 411) Install an approved shut off; connector and gas piping for the dryer.
- 3. Basement -Laundry Tub (MPC 701) Install the waste piping to code.
- 4. Basement -Laundry Tub -(MPC .0100 & 901) Install a proper fixture vent to code.
- 5. Basement -Lavatory (MPC .0100 E & 901) Install a proper fixture vent to code.
- 6. Basement -Lavatory (MPC 701) Install the waste piping to code.

- 7. Basement -Soil and Waste Piping -(MPC 707.4) Install a clean out at the upper terminal at each horizontal drainage pipe.
- 8. Basement -Soil and Waste Piping -(MPC 704 & 706) Replace all improper connections, transitions, fittings or pipe usage.
- 9. Basement -Toilet Facilities -(MPC .0100 E & 901) Install a proper fixture vent to code.
- 10. Basement -Toilet Facilities -(MPC 701) Install the waste piping to code.
- 11. Basement -Tub and Shower -(MPC .0100 E & 901)Install a proper fixture vent to code.
- 12. Basement Tub and Shower (MPC 701) Install the waste piping to code.
- 13. Basement -Water Heater -(MFGC 409) Install the gas shut off and the gas piping to code.
- 14. Basement -Water Heater (MFGC 503) Install the water heater gas venting to code.
- 15. Basement -Water Heater (MMC 701) Provide adequate combustion air for the gas burning appliance.
- 16. Basement -Water Heater -(MFGC 501.12) The water heater venting requires a chimney liner.
- 17. Basement -Water Heater -(MPC .0100 Q)The water heater must be fired and in service.
- 18. Basement -Water Meter -(MPC 609.11 & SPRWS Sec.88.14) The water meter must be installed and in service.
- 19. Basement -Water Piping -(SPRWS 93.07) Provide a one (1) inch water line to the first major take off.
- 20. Exterior -Lawn Hydrants -(MPC 603.5.7) The lawn hydrant(s) require a backflow preventer.
- 21. First Floor -Sink -(MPC .0100 E & 901) Install a proper fixture vent to code.
- 22. First Floor -Sink -(MPC 701) Install the waste piping to code.
- 23. Second Floor -Toilet Facilities (MPC 301.1) Repair/replace the fixture that is missing, broken or has parts missing.
- 24. Second Floor -Tub and Shower -(MPC 401.1 & 409.2) Replace the waste and overflow.
- 25. All the above corrections to waste, vent, water, and gas piping shall be per the Minnesota Plumbing Code Chapter 4714, Minnesota Rules Chapter 326, 4716, 1300, the Minnesota Mechanical Code, the Minnesota Fuel Gas Code, and Saint Paul Regional Water Services Water Code. All plumbing must be done by a plumbing contractor licensed in the State of Minnesota and the City of St. Paul by a plumber licensed in the State of Minnesota who also possess a City of Saint Paul Competency Card and after obtaining an approved City of Saint Paul Plumbing Permit.

Heating Inspector: Aaron Havlicek Phone: 651-266-9043

- 1. Install approved lever handle manual gas shutoff valve on furnace/boiler and remove unapproved valve.
- 2. Install approved automatic gas valve for furnace/boiler.

- 3. Clean and Orsat test furnace/boiler burner. Check all controls for proper operation. Check furnace heat exchanger for leak; provide documentation from a licensed contractor that the heating unit is safe.
- 4. Move return air intake a minimum of ten (10) feet from furnace flue draft diverter or relocate it to another room.
- 5. Install approved metal chimney liner.
- 6. Replace furnace/boiler flue venting to code.
- 7. Connect furnace/boiler and water heater venting into chimney liner.
- 8. Provide adequate clearance from flue vent pipe on furnace/boiler to combustible materials or provide approved shielding according to code.
- 9. Vent clothes dryer to code and provide approved gas piping and valve (plumbing or mechanical gas permit is required).
- 10. Provide adequate combustion air and support duct to code.
- 11. Provide support for gas lines to code.
- 12. Plug, cap and/or remove all disconnected gas lines, non-conforming gas lines and unapproved valves.
- 13. Bathrooms require a means to ventilate the space. Provide a window with an aggregate glazing area of not less than 3 square feet, one half of which must be operable. Alternative is a bath fan properly vented to the outside. All kitchen exhaust must be venting to exterior. A mechanical ventilation permit will be required for the bath fan and/or kitchen exhaust.
- 14. Provide all supply and return ducts for warm air heating system must be clean before final approval for occupancy. Documentation is required from a licensed duct-cleaning contractor that the duct system has been cleaned.
- 15. Repair and/or replace heating registers as necessary.
- 16. Provide heat in every habitable room and bathrooms.
- 17. Provide a means of returning air from every habitable room to the furnace. Return air can not be taken from closets, bathrooms, toilet rooms, kitchen or mechanical rooms.
- 18. Submit documentation verifying that A/C system is operable, if not, repair, replace or remove and seal all openings.
- 19. Unable to gain entry to garage during inspection, however chimney vent is visible through the roof. If there is any nonconforming heating equipment in the garage, remove it and all connecting piping and venting and permanently seal and plug all openings or install equipment to code.
- 20. Mechanical permits are required for the above work.

Notes:

- 1. See attachment for permit requirements and appeals procedure.
- 2. Provide plans and specifications for any portion of the building that is to be rebuilt.
- 3. There was considerable storage/clutter within property at the time of the inspection. Property is to meet appropriate codes when complete.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected in accordance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34) and all required permits must receive final approval within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Jim Seeger between 7:30 - 9:00 AM at 651-266-9046 or leave a voice mail message.

Sincerely,

James L. Seeger
Code Compliance Officer
Department of Safety and Inspections
City of Saint Paul
375 Jackson Street, Suite 220
Saint Paul MN 55101

Phone: 651-266-9046

Email: jim.seeger@ci.stpaul.mn.us

Attachments