

CITY OF SAINT PAUL

375 Jackson Street., Suite 220 Saint Paul, MN 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-1919 Web: www.stpaul.gov/dsi

October 25, 2019

Fillmore Avenue Apartments LLC C/O Weidner Investment Serv Inc 9757 Ne Juanita Dr Ste 300 Kirkland WA 98034-4291 Jim Hunt Fillmore Ave Apartments 24 University Ave Ne #150 Minneapolis MN 55413

Order to Abate Nuisance Building(s)

Dear Interested or Responsible Party:

The Vacant/Nuisance Buildings Unit, Department of the Department of Safety and Inspections, Division of Code Enforcement, hereby declares the premises located at:

173 ROBERT ST S

With the following Historic Preservation information: NONE

and legally described as follows, to wit:

BAZIL AND ROBERT'S ADDITION ST ACCRUING AS VAC IN ABST DOC 1819955 & TS DOC 567230 & FOL; EX SWLY QUADRANGULAR PART MEASURING 10 FT ON SELY L OF LOT 5 AND 24 FT ON NWLY L OF LOT 4 LOTS 4 AND LOT 5 BLK 15

to comprise a nuisance condition in violation of the Saint Paul Legislative Code, Chapter 45.02, and subject to demolition under authority of Chapter 45.11.

On October 17, 2019 a Building Deficiency Inspection Report was compiled and the following conditions were observed.

This list of deficiencies is not necessarily all the deficiencies present at this time. This building(s) is subject to the restrictions of Saint Paul Ordinance Chapter 33.03 and shall not again be used for occupancy until such time as a Certificate of Compliance or a Certificate of Occupancy has been issued. All repairs must be in accordance with appropriate codes. Changes or additions to the electrical system, mechanical system, or the plumbing system may necessitate updating or upgrading the systems involved.

This is a one-story, wood frame, commercial building.

On September 24, 2019, Inspector Dornfeld received an email from C of O Inspector Neis notifying him of the conditions found at the property after he had been called out on a fire outside of the building. It appeared individuals were climbing up the duct work at the back of the building and gaining entrance through the roof. Inside the building, he found copper piping had been removed and insulation had been burned. There was heavy mold, rat droppings, and several beds were present indicating people were sleeping there. He spoke with a representative of the property who indicated the plan was to redevelop the area. Inspector Neis suggested changing the property status to a Category 3 Vacant Building. The following is a list of deficiencies found at the building when the inspection was conducted:

DEFICIENCIES

- Infestation of Cockroaches. Exterminate and eliminate all cockroaches throughout the entire building. Provide this office with a copy of the extermination report from a licensed professional Pest Control Operator and follow their recommendations to eradicate these pests.
- Lack of Electricity: Immediately restore electrical service. Failure to provide proper electrical service will result in these premises being declared Unfit for Human Habitation and ordered vacated for lack of this basic facility. Use of candles, fuel operated lighting or extension cord wiring is not permitted while the power is off.
- The eaves and soffits are in a state of disrepair or deterioration. Repair all defects, holes, breaks, lose or rotting boards, to a professional state of maintenance. Permit may be required.
- The exterior walls and/or trim of the house and/or garage have defective, peeled, flaked, scaled or chalking paint or have unpainted wood surfaces. Scrape and repaint to affect a sound condition in a professional manner.
- The foundation is deteriorated, defective or in a state of disrepair. Repair all foundation defects in a professional manner to a weather-tight, water-tight and rodent-proof condition. Permit may be required.
- Lack of Natural Gas Service: Immediately restore natural gas service. Failure to provide natural gas service will result in these premises being declared Unfit for Human Habitation and ordered vacated for lack of this basic facility.
- The interior ceilings are defective. Repair all ceiling defects and finish in a professional manner.
- The interior walls are defective. Repair all wall defects and finish in a professional manner.
- There is evidence of a rodent infestation. Immediately exterminate and eliminate all rodents from the entire building. Remove rodent harborages in the yard areas. Tuckpoint the foundation, if necessary, to rodent-proof the building to prevent re-infestation. Immediately remove any dead rodents from the premises.
- The roof is deteriorated, defective, or in a state of disrepair. Repair or replace the roof covering to a sound, tight and water impervious condition. Permit may be required.
- Smoke Detector: Lack of properly installed and operable smoke detector. Provide functioning smoke detectors in accordance with the attached requirement, within 24 hours.

- Lack of Water Service: Immediately restore water service. Failure to provide water service will result in these premises being declared Unfit for Human Habitation and ordered vacated for lack of this basic facility.
- The window and/or door screens are missing, defective or in a state of disrepair. Provide proper window and door screens for all openable windows and doors. Screens must be tight-fitting and securely fastened to the frames.

As owner, agent or responsible party, you are hereby notified that if these deficiencies and the resulting nuisance condition is not corrected by **November 24, 2019** the Department of Safety and Inspections, Division of Code Enforcement, will begin a substantial abatement process to demolish and remove the building(s). The costs of this action, including administrative costs and demolition costs will be assessed against the property taxes as a special assessment in accordance with law.

As first remedial action, a Code Compliance Inspection Report must be obtained from the Building Inspection and Design Section, 375 Jackson Street, Suite 220, (651) 266-8989. This inspection will identify specific defects, necessary repairs and legal requirements to correct this nuisance condition. You may also be required to post a five thousand dollars (\$5,000.00) performance bond with the Department of Safety and Inspections before any permits are issued, except for a demolition permit. Call the Department of Safety and Inspections for more information at 651-266-8989.

If this building is located in a historic district or site (noted on page 1, above, just below the property address) then you must contact Heritage Preservation (HPC) staff to discuss your proposal for the repairs required by this order and compliance with preservation guidelines. Copies of the guidelines and design review application and forms are available from the Department of Safety and Inspections web site (see letterhead) and from the HPC staff. No permits will be issued without HPC review and approval. HPC staff also can be reached by calling 651-266-9078.

As an owner or responsible party, you are required by law to provide full and complete disclosure of this "Order to Abate" to all interested parties, all present or subsequent renters and any subsequent owners. The property shall not be sold, transferred or conveyed in any manner until the Nuisance Conditions have been abated and the Certificate of Code Compliance or Certificate of Occupancy has been issued.

The Enforcement Officer is required by law to post a placard on this property which declares it to be a "nuisance condition", subject to demolition and removal by the City. This placard shall not be removed without the written authority of the Department of Safety and Inspections, Division of Code Enforcement. The department is further required to file a copy of this "Order to Abate" with the City Clerk's Office.

If corrective action is not taken within the time specified in this order, the Enforcement Officer will notify the City Council that abatement action is necessary. The City Clerk will then schedule dates for Public Hearings before the City Council at which time testimony will be heard from interested parties. After this hearing the City Council will adopt a resolution stating what action if any, it deems appropriate.

If the resolution calls for abatement action the Council may either order the City to take the abatement action or fix a time within which this nuisance must be abated in accordance with the

October 25, 2019 173 ROBERT ST S Page 4

provisions of Chapter 33 of the Saint Paul Legislative Code and provide that if corrective action is not taken within the specified time, the City shall abate this nuisance. The costs of this action, including administrative costs will be assessed against the property as a special assessment in accordance with law.

If you have any questions or request additional information please contact **Matt Dornfeld** at **651-266-1902**, or you may leave a voice mail message.

Sincerely,

Matt Dornfeld

Vacant Buildings Enforcement Inspector