

WORK PLAN - BREAKDOWN COST OF REHABILITATION

(To be done in accordance with the Code Compliance Inspection Report) Address: 985 Woodbridge St

WEEK OF	TASKS	CONTRACTOR	Supplies/Materials on hand (if any)	Needed Supplies/Materials	Owner/Developer Labor	Value of Cost
2-27-20	Heat-Rough In	Metro Heating	Supplied by contractor			\$870-
3-15-20	Electrical Rough In	Palm Electric	Supplied by Contractor			6000-
4-15-20	Plumbing Rough In	Plumbing Services Inc.	Supplied by Contractor + Home Owner			4600-
4-22-20	Sheet rock, Repair and Remodeling work to begin	Home Owner	Supplied by Home Owner	Various Construction Materials		12,500
4-15-20 4/15/20	Electrical Finish	Palm Elect.	Supplied by Contractor			4,300
4/30/20	Plumbing Finish	Plumbing Services Inc.	" " "			3400
7-20-20	General Repair Finish Paint + Flooring	Home Owner	Supplied by Home Owner	Paint + Flooring		6,200

Total Project Cost: \$ 31,920

Bill Berner 2-19-2

Note: (Code Enforcement Officers estimate the cost to repair this structure is \$ _____ to \$ _____).