SAINT

CITY OF SAINT PAUL

375 Jackson Street, Suite 220 St Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-9124 Web: www.stpaul.gov/dsi

October 21, 2019

Carolyn J Brandt 1940 Fairmount Ave St Paul MN 55105-1540

Dear Carolyn J Brandt and others, if listed:

On October 21, 2019, this department conducted an inspection of your property at **1940 FAIRMOUNT AVE** and because **you were not compliant with a previous order**.

Deficiency: Failure to complete exterior maintenance of rear deck and stairs. Please complete the project. Have the permit inspected and approved.

**YOU ARE BEING BILLED <u>\$122.00</u>** for the cost of this inspection. This is in accordance with Chapter 34.24 of the Saint Paul Legislative Code. Payment is due upon receipt of this letter. Make your check payable to the "City of Saint Paul" and mail your payment to:

Department of Safety and Inspections, Code Enforcement Excessive Consumption Unit 375 Jackson Street, Suite 220 St. Paul, MN 55101-1806

If you do not pay within 30 days, the amount of this bill, *plus administrative costs*, will be assessed to your property taxes.

### **NOTICE**

Your property is scheduled for a REINSPECTION on November 4, 2019.

### **WARNING**

IF YOU DO NOT HAVE THE VIOLATION(S) CORRECTED BY THE NEXT INSPECTION DATE, November 4, 2019, YOU WILL BE BILLED AN ADDITIONAL \$120.00. CALL THE INSPECTOR IF YOU HAVE ANY QUESTIONS: Lisa Martin, 651-266-1940

Lisa Martin Code Enforcement Inspector

# City of Saint Paul, Department of Department of Safety and Inspections

October 21, 2019

## **EXCESSIVE CONSUMPTION**

Invoice #: 1469027

File #: 18-071597

Property Address: 1940 FAIRMOUNT AVE

Property PIN: 042823330072 Owner Name: Carolyn J Brandt

> **Fee Description Amount** Excessive Consumption (Non Compliance) \$ 122.00

Payment is due upon receipt of this letter. Failure to pay within 30 days will result in the amount due assessed to your property taxes. Make your check payable to the City of Saint Paul.

Send payment to: Department of Safety and Inspections

> **Excessive Consumption Unit** 375 Jackson Street, Suite 220 St. Paul, MN 55101-1806

Keep this port	ion for your records:		
Date Paid:	Amount Paid: \$	Check or Money Order #:	
Deficiency: "Exterior maintenance of the building/property needs repair or replacement" 335			
	CUT HERE	· <del>(</del>	_

## \*\*\*RETURN THIS PORTION WITH YOUR PAYMENT\*\*\*

City of Saint Paul, Department of Department of Safety and Inspections, Code Enforcement Division

**EXCESSIVE CONSUMPTION PAYMENT** 

Folder #: 18-071597

Invoice: No: 1469027 Date: October 21, 2019

Property Address: 1940 FAIRMOUNT AVE

Property PIN: 042823330072 Owner Name: Carolyn J Brandt

> **Fee Description Amount** Excessive Consumption (Non Compliance) \$ 122.00

**Deficiency**: "Exterior maintenance of the building/property needs repair or replacement"