

## SPRWS Work Related Injuries

January 2020 - March 2020

SPRWS Claim #	Date of Injury	Division	Job Title	Injury Description	Body Part
20-0001	01/07/2020	Engineering	Water Utility Technician II	Employee was putting ice grips on his boots when he lost balance and hit his head on the door of the work van.	Head
20-0002	01/15/2020	Production	Water Utility Worker I	Employee tripped as he was walking through a brush pile while carrying a chainsaw, causing him to feel pain in his back.	Back
20-0003	01/21/2020	Business	Business Division Manager	While walking into work from the building parking lot, the employee slipped on the ice causing her to feel pain in her left ankle	Left Ankle
20-0004	02/18/2020	Distribution	Water Utility Worker I	Employee was shoveling salt out of a salt bin located in the back of a pick-up truck when he slipped causing pain to the back of his left leg.	Left Leg
20-0005	03/11/2020	Distribution	Water System Worker II	Employee was standing next to a coworker who was using a blow rod when some of the dirt blew into his left eye.	Left Eye