WORK PLAN - BREAKDOWN COST OF REHABILATION

(To be done in accordance with the Code Compliance Inspection Report) Address:____134 Elizabeth St E _____

WEEK	TASKS	CONTRACTOR	Supplies/Materials	Needed	Owner/Developer	Value of
OF			on hand (if any)	Supplies/Materials	Labor	Cost
8/17/20	Electrical and	Weaver Electric			Maurice Weaver	Time and Materials
	hardwired smoke					
	detection					
8/17/20	plumbing	Discount Plumbers			Clint	2250.00
8/18/20	Dry out basement	RRI				2500.00
	Leveling basement					
	floors and plinth					
	blocks were needed					
	and inspect post					
8/21/20	Repair all doors	RRI				2790.00
	storms and screens					
8/22/20	Repairing walls and	RRI				1850.00
	flooring					
8/24/20	Siding and stone	RRI				16500.00
	installation					
8/24/20	Heating	Standard heating				Time and
	8					Materials
8/26/20	Bathroom,	RRI				
0/20/20	handrails and					
	window repairs					
8/28/20	Gutter system	RRI				1750.00
0,20,20	inallation					2.0000
8/28/20	Deck rebuild/repair	RRI				4500.00
9/04//20	Painting exterior of	RRI				5500.00
7/04//20	the house	KKI				3300.00
9/07/20	Attic insulation	RRI				3265.00
2/0//20	Contractors 10%	IXXI				4104.50
	Contractors 10 / 0					7107.50

T-4-1 D !4 C	Cost\$ 45193.50		
Total Project C			