SPRWS Work Related Injuries

April 2020 - June 2020

| SPRWS Claim # | Date of Injury | Division | Job Title | Injury Description | Body Part |
|---------------|----------------|--------------|----------------------------------|---|------------------------------------|
| 20-0006 | 04/16/2020 | Distribution | Water Utility Worker I | Employee experienced cramping in his stomach which spread throughout the rest of his body causing him to have to stop working and seek medical attention. | Stomach & Other Areas of the Body |
| 20-0007 | 04/24/2020 | Distribution | Heavy Equipment Operator | Employee tripped and fell on uneven asphalt pavement and immediately felt pain in his ribs on the right side. | Right Side Ribs |
| 20-0008 | 05/01/2020 | Distribution | Water System Worker II | Employee was turning a gate valve with a gate valve rod when the rod slipped out of position causing him to feel pain in his right shoulder. | Right Shoulder |
| 20-0009 | 05/05/2020 | Production | Water Utility Worker I | Employee was working in the plant reservoir when sodium hydroxide dripped down on him from a leaky pipe causing a chemical burn to his right arm and shoulder. | Right Arm & Shoulder |
| 20-0010 | 05/19/2020 | Distribution | Water Distribution Supervisor II | Employee was lifting a cast iron pipe when he felt pain in his lower back. | Lower Back |
| 20-0011 | 06/03/2020 | Distribution | Water Utility Worker I | Employee was using a hammer to remove rust and debris from a gate valve, when a piece of rusted metal flew into his left eye. | Left Eye |
| 20-0012 | 05/20/2020 | Distribution | Water Utility Worker I | Employee developed pain in his arms, hands, neck, and upper back over time from daily hand and power tool use. | Hands, Arms, Neck, & Upper Back |
| 20-0013 | 06/9/2020 | Distribution | Water Utility Worker II | Employee was placing a wooden end panel in a trailer when it slipped off the trailer and landed on his right foot. | Right Foot |
| 20-0014 | 06/12/2020 | Distribution | Water Utility Worker I | Employee was holding a piece of temporary pipe in place for another employee when the other employee twisted the pipe causing the coupling on the end of the pipe to cut her right ear. | Right Ear |
| 20-0015 | 06/29/2020 | Distribution | Water Utility Worker I | Employee was lifting a wooden driveway ramp when he heard a pop and felt pain in his right wrist. | Right Wrist |