

Ashli Jones

From: no-reply@ci.stpaul.mn.us
Sent: Wednesday, January 24, 2024 8:20 PM
To: #CI-StPaul_Form4
Subject: Inspection Request

The following inspection request was submitted on 24 Jan 2024 20:20:

Owner Name: NICOLAS RESENDIZ CECILIA RESENDIZ
Address: 1056 BEECH ST

Property Type: single-family

No Heat: on

Situation Description: This is a vacant house and family members checked on it today and found that the heat was not working and a water pipe had burst. Water had leaked over the furnace and it was not operational. The gas was shut off at the meter and Xcel was requested to ensure it was safe to turn the gas back on. Please complete an inspection to ensure the house is safe.

Name: Andrew Vorlicek
Rank: FDC
Company: D3B